

0005

8-28-87



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

File

SCC JCH

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Aug. 7, 1987
11:00 am to 12:00 pm

Permittee and/or Operators Name: Soldier Creek Coal Company
Business Address: P. O. Box I Price, Utah 84501
Mine Name: Banning Siding Permit Number: ACT/007/034
Type of Mining Activity: Underground Surface Other Preparation Plant
County: Carbon
Company Official (s): Dave Spillman
State Official(s): Holland Shepherd, Harold Sandbeck
Partial: X Complete: Date of Last Inspection: June 4, 1987
Weather Conditions: Sunny - cloudy, some runoff on site
Acreage: Permitted n/a Disturbed n/a Regraded 0 Seeded 0 Bonded 0
Enforcement Action: N 87-9-6-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. <u>PERMITS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
2. <u>SIGNS AND MARKERS</u>	<u>(X)</u>	<u>()</u>	<u>()</u>	<u>()</u>
3. <u>TOPSOIL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
b. <u>DIVERSIONS</u>	<u>(X)</u>	<u>()</u>	<u>()</u>	<u>()</u>
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	<u>(X)</u>	<u>()</u>	<u>()</u>	<u>(X)</u>
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
f. <u>EFFLUENT LIMITATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
5. <u>EXPLOSIVES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
7. <u>COAL PROCESSING WASTE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
8. <u>NONCOAL WASTE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
9. <u>PROTECTION OF FISH, WILDLIFE AND</u> <u>RELATED ENVIRONMENTAL VALUES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
10. <u>SLIDES AND OTHER DAMAGE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
11. <u>CONTEMPORANEOUS RECLAMATION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
12. <u>BACKFILLING AND GRADING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
13. <u>REVEGETATION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
14. <u>SUBSIDENCE CONTROL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
15. <u>CESSATION OF OPERATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
b. <u>DRAINAGE CONTROLS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
c. <u>SURFACING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
d. <u>MAINTENANCE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
17. <u>OTHER TRANSPORTATION FACILITIES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u> <small>an equal opportunity employer</small>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION 8-7-87

(Comments are Numbered to Correspond with Topics Listed Above)

4.d. SEDIMENT CONTROL AND EROSION:

The area where piping had been occurring along the northwest fenceline, has been completely repaired, and has held up after heavy rains encountered during the previous week.

During the last inspection NOV87-9-6-1 had been written regarding a problem with drainage piping under the fence and berm located in this area. According to the operator the violation was abated the day after it was written which would be 7-18-87. The operator had been given an abatement date of 8-3-87.

Mailed to: Chris Allen (Sold. Crk), Donna Griffin (OSM)
Given to: Joe Helfrich (DOGM)

Inspector's Signature and Number: Holland Shepherd #9 Date: 8-7-87

0017
0018