

7-20-87

0007



UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N87-9-6-1

To the following Permittee or Operator:

Name Soldier Creek Coal Company

Mine Banning Riding Prep Plant Surface Underground Other

County Carbon State UT Telephone 637-6360

Mailing Address P.O. Box I Price, UT 84501

State Permit No. ACT/007/034

Ownership Category State Federal Fee Mixed

Date of inspection July 17, 19 87

Time of inspection 9:00 a.m. p.m. to 11:00 a.m. p.m.

Operator Name (other than Permittee) same as above

Mailing Address same as above

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing July 17, 1987 Time of service/ mailing 11:00 a.m. p.m.

Permittee/Operator representative Chris Allen Title Mine Engineer

Signature [Signature]

Division of Oil, Gas & Mining representative Hollan Shepherd #9 Title Reclamation Specialist

Signature [Signature] Identification Number _____

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

0918



NOTICE OF VIOLATION NO. N87-9-6-1

Violation No. 1 of 1

Nature of violation

Failure to prevent to the extent possible, additional contributions of sediment to stream flow outside the permit area.

Provisions of act, regulations or permit violated

UMC 827.12 (d)
UMC 817.45

Portion of operation to which notice applies

Northwest boundary of the disturbed area, along berm which follows fence line. Piping holes have developed under berms. Drainage from disturbed area is running through holes to gulch on the other side of the fence.

Remedial action required (including any interim steps)

1) Repair two holes where piping has developed

Abatement time (including interim steps)

1) By Aug. 3, 1987