



NO. N 88-13-1-1

notice of violation

To the following Permittee or Operator:

Name Solomon Creek Coal Company

Mine Bannock Summit  Surface  Underground  Other

County CARBON State UTAH Telephone 637-6360

Mailing Address P.O. Box 1, Carbon Utah

State Permit No. ACT 1007/034

Ownership Category  State  Federal  Fee  Mixed

Date of inspection April 18, 19 88

Time of inspection 5:45  a.m.  p.m. to 7:00  a.m.  p.m.

Operator Name (other than Permittee) SAVAGE BROS.

Mailing Address \_\_\_\_\_

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing 4/18/88 Time of service/ mailing 7:00  a.m.  p.m.

JEFF GREEN  
Permittee/Operator representative

Plant Foreman  
Title

Jeff M. Green  
Signature

RANDY HORDEN  
Division of Oil, Gas & Mining representative

Reclamation Engineer  
Title

J. Russell Hauer  
Signature

#13  
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N88-13-1-1

Violation No. 1 of 1

Nature of violation

FAILURE TO PASS DISTURBED RUNOFF THROUGH  
AN OPERATING SEDIMENT CONTROL STRUCTURE

Provisions of act, regulations or permit violated

UMC 817.42 a ALL SURFACE DRAINAGE FROM THE  
DISTURBED AREA SHALL BE PASSED THROUGH A SEDIMENT  
POND OR A SERIES OF SEDIMENT PONDS BEFORE LEAVING  
THE PERMIT AREA.

Portion of operation to which notice applies

DISTURBED AREA COLLECTION DITCH ALONG SOUTH END OF  
SITE - DISCHARGING @ SW CORNER OF PROPERTY. EST. FLOW  
50 gpm. FLOW PASSING UNDER AND AROUND SILT  
FENCES AND STRAW BALES. FLOW WAS TOO LARGE  
FOR SEDIMENT CONTROL STRUCTURES AS INSTALLED.

Remedial action required (including any interim steps)

REPLACE AND REPAIR STRAW BALES AND SILT FENCE  
IN AND ALONG DITCH. RE-ESTABLISH EFFECTIVE  
SEDIMENT CONTROL ON OR BEFORE 10 DAYS OF THIS  
NOTICE - (APRIL 28, 1988). MAKE REMEDIAL REPAIRS  
AS SOON AS MATERIAL FOR REPAIRS IS AVAILABLE -

Abatement time (including interim steps)

ON OR BEFORE APRIL 28, 1988