

0006

**SC<sup>3</sup> SOLDIER CREEK COAL CO.**

Telephone (801) 637-6360

P.O. Box 1  
Price, Utah 84501

File ACT/007/034-  
89A  
FOLDER 2

June 30, 1989

Ms. Susan C. Linner  
Permit Supervisor  
Division of Oil, Gas & Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

**RECEIVED**  
JUL 03 1989

DIVISION OF  
OIL, GAS & MINING

Re: TDN 89-02-107-4(2)  
Banning Loadout  
ACT/007/034

Dear Susan:

In response to Ten-Day Notice (TDN) 89-02-107-4(2), Soldier Creek Coal Company is requesting an Incidental Boundary Change (IBC) at Banning Loadout. This IBC is necessary to incorporate all the disturbance associated with the vegetation test plot into the permit area boundary.

The test plot boundary as well as the requested IBC is accurately illustrated on the enclosed drawing (Exhibit 5.2-1). Following Division approval, the necessary number of copies of a revised permit area map shall be submitted for direct incorporation into the approved Mining and Reclamation Plan.

Please contact me if you have any questions or require any additional information concerning this matter.

Sincerely,

SOLDIER CREEK COAL COMPANY



David G. Spillman  
Mine Engineer

Enclosure

DGS/sm