

0004



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340
(801) 359-3940 (Fax)

Partial: XXX Complete: Exploration:

Inspection Date & Time: 10/06/97 / 10:00a.m.-1:00p.m.

Date of Last Inspection: 9/11/97

Mine Name: Banning Siding Loadout County: Carbon Permit Number: ACT/007/034

Permittee and/or Operator's Name: Canyon Fuel Company

Business Address: P.O. Box 1029, Wellington, Utah 84542

Type of Mining Activity: Underground Surface Prep. Plant XXX Other

Company Official(s): None

State Officials(s): Steve Demczak Federal Official(s): None

Weather Conditions: Warm, Clear, 70's

Existing Acreage: Permitted- 36 Disturbed- 21.6 Regraded- 0 Seeded- 0 Bonded- 21.6

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture

Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

| | EVALUATED | N/A | COMMENTS | NOV/ENF |
|--|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. SIGNS AND MARKERS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. TOPSOIL | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. DIVERSIONS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| b. SEDIMENT PONDS AND IMPOUNDMENTS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| c. OTHER SEDIMENT CONTROL MEASURES | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| d. WATER MONITORING | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| e. EFFLUENT LIMITATIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. EXPLOSIVES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. NONCOAL WASTE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. SLIDES AND OTHER DAMAGE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. CONTEMPORANEOUS RECLAMATION | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. BACKFILLING AND GRADING | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. REVEGETATION | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 14. SUBSIDENCE CONTROL | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. CESSATION OF OPERATIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16. ROADS: | | | | |
| a. CONSTRUCTION/MAINTENANCE/SURFACING | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| b. DRAINAGE CONTROLS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 17. OTHER TRANSPORTATION FACILITIES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS CHECK (4th Quarter-April, May, June) _____(date) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20. AIR QUALITY PERMIT | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 21. BONDING & INSURANCE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |



gph

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION: 10/06/97

(Comments are Numbered to Correspond with Topics Listed Above)

4A. DIVERSIONS -

The diversions were spot-checked and in several areas sediment has started to build-up. The permittee will need to clean out the sediment before ditches become non-functional.

4B. SEDIMENT PONDS -

The sediment pond was inspected and no hazardous conditions were noticed. This pond did contain a small amount of water. This pond is incised. Small erosion marks have started but no violation nor a safety hazard exists.


4C. OTHER SEDIMENT CONTROL -

The silt fences along the haul road will need to be cleaned out in the near future. Sediment has started to build-up. This was caused by the frequent number of rain storms in August and September.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Dave Spillman (Soldier Canyon) Henry Austin (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: October 6, 1997

Inspector's Signature:  #39
Stephen J. Demczak