

WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

November 7, 2003

TO: Internal File

THRU: Daron R. Haddock, Permit Supervisor

FROM: Dana Dean, P.E., Senior Reclamation Hydrologist

RE: 2003 Second Quarter Water Monitoring, Canyon Fuel Company, Banning Siding, C/007/0034, Task ID #1767

- 1. Was data submitted for all of the MRP required sites?** YES NO
Identify sites not monitored and reason why, if known:

The Truck Dump Sump is the only MRP required monitoring site, other than the UPDES sites. Only one sample per year is required, in the "late fall" according to the MRP. The MRP does not require monitoring during the second quarter.

- 2. On what date does the MRP require a five-year resampling of baseline water data.**
See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

Resampling due date

There is no commitment in the MRP to resample for baseline parameters.

- 3. Were all required parameters reported for each site?** YES NO
Comments, including identity of monitoring site:

The MRP does not require monitoring in the first quarter.

4. **Were irregularities found in the data?** YES NO
Comments, including identity of monitoring site:

The MRP does not require monitoring in the first quarter.

5. **Were DMR forms submitted for all required sites?**

1 st month,	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
2 nd month,	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
3 rd month,	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>

All DMRs reported "no flow".

6. **Were all required DMR parameters reported?** YES NO
Comments, including identity of monitoring site:

All DMRs reported "no flow".

7. **Were irregularities found in the DMR data?** YES NO
Comments, including identity of monitoring site:

All DMRs reported "no flow".

8. **Based on your review, what further actions, if any, do you recommend?**

No further actions are necessary at this time.