



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

C0070034
Outgoing
#4309
K

April 11, 2013

Rick Parkins, General Manager
Canyon Fuel Company
P.O. Box 1029
Wellington, UT 84542

Subject: 2012 Annual Report Review Completion, Banning Loadout, C/007/0034, Task ID # 4309

Dear Mr. Parkins:

The Division staff has completed the review of the 2012 Annual Report. Enclosed is a copy of the review with each reviewer's comments completed on April 11, 2013.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5325 or Ingrid Campbell at 801-538-5318.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/sqs
Enclosure
cc: Price Field Office
O:\007034.BAN\WG4309\ReviewCompletionLetter1.doc

Print Form

Submit by Email

Reset Form

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Canyon Fuel Company, LLC	Mine Name	Banning Loadout
Permit Number	C/007/0034	Permit expiration Date	10/24/2013
Operator Name	Same	Phone Number	+1 (435) 637-6360
Mailing Address	P O Box 1029	Email	dspillman@archcoal.com
City	Wellington		
State	Utah	Zip Code	84542

DOGM File Location or Annual Report Location

Excess Spoil Piles

- Required
 Not Required

Refuse Piles

- Required
 Not Required

Impoundments

- Required
 Not Required

Other:

OPERATOR COMMENTS

REVIEWER COMMENTS

- Met Requirements Did Not meet Requirements

The Banning site is in temporary cessation status and it has a quarterly complete inspection frequency. The most recent inspection(s) consisted of a records review on February 4, 2013 and a site inspection on March 26, 2013. Snow on the access road and the site itself prevented a site inspection on February 4, 2013.

The 2012 Annual Report consists of four quarterly impoundment inspections for the Banning sediment pond (conducted by Ms. Vickie Miller) and an annual impoundment inspection and certification conducted by Mr. Dave Spillman, Utah registered P.E.

None of the quarterly inspections reported signs of instability, or other hazardous conditions. This pond is incised, and the surrounding water shed is very flat. With the exception of a small sediment volume at the outlet of the primary discharge spillway, no other maintenance issues were identified. The pond has 77 % of the sediment storage capacity remaining as of December 3, 2012. Mr.

Spillman certified the annual inspection report on December 3, 2012. The professional engineers certification stamp meets the requirements of R156-22-601, (1 a, b, c, d, e and f). (PHH, 3/28/2013)

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

Reviewer Comments