



GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

May 23, 2014

Rick Parkins, General Manager
Canyon Fuel Company, LLC
P.O. Box 1029
Wellington, Utah 84542

Subject: 2013 Annual Report Review Completion, Banning Loadout, C/007/0034, Task ID #4549

Dear Mr. Parkins:

The Division staff has completed the review of the 2013 Annual Report. Enclosed is a copy of the review with each reviewer's comments completed on May 23, 2014.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/sqs
Enclosure
O:\007034.BAN\WG4549\ReviewCompletionLetter.doc

Print Form

Submit by Email

Reset Form

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Canyon Fuel Company, LLC	Mine Name	Banning Loadout
Permit Number	C/007/0034	Permit expiration Date	October 24, 2018
Operator Name	Same	Phone Number	+1 (435) 637-6360
Mailing Address	PO Box 1029	Email	dspillman@bowieresources.com
City	Wellington		
State	UT	Zip Code	84542

DOGM File Location or Annual Report Location

Excess Spoil Piles	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Not Required	
Refuse Piles	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Not Required	
Impoundments	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Attached
Other:		

OPERATOR COMMENTS

REVIEWER COMMENTS

Met Requirements Did Not meet Requirements

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

N/A

Reviewer Comments

The Banning site is in temporary cessation status. It is inspected 4 times per year as a complete inspection during each quarter. The site received a joint Division / OSMRE-WRCC partial oversight inspection on October 29, 2013. (PHH, 4/1/2014)

The annual report information provided by the Permittee included PE certified reports/inspections for the Banning Loadout Sedimentation Pond as required under R645-301-514. (SKC 5/22/2014)