

0047

SUNNYSIDE COGENERATION ASSOCIATES

POST OFFICE BOX 58087
SALT LAKE CITY, UTAH 84158-0087

September 22, 1993

Randy Harden
Department of Natural Resources
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Copy RAM (all)
ACT/007/035
#5

Dear Randy:

This letter is in response to the Notice of Violation received, No. N 93-40-6-4, Violation No. 3 of 4, for failing to conduct piezometer monitoring in the embankment of the east slurry cell and/or maintaining records of this activity at the site.

The information enclosed shows that the piezometer monitoring has been currently brought up to date and has been entered into the records kept on-site.

If you have any questions, please call.

Sincerely,



David R. Pearce
Authorized Member, Management Committee



Jim Comas
Environmental Auditor
Eckhoff, Watson and Preator Engineering

JC/sb

cc: Brian Burnett/Callister, Duncan and Nebeker

DATE	TOP HOLE	MIDDLE HOLE	BOTTOM HOLE
8-17-92	53' 1 1/2" DRY	PLUGGED	13' 11" WET
9-01-92	53' 1 1/2" "	"	13' 11" "
9-08-92	53' 1 1/2" "	"	13' 11" "
9-09-92	52' 7" "	"	13' 11" "
9-14-92	52' 7" "	"	13' 11" "
9-21-92	" "	"	" DRY
9-29-92	" "	"	" "
10-5-92	" "	"	" "
10-26-92	" "	"	" "
11-4-92	" "	"	" "
12-7-92	" "	"	" "
12-23-92	" "	"	" "
7-6-93	52' 6" WET	"	" DAMP
7-12-93	52' 7" "	"	" DRY
7-20-93	52' 7" "	"	" "
8-2-93	52' 5 1/2" "	"	" "
8-19-93	52' 6 3/4" "	"	" "
8-16-93	52' 5 1/2" "	"	" "
8-24-93	52' 6" "	UNPLUGGED 8-15-93 35' 10" DRY	" "
8-30-93	51' 9 3/4" "	" "	" "
9-10-93	51' 10" "	" "	" "
9-14-93	51' 10 3/4" "	" "	" "
9-20-93	52' 1/2" "	" "	" "