



*gh*

### MODIFICATION OF NOTICE OF VIOLATION/CESSATION ORDER

To the following Permittee or Operator:

Name SUNNYSIDE COGENERATION ASSOCIATES

Mailing Address P.O. BOX 8087 SALT LAKE CITY UT 84158-0087

State Permit No. ACT/007/035

Utah Coal Mining & Reclamation Act, Section 40-10-1 et seq., Utah Code Annotated (1953):

Notice of Violation No. N 93-13-1-1 dated OCTOBER 15, 1993.

Cessation Order No. C \_\_\_\_\_ dated \_\_\_\_\_, 19 \_\_\_\_.

Part 1 of \_\_\_\_\_ is modified as follows: ABATEMENT DATE EXTENDED TO 5:00pm, NOVEMBER 30, 1993.

Reason for modification is AS PER OPERATOR'S REQUEST.

Part \_\_\_\_\_ of \_\_\_\_\_ is modified as follows: \_\_\_\_\_

Reason for modification is \_\_\_\_\_

Part \_\_\_\_\_ of \_\_\_\_\_ is modified as follows: \_\_\_\_\_

Date of service mailing 11/19/93 Time of service mailing 3:30  a.m.  p.m.

Date of inspection Nov. 16, 1993

FRED FINLIXSON  
Permittee/Operator representative

RESIDENT AGENT FOR SGA  
Title

Signature

J. Randall Haroon  
Division of Oil, Gas & Mining

Sr. Recl. ENGR.  
Title

J. Randall Haroon  
Signature

SUNNYSIDE COGENERATION ASSOCIATES

POST OFFICE BOX 58087  
SALT LAKE CITY, UTAH 84158-0087

November 16, 1993

RECEIVED

NOV 16 1993

DIVISION OF  
OIL, GAS & MINING

Mr. Randy Harden  
Division of Oil, Gas and Mining  
3 Triad Center - Suite 350  
Salt Lake City, UT 84180-1203

RE: Sunnyside Cogeneration Associates - Violation No. 93-13-1-1

Dear Randy,

On November 5, 1993, Sunnyside Cogeneration Associates requested a 30 day extension for the abatement of Violation No. 93-13-1-1. The Division of Oil, Gas and Mining responded with an extension until November 16, 1993. The violation was issued for failure to identify and describe all mining and related activities within the permit area.

Eleven days is not adequate time to provide the information required to fulfill the requirements of this violation. As DOGM is aware, there are in excess of forty certified drawings contained in the SCA Permit Document. In order to change all of these drawings to incorporate a permit boundary change, it will take a significant amount of time. Additionally, the crusher facility will require a field survey and detailed site plan and the SCA Permit Document will also require updating.

SCA is requesting an extension for this violation until December 15, 1993. If you have any questions, please feel free to call.

Sincerely,

*AEB for*  
David Pearce

Authorized Member, Management Committee

*Alane E. Boyd*

Alane E. Boyd, P.E.  
Senior Engineer

cc: Brian Burnett, CDN