

0032



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

July 23, 1993

Mr. David Pearce
Sunnyside Cogeneration Associates
P.O. Box 58087
Salt Lake City, Utah 84158-0087

Dear Mr. Pearce:

Re: Stipulation #18, Sunnyside Cogeneration Associates, Refuse and Slurry,
ACT/007/035, Folder #2, Carbon County, Utah

Pursuant to the meeting held on July 22, 1993 at the Division, it was verbally agreed by Alane Boyd, EWP, that Sunnyside Cogeneration Associates would revise the drill hole resampling to exclude drill hole 92-9, to include drill holes 92-2, 92-3, 92-10, 92-12, 92-12, 92-16, and 92-17. Drill holes 92-13 and 92-14 were also deemed acceptable for the screening program (see enclosed memo). Three more samples will be taken from each of these holes and stored for ten months. Testing may begin on the existing 92 samples now.

Please submit a written commitment for insertion into the plan by August 6, 1993 regarding this stipulation. If you have any questions, please call me.

Sincerely,

A handwritten signature in black ink, appearing to read 'Pamela Grubaugh-Littig'.
Pamela Grubaugh-Littig
Permit Supervisor

Enclosure

cc: HSauer
HKlein





State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

July 22, 1993

TO: Pamela Grubaugh-Littig, Permit Supervisor
FROM: Henry Sauer, Senior Reclamation Soils Specialist 
RE: Stipulation No.18, Sunnyside Cogeneration Association,
Sunnyside Refuse Pile, ACT/007/035, Folder #2, Carbon
County, Utah

SYNOPSIS

The permittee responded (June 11, 1993) to the Division's letter dated April 29, 1993. In the April 29, 1993 Division letter a request to develop a refuse sample screening plan was made. The permittee responded to the Division's request by identifying drill holes which would be resampled to determine the effects of sample storage (at Commercial Testing and Engineering Co. laboratories in Huntington, Utah) upon the physicochemical nature of the refuse samples collected by John T. Boyd in August of 1992.

The proposal to resample the drill holes is not acceptable and must be revise prior to approval.

ANALYSIS

On July 22, 1993 Jim Comas (EWP), representing the Sunnyside Cogeneration Association, and myself attempted to locate the John T. Boyd drill hole sites. The following observation were made: Drill hole 92-9 has been covered and must be excluded from the screening program; Drill holes 92-13 & 14 were located and determined to be acceptable sites for the screening program; Drill holes 92-2 & 3, 92-10, 92-12, 92-16 and 92-17 were located on-the-ground and determined to be acceptable sites for the refuse sample screening program. Drill holes 92-2,3,10,12,16 & 17 must be included in the screening program.

RECOMMENDATION

The permittee must adequately revise the response to Stipulation No.18 prior to Division approval.

