



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

10077
gjh

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: Complete: Exploration XX

Inspection Date/Time: September 8, 1993/01:00pm-02:30pm

Date of Last Inspection: August 9, 1993

Mine Name: Blackhawk Site County: Carbon Permit Number: ACT/007/038
Permittee and/or Operator's Name: Cyprus Plateau Mining/Western Coal Company
Business Address: P. O. Box PMC, Price, UT 84501
Type of Mining Activity: Underground Surface Prep. Plant Other XX
Officials(s): State: Stephen J. Demczak Company:
Federal Official(s): Weather Conditions: Warm 80's
Existing Acreage: Permitted-11,500 Disturbed-3.7 Regraded- Seeded-0 Bonded-3.7
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: X Exploration/ Active/ Inactive/ Temp Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[]	[XX]	[]
2. SIGNS AND MARKERS	[]	[]	[]	[]
3. TOPSOIL	[]	[]	[]	[]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[]	[XX]	[]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[]	[]	[]	[]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[]	[XX]	[]
d. WATER MONITORING	[]	[]	[]	[]
e. EFFLUENT LIMITATIONS	[]	[]	[]	[]
5. EXPLOSIVES	[]	[]	[]	[]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[]	[]	[]	[]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[]	[]	[]	[]
8. NONCOAL WASTE	[]	[]	[]	[]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	[]	[]	[]	[]
11. CONTEMPORANEOUS RECLAMATION	[]	[]	[]	[]
12. BACKFILLING AND GRADING	[]	[]	[]	[]
13. REVEGETATION	[]	[]	[]	[]
14. SUBSIDENCE CONTROL	[]	[]	[]	[]
15. CESSATION OF OPERATIONS	[]	[]	[]	[]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[]	[]	[]	[]
b. DRAINAGE CONTROLS	[]	[]	[]	[]
17. OTHER TRANSPORTATION FACILITIES	[]	[]	[]	[]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[]	[]	[]	[]
19. AVS CHECK (4th Quarter-April, May, June) _____ date	[]	[]	[]	[]
20. AIR QUALITY PERMIT	[]	[]	[]	[]
21. BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/038 DATE OF INSPECTION: September 9, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The main exploration permit will expire on November 30, 1993. The operator must reclaim this area prior to the exploration expiration date; unless the operator has an approved major exploration permit or a short term extension of the existing permit with justifiable reasons.

4a. Diversions -

The diversions were functioning as designed with no breaching of berms. There were signs of flow through the ditches.

4c. Other Sediment Control Measures -

The catch basins were dry and no breaching occurred and no safety problems were observed at these sights.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Cyprus Plateau Mining/Western Coal Company

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: September 13, 1993

Inspector's Signature and Number:  #39
Stephen J. Demczak