

0048



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Price Field Office
125 South 600 West
Price, Utah 84501
www.ut.blm.gov



RECEIVED

APR 2 / 2005

DIV. OF OIL, GAS & MINING

IN REPLY REFER TO:
3482
U-50722
SL-051279-063188
U-07064-027821
UTU-69635
(UT-070)

APR 25 2005

INCOMING
00000054

Certified Mail—Return Receipt Requested
Certificate No. 7003 1010 0005 2128 9885

cc: WAYNE H.
RAMB.

Utah Division of Oil Gas and Mining
Coal Regulatory Program
P.O. Box 145801
Salt Lake City, Utah 84116

Subject: Approval of the Dugout Out Mine, Pace Canyon Fan Portal Facilities Amendment C/007/039,
March 2005


Dear Mr. Mesch:

BLM has reviewed the Pace Canyon Fan Portal Facilities document dated March 15, 2005 and finds the updates to the plan satisfactory. Therefore, BLM recommends that a permit modification be granted to the Dugout Mine for this action.

BLM has reviewed the Probable Hydrologic Consequences (PHC) submitted by the Dugout Mine and has made a condition of approval in the Resource Recovery and Protection Plan (R2P2) approval for this site, that final portal seal and shaft filling designs be deferred until the action is to take place. There may be other circumstances known at that time which may be necessary for the company to consider in the designs.

If you have any questions, please feel free to contact Mr. Stan Perkes (801-539-4036).

Sincerely

for

Patrick Gubbins
Field Manager

cc: USO-Chief, Branch of Solid Minerals