



June 30, 2005

Utah Division of Oil Gas and Mining
Attn. Pamela Grubaugh-Littig
1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City UT 84114-5801

RE: SCA Star Point Waste Fuel, C/007/042 Task ID #2252
Chapter One Text Revision – Resident Agent - Clean copies

Dear Pam:

As requested we are submitting three clean copies of the above noted permit change which was conditionally approved by the Division upon receipt of these clean copies.

Please return a stamped incorporated copy of the approved documents to

Mike Blakey, Plant Manager
Sunnyside Cogeneration Associates
PO Box 159
Sunnyside UT 84539

Thank you for your assistance.

Sincerely,

A handwritten signature in cursive script that reads "S. Scott Carlson".

S. Scott Carlson, PE, PLS
President

112.200-210. Information Regarding the Applicant.

Additional information regarding the applicant may be obtained by contacting:

Local

Sunnyside Cogeneration Associates
Attn: Plant Manager
One Power Plant Road,
P.O. Box 159
Sunnyside, UT 84539
Phone: (435) 888-4476
Fax: (435) 888-2538

Environmental Coordinator

Attn: Rusty Netz
One Power Plant Road,
P.O. Box 159
Sunnyside, UT 84539
EIN: 52-2318424
Phone: (435) 888-4476
Fax: (435) 888-2538

Utah Counsel

Fred W. Finlinson, Esq.
Brian W. Burnett, Esq.
Callister Nebeker & McCullough
10 East South Temple
Salt Lake City, UT 84133
Phone: (801) 530-7300

Safety / Environmental

Manager

Attn: Neil Nelson
COSI
775 Sunrise Ave. S-200
Roseville, CA 95661
Phone: (916) 783-8616
Fax: (916) 783-3831

General Manager

Kendall Reed
ACI
RR2 Box 56, Highway 3016
Clarion, PA 16214
Phone: (814) 226-8001
Fax: (814) 226-7909

112.220. Information Regarding the Resident Agent.

Sunnyside Cogeneration Associates
Attn: Mike Blakey, Plant Manager
P.O. Box 159, Sunnyside, UT 84539 (mailing address)
One Power Plant Road, Sunnyside, UT 84539 (street address)
Phone: (435) 888-4476
EIN: 52-2318424

112.230. Information Regarding Abandoned Mine Land Reclamation Fee.

A letter was sent to the Office of Surface Mining on June 6, 2003 requesting a no value/fee determination for the Starpoint Mine Coal Refuse Pile. A copy of this letter is included in Exhibit 112.230a.

Any required Abandoned Mine Land Reclamation Fees will be paid by:

Sunnyside Cogeneration Associates
Attn: Plant Manager
P.O. Box 159
Sunnyside, Utah 84539
EIN: 52-2318424
Phone: (435) 888-4476