

NORTHWEST CARBON CORPORATION

315 EAST 200 SOUTH
P O BOX 1526
SALT LAKE CITY, UTAH 84110
801-534-3500

March 17, 1981

*MidMay - June 1st
inspection
Jerry Lebing of G.S.
will visit
FS.*

6373547

Mr. Ira Hatch
District Forest Ranger
U.S. Forest Service
10 North Carbon Ave.
Price, Utah 84501

Bill Bolle

Dear Mr. Hatch:

Attached please find two copies of our Access Road Use Permit Application to complete our drilling operation on Gentry Mountain. In our original application submitted to your office in August, 1980, permission to access T-3 was denied.

It is very critical that this drilling hole is reinstated so we can determine the extent of our reserves and the coal thickness in this area.

As shown on the attached map proposed access is from a different location than the one indicated during the on-site inspection on June 23, 1980. The proposed new road will be 6,000 feet in length with a 4% grade.

In addition to reinstating T-3 we propose to drill one additional hole, T-9, on our lease with access off an existing road.

Your expeditious handling of this matter will be appreciated.

Sincerely,

Catherine V. Chachas

Catherine V. Chachas
Environmental Engineer

CVC/bno

Attachment