

0004

September 8, 1983

Inspection Memo
to Coal File:

RE: Beaver Creek Coal Company
Huntington #4 Mine
ACT/015/004, Folder No. 7
Emery County, Utah

A partial inspection was conducted by Barton Kale of the Division on August 11, 1983 accompanied by Dan Guy of Beaver Creek Coal Company (BCCC).

At this time, no problems were evident. The disturbed area drainage below the fuel tank, by the coal stockpile, will be redesigned to contain fuel spillage in the area of the tank.

The results of the sediment pond discharge have not yet been seen by the inspector. It is expected that these data will be made available on the next inspection.


BARTON KALE
FIELD SPECIALIST

BK/btb

cc: Tom Ehmett, OSM
Dan Guy, BCCC
J. Helfrich, DOGM
T. Munson, DOGM

Statistics:

See Gordon Creek #2 Mine memo dated August 18, 1983