

0012

June 11, 1984

Inspection Memo  
to Coal File:

RE: Huntington Canyon #4  
Beaver Creek Coal Company  
ACT/015/004, Folder #7  
Emery County, Utah

On May 18, 1984 a partial inspection was conducted at the above site by Bart Kale and Tom Wright, Division Field Specialists. The purpose of this visit was to familiarize Mr. Wright with the mine and to collect water samples. The weather was warn and sunny.

The mine roadway was examined at the location where last winter violation N84-6-2-1 was issued for failure to minimize contribution of sediment off site. Some off site effects had previously occurred, however, the operator had properly completed the remedial action and the violation had been terminated. Also, the operator had applied hydromulch to the areas involved for additional sediment control.

Water samples were taken at two locations from the stream in the canyon. At sample site one, a sample was collected on the water shed just above the mine site. At site two a sample was taken just below the sediment pond. These samples were taken for comparison and to check any impacts of mining.

The sediment pond for the site was examined and found to be dry. It appears that no discharge has occurred recently.

No violations were noted during the inspection.

Tom Wright *TW*  
Mining Field Specialist

TW:re

cc: Jodie Merriman, OSM  
Joe Helfrich, DOGM  
Bart Kale, DOGM  
Mary Boucek, DOGM

Statistics: See Hidden Valley Memo dated May 22, 1984  
92530-1