

February 26, 1985

TO: Coal File, Inspection and Enforcement Folder
FROM: Tom Wright, Mining Field Specialist TW
RE: Beaver Creek Coal Company, Huntington Canyon #4 Mine,
ACT/015/004, Emery County, Utah

On February 21, 1985 I conducted a partial inspection of the Huntington #4 Mine. Dan Guy of Beaver Creek Coal Company (BCCC) was not available, so I conducted the inspection alone. The weather was clear and cold with heavy snow cover.

Mining has been completed on this site and the operator has requested the area be designated inactive until reclamation of the area begins.

Mel Coonrod, who contracts water sampling, was on the area collecting February samples during the inspection. He reported that no access to the upper pad was possible due to heavy snow cover.

No activity on the area by the operator, other than surveillance, has been done since the last inspection. The haulroad to the mine was snowpacked with some drifting in spots.

In a conversation on the following day, Dan Guy reported that he had attempted to lock the gates at the road entrance but the gates were locked in the open position. Mr. Guy indicated that he would attempt to close and lock the gate in the next few days.

Due to the snow cover, this inspection was limited to the area from the sediment pond to the main highway. No violations were noted during this inspection.

re

cc: Dan Guy
Donna Griffin, OSM
Mary Boucek
Joe Helfrich

Statistics:

Vehicle: EX45428 - 554 miles
Per Diem: 1 person x 2 days 7 hours = \$107.50
Grant: A&E

0085Q-24