



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 1/10/91
9:00am - 11:00am

Permittee and/or Operators Name: Cal Mat Company
Business Address: 1801 University Dr., Phoenix, AZ 85034
Mine Name: Hidden Valley Permit Number: ACT/015/007
Type of Mining Activity: Underground x Surface Other
County: Emery
Company Official (s): Karla Knoop (JBR)
State Official(s): Susan M. White
Partial: x Complete: Date of Last Inspection: 12/13/90
Weather Conditions: Partly cloudy and cold
Acreage: Permitted 950 Disturbed 7 Regraded 7 Seeded 7 Bonded 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(x)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(x)	()	()	(x)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	(x)	()	()	(x)
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 1/10/91

(Comments are Numbered to Correspond with Topics Listed Above)

The site had approximately 2 inches of snow from a storm about a week ago. Ivy Creek had an unusually high volume of water for this time of year, perhaps the amount of ice just made the volume appear like more. The site appeared unchanged from previous visits.

Silt fences were in place and in good repair. No runoff had occurred on site.

As a result of the previous site visit with OSM a Ten Day Letter was issued concerning the remaining cut and fill slopes. This issue was discussed with Ms. Knoop. A variance will need to be requested and appropriate regulations addressed and met.

The petroglyphs were observed on the cliffs directly above the mine site. Foot prints and vehicle tracts from other visitors were noted.

Copy of this Report:

Mailed to: Lee Edmonson (Cal Mat), Karla Knoop (JBR), John
Kathman (OSM)

Given to: Joe Helfrich

Inspectors Signature & Number: Susan M. White #35 Date: 1/11/91