

0016



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 3/20/95 8:00am-1:00pm
Date of Last Inspection: 2/16/95

Mine Name: Emery Deep Mine County: Emery Permit Number: ACT/015/015
Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P. O. Box 527, Emery, Utah 84522
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Steve Behling
State Officials(s): Peter Hess Federal Official(s):
Weather Conditions: Partly cloudy/Warm
Existing Acreage: Permitted- 5180 Disturbed- 40 Regraded- 2.7 Seeded- 2.7 Bonded- 207
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXXActive/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; DIVERSIONS; SEDIMENT PONDS AND IMPOUNDMENTS; OTHER SEDIMENT CONTROL MEASURES; WATER MONITORING; EFFLUENT LIMITATIONS; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION: 3/20/95

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The permittee has had the necessary repairs made to the 006 pond deep well pump, and returned same to service on February 27, 1995. Neither 001 nor 006 pond discharged during the month of February.

d. WATER MONITORING

The permittee collected the first set of UPDES water monitoring samples from ponds 001 and 006 on March 7, 1995. According to Mr. Behling, the results as received from Commercial Testing and Engineering in Huntington, Utah appear good concerning the meeting of effluent parameters.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Steven Behling (Consol Coal) Donna Griffin (OSM)
Given to: Joe Helfrich (DOGMD) Filed to: Price Field Office
Date: March 27, 1995

Inspector's Signature:  #46
Peter Hess