

0009



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten initials/signature

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Partial: Complete: XXX Exploration:
Inspection Date & Time: 8/9/2000 / 9:00A.M.-3:30P.M.
Date of Last Inspection: 8/2/2000

Mine Name: Hidden Valley Mine County: Emery Permit Number: ACT/015/007
Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P.O. Box 566, Sesser, Illinois 62884
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Steve Behling
State Officials(s): Bill Malencik Federal Official(s): None
Weather Conditions: Clear, Hot, Mid 90's
Existing Acreage: Permitted- 950 Disturbed- 7 Regraded- Seeded- Bonded- 7
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability 1986 Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows list 21 inspection items such as PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; etc.

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 8/9/2000

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

The general area including the mine received the first moisture in the form of rain. The only sign of runoff was in the undisturbed drainage that was 6" deep and about 3' wide.

No violations were issued. The environmental control measures appear to meet the coal rule performance standards.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were stable and showed no evidence of recent runoff. The diversion above the "A" seam maintained this past summer, meets performance standards. Some fine material from the escarpment is being deposited in the diversion, but doesn't constitute a concern at this point in time.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The MRP requires water monitoring at high and low flow. The sampling on Ivie Creek above and below the mine are to be taken in May and September. The last sampling was taken May 2000. The company is working with the Division to submit automated data. Ivie Creek is dry at the lower station. There is a very small flow on the upper station.

8. NONCOAL WASTE

The noncoal waste on the surface is not a problem. The exception is at the end of the county road. However, no significant noncoal waste, pop cans, etc. were observed during the instant inspection.

13. REVEGETATION

The perennial grass plant are dormant, likewise the annuals with the exception of a small Halogeton that germinated as a result of the last storm. The brouse plants are doing the best, in spite of the dry conditions.

16a. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Emery County repaired the county road into and out of the permitted area. The work consisted of repairing the drainage across the road. Also, some bumps were repaired.

21. BONDING AND INSURANCE

Insurance expires 11/5/2000. The surety bond is on records for \$90,758.00 and no bond release has been approved by the Division.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Tim Kirschbaum (Consol)

Henry Austin (OSM)

Given to: Pam Grubaugh-Littig (DOGM)

Filed to: Price Field Office

Date: August 16, 2000

Inspector's Signature: *Wm. J. Malencik*
Wm. J. Malencik

#26