



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340 telephone
(801) 359-3940 fax
(801) 538-7223 TTY
www.nr.utah.gov

Michael O. Leavitt
Governor
Robert L. Morgan
Executive Director
Lowell P. Braxton
Division Director

Handwritten initials: ORZ

Handwritten mark: ok

INSPECTION REPORT

Partial XXX Complete ___ Exploration ___
Inspection Date: 08/27/2002 / Time: 10:15 to 2:00
Date of Last Inspection: 07/10/2002

Mine Name: Hidden Valley Mine County: Emery Permit Number: C/015/007
Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P.O. Box 566, Sesser IL 62884/P.O. Box 527, Emery, Utah 84522
Company Official(s): Steve Behling Federal Official(s): None
State Official(s): Joe Helfrich
Weather Conditions: Sunny, 85
Type of Mining Activity: Underground XXX Surface ___ Prep Plant ___ Other ___
Existing Acreage: Permitted 960 Disturbed 7 Regraded ___ Seeded ___
Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; DIVERSIONS; SEDIMENT PONDS AND IMPOUNDMENTS; OTHER SEDIMENT CONTROL MEASURES; WATER MONITORING; EFFLUENT LIMITATIONS; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AS THE 4th Quarter- April, May, June); AIR QUALITY PERMIT; BONDING & INSURANCE.



INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/007

DATE OF INSPECTION: 08/27/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. **PERMITS, CHANGE, TRANSFER, RENEWAL, SALE**

The reclamation permit was renewed on January 29, 2002 and expires January 30, 2007. There are no amendments pending.

2. **SIGNS AND MARKERS**

Point of access signs and perimeter markers were correctly posted.

4C. **HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES**

The berms and ditches along the road, disturbed area, and reclaimed area were in good repair and functioning properly at the time of this inspection.

13. **REVEGETATION**

The shrubs, mat saltbush, fourwing saltbush, and shadscale were showing improved signs of vigor. Ivie Creek was flowing from above the reclaimed area to the main diversion channel at the time of this inspection.

Inspector's Signature: _____


Joseph C. Helfrich #1

Date: August 28, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Tim Kirschbaum, Consol, Illinois
Seth McCourt, Consol, Emery
Price Field office

O:\015007.HID\Compliance\2002\p_0827.doc