

0001



CONSOL ENERGY™

COPY

*015/007 Incoming
cc: Steve C.*

CONSOLIDATION COAL COMPANY

PO Box 566
Sesser, IL 62884

*#3410
OK*

Phone: (618)625-6847
Fax: (618)625-6844

February 10, 2010

Mr. Daron Haddock, Permit Supervisor
Utah Coal Regulatory Program
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

Re: Final Clean Copy
Hidden Valley Mine
Midterm Review

Dear Mr. Haddock:

Please find enclosed eight (8) clean copies of the revision to complete the Midterm Permit Review of the Hidden Valley Mine. The revision updates the Ownership and Control, Permit Listing and Notice of Violations of the last 3 years for Consol Energy and subsidiaries. The map entitled as "Surface & Coal Ownership" has been revised the permitted area under ACT/015/007 to reflect the name change from Hidden Valley Coal Company to Consolidation Coal noted as "CONSOL" on the map.

If you have any questions concerning this matter, please call me at (618)625-6847.

Sincerely,

Timothy D. Kirschbaum
Environmental Engineer

File in:

Confidential

Shelf

Expandable

Refer to Record No. 0001 Date 02/10/2010

In C. 0150007 2010 Incoming

For additional information

RECEIVED

FEB 16 2010

DIV. OF OIL, GAS & MINING

APPLICATION FOR COAL PERMIT PROCESSING

COPY

Permit Change New Permit Renewal Exploration Bond Release Transfer

Permittee: Consolidation Coal Company

Mine: Hidden Valley Mine

Permit Number: ACT/015/007

Title: Response to Midterm Permit Review, Task #3302.

Description, Include reason for application and timing required to implement:

Response to midterm review update legal information, ownership & control and bond rider.

Instructions: If you answer yes to any of the first eight (gray) questions, this application may require Public Notice publication.

- | | |
|---|---|
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 1. Change in the size of the Permit Area? Acres: _____ Disturbed Area: _____ <input type="checkbox"/> increase <input type="checkbox"/> decrease. |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 2. Is the application submitted as a result of a Division Order? DO# _____ |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 3. Does the application include operations outside a previously identified Cumulative Hydrologic Impact Area? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 4. Does the application include operations in hydrologic basins other than as currently approved? |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 5. Does the application result from cancellation, reduction or increase of insurance or reclamation bond? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 6. Does the application require or include public notice publication? |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 7. Does the application require or include ownership, control, right-of-entry, or compliance information? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 8. Is proposed activity within 100 feet of a public road or cemetery or 300 feet of an occupied dwelling? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 9. Is the application submitted as a result of a Violation? NOV # _____ |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 10. Is the application submitted as a result of other laws or regulations or policies?
<i>Explain:</i> _____ |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 11. Does the application affect the surface landowner or change the post mining land use? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 12. Does the application require or include underground design or mine sequence and timing? (Modification of R2P2) |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 13. Does the application require or include collection and reporting of any baseline information? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 14. Could the application have any effect on wildlife or vegetation outside the current disturbed area? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 15. Does the application require or include soil removal, storage or placement? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 16. Does the application require or include vegetation monitoring, removal or revegetation activities? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 17. Does the application require or include construction, modification, or removal of surface facilities? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 18. Does the application require or include water monitoring, sediment or drainage control measures? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 19. Does the application require or include certified designs, maps or calculation? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 20. Does the application require or include subsidence control or monitoring? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 21. Have reclamation costs for bonding been provided? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 22. Does the application involve a perennial stream, a stream buffer zone or discharges to a stream? |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 23. Does the application affect permits issued by other agencies or permits issued to other entities? |

Please attach four (4) review copies of the application. If the mine is on or adjacent to Forest Service land please submit five (5) copies, thank you. (These numbers include a copy for the Price Field Office)

I hereby certify that I am a responsible official of the applicant and that the information contained in this application is true and correct to the best of my information and belief in all respects with the laws of Utah in reference to commitments, undertakings, and obligations, herein.

Jonathan M. Pachter
Print Name

Jonathan M. Pachter 9/30/09
Sign Name, Position, Date
General Manager, Environmental Services

Subscribed and sworn to before me this 30 day of SEPTEMBER, 2009

Jane M. Young
Notary Public
My commission Expires: _____ 20____
Attest: State of PENNSYLVANIA
County of WASHINGTON

COMMONWEALTH OF PENNSYLVANIA
Notarial Seal
Jane M. Young, Notary Public
Cecll Twp., Washington County
My Commission Expires June 20, 2013
Member, Pennsylvania Association of Notaries

For Office Use Only:

Assigned Tracking
Number:

Received by Oil, Gas & Mining

RECEIVED
FEB 16 2010
DIV. OF OIL, GAS & MINING

I. Legal, Financial, and Compliance Information (R645-301-100)

The Hidden Valley Mine is owned by Consolidation Coal Company (Consol). Consolidation Coal Company is 100% owned by CONSOL Energy Inc. The first page of Appendix I is a chart of Consol's ownership structure.

Permit Applicant (112.210):	Consolidation Coal Company CNX Center 1000 Consol Energy Drive Canonsburg, PA 15317 (724) 485-4000
Resident Agent (112.220):	C T. Corporation System 175 South Main St. Salt Lake City, UT 84111
Person Who Will Pay Abandoned Mine Land Fee (112.230):	Consolidation Coal Company CNX Center 1000 Consol Energy Drive Canonsburg, PA 15317 (724) 485-4000
Mine Operator(112.300):	Consolidation Coal Company Route 148 North P.O. Box 566 Sesser, IL, 62884 (618) 625-2301
Mine Operation:	Hidden Valley Mine P. O. Box 527 Emery, UT 84522 (435) 286-3516

Consolidation Coal Company is a corporation, incorporated under the laws of the State of Delaware.

A list of the officers and directors of Consol is contained in Appendix I (112.300).

Revised 10/2009

Current or Previous Coal Mining Permits (112.400 and .410):

Appendix III contains a detailed listing of current, previous and pending coal mining related permits in the United States held, or applied for, by Consol.

Legal or Equitable Owners of Record (112.500 and .600):

The Legal or Equitable Owners of the Area to be affected by the Surface Operations and Facilities are:

Surface owner is Consolidation Coal Company;

The Holders of Record of Any Leasehold Interest in Areas to be Affected by Surface Operations or Facilities:

None

The following are the Owners of Coal Estate for the Mined Areas:

Ivie Creek Coal Company Shareholders Trust.

Surface and Mineral Ownership contiguous to Consolidation Coal Company:

Refer to Appendix II.

The Holders of Record of Any Leasehold Interest in the Coal to be Mined are:

Consolidation Coal Company – Assignment of Coal Lease recorded Emery County, Book 219, Pages 363-369.

MSHA Number (112.700):

No current Mine Safety and Health Administration identification number is assigned for the Hidden Valley Mine (112.700).

Option - Contiguous Lands (112.800):

There are no outstanding interests in lands, options or pending bids on interests held or made by the applicant for lands which are contiguous to the area to be covered by the permit

ATTACHMENT "C"

SURFACE AND MINERAL OWNERSHIP

CONTIGUOUS TO HIDDEN VALLEY COAL COMPANY

<u>Description</u>	<u>Surface</u>	<u>Mineral</u>
T23S, R5E,		
SEC 12	U.S.A	U.S.A.
SEC 13	U.S.A.	U.S.A.
SEC 24	State of Utah	State of Utah
	Subject to interest, If any, of Johnson Cattle Company. NOTE: Sevier County shows ownership of Johnson Cattle Company	
T23S, R6E,		
SEC 7, W1/2 and NE ¼	U.S.A	U.S.A.
SEC 7, SE1/4	100% Consolidation Coal Co.	100% Consolidation Coal Co.
SEC 8, W1/2	100% Consolidation Coal Co.	100% Consolidation Coal Co.
SEC 8, E1/2	U.S.A.	U.S.A.
SEC 18	100% Consolidation Coal	U.S.A. Lease from Ivie Creek Coal Company Shareholders Trust.
SEC 19	State of Utah.	State of Utah
SEC 20	U.S.A.	U.S.A.
SEC 17, E1/2	U.S.A.	U.S.A.
SEC 17 W1/2	100% Consolidation Coal Co.	Lease From Ivie Creek Coal Company Shareholders Trust


adit slope, with the resulting material removed from the slope to be used to flatten the area between the slope and Ivie Creek. After reconfiguration of the area, it is planned to remove rocky materials from the lower area of the access road and road slope to be used to apply a coarse fragment cover of approximate 12" thickness to the regraded "B" seam adit slope, and to create a series of depressions upon the slope through surface roughening. Selected material from the same source will be used to selectively apply a partial cover of coarse fragments to the flattened area between the slope and Ivie Creek. This area will also be surface roughened. Further, selected coarse materials will be used to effectively "riprap" the transition slope from the flattened area to existing grade (see drawing).

The expected result will be to restore the adit slope to more closely resemble the area prior to disturbance. The use of coarse, rocky material to cover the slope, in conjunction with surface roughening, will also serve to prevent erosion, and help in re-vegetation through water harvesting and the shading effect of the larger fragments. In regrading the area between the slope and the Creek, the result will be a flatter configuration that will serve to minimize erosion and to better harvest available moisture. Any possibility of this area flowing directly into Ivie Creek will be eliminated by construction of a deflection berm. The partial application of coarse fragments in combination with surface roughening over this general area is to provide the same benefits, i.e. the harvesting of moisture, shading, and the prevention of sediment production and transport.

Phase 2 of the two part project is to consist of the same treatment to the slope covering the "A" seam adit, with the exception that this slope will not require regrading, as it is presently at 2H: IV, which is about the steepest that can be safely traversed by construction equipment in application of coarse fragments. This phase of the will depend on the success evident with the first phase. Revegetation of disturbed sites in this part of the U.S. is, admittedly, difficult, and it is appropriate to evaluate the success of this first phase of the project prior to continuing.

D. Construction

The site will be accessed using the present roadway. Equipment will consist of a crawler bull dozer, an endloader, a hydraulic excavator, and necessary support such as fueling equipment and pickup trucks. The bulldozer will be used in the initial operations of pushing the present topsoil from the adit slope for redistribution on the surface in combination with the coarse material described below. The bulldozer will then regrade the adit slope, pushing the material from the slope to the area between the slope and Me Creek. Grading will be done so as to make certain that any dark material or material of suspect quality will not be exposed on the surface. Any dark lithochromic shale will be buried under the deepest layer of fill and soil cover. The endloader will then excavate, carry, and deposit the coarse material and surface soil on both the slope and the flattened area. The excavator will serve to place the coarse fragments on the area, as well as to roughen the surface. All machines will be used to configure and finish grade the roadway area so as to restore it to a condition such that future access is available.




Organizational Chart



CONSOL Energy Inc.
and Related Companies

Revised January 1, 2009 (Replaces August 31, 2007)
* Non permit holding entity



Organizational Chart




**CONSOL Energy Inc.
and Related Companies**

Revised January 1, 2009 (Replaces August 31, 2007)

* Non permit holding entity

¹ Assumed name - Powellton Coal Company, L.L.C.

² Assumed name - Powellton Coal Company



MAP LEGEND
 --- Permit Boundary 015007
 - - - - - Adjacent Property Boundary



SURFACE & COAL OWNERSHIP

CONSOLIDATION COAL COMPANY
 P.O. BOX 566
 SESSER, IL 62884-0566

HIDDEN VALLEY MINE
 DEPT. COUNTY, UTAH
 PERMIT NO. ACT015/007

APPROVED BY: TDK
100% DRAWN BY: TDK
CHECKED BY: JAG
ORIGINAL DATE: 9/09

NO.	DATE	BY	DESCRIPTION

EXTERNAL REFERENCES:
 Permit Midterm 2009 Block_03.dwg
 Permit Midterm USGS Topo_03.dwg
 Permit Midterm 2009 NA003-Propor.dwg
 ModifedBar_faces.dwg

DATE: 1/21/2010 1:31:39 PM
PROJECT: Permit Midterm 2009.n83v8.dgn



Ownership and Control Report

Sep/28/2009

Company Name: AMVEST Coal & Rail, L.L.C.
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 54-0696869 **Ownership/Control relationship to CONSOL Energy Inc.:** 3rd Tier Subsidiary

Entity I.D.:	AMVEST Coal & Rail, L.L.C.	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
	AMVEST Minerals Company, L.L.C.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 54-0696869	Sole Shareholder	100%		
	Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009	
	Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724)485-4000	PA 15317	Manager	zero	08/21/2008	
	Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724)485-4000	PA 15317	President	zero	02/19/2009	
	Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	06/23/2008	
	William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007	
	Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/23/2008	
	Robert F. Pusateri	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007	

Entity I.D.: AMVEST Coal & Rail, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	08/28/2007	
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/19/2009	
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007	
Martha A. Wiegand	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	02/19/2009	

Company Name: AMVEST Corporation
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 54-0696869 **Ownership/Control relationship to CONSOL Energy Inc.:** 1st Tier Subsidiary

Entity I.D.:	AMVEST Corporation	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
CONSOL Energy Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	51-0337383	Sole Shareholder	100%	07/31/2007	
Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Director	zero	02/19/2009	
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Director	zero	07/31/2007	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Director	zero	07/31/2007	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		President	zero	02/19/2009	
Stephen W. Johnson	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Vice President	zero	02/19/2009	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Director	zero	07/31/2007	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Vice President	zero	07/31/2007	

Entity I.D.: AMVEST Corporation

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000 PA 15317		Chief Financial Officer	zero	08/14/2007	
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000 PA 15317		Director	zero	07/31/2007	
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000 PA 15317		Treasurer	zero	07/31/2007	
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000 PA 15317		Secretary	zero	07/31/2007	
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200 VA 24631		Vice President	N/A	02/19/2009	
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000 PA 15317		Director	zero	07/31/2007	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000 PA 15317		Assistant Secretary	zero	07/31/2007	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000 PA 15317		Controller	zero	07/31/2007	

Company Name: AMVEST Minerals Company, L.L.C.

Mailing Address: 1000 CONSOL Energy Drive

City: Canonsburg **State:** PA **ZIP:** 15317

Telephone No.: (724) 485-4000

FEIN: 54-0696869 **Ownership/Control relationship to CONSOL Energy Inc.:** 2nd Tier Subsidiary

Entity I.D.:	AMVEST Minerals Company, L.L.C.			Start Date	
Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	End Date
AMVEST Corporation	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 54-0696869	Sole Shareholder	100%	
Nicholas J. Deluilis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009
William D. Gillenwater	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/14/2007
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	08/14/2007
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/14/2007
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chief Financial Officer	zero	08/14/2007

Entity I.D.: AMVEST Minerals Company, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/14/2007	
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	08/14/2007	
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	08/14/2007	
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/19/2009	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero	08/14/2007	

Company Name: AMVEST West Virginia Coal, L.L.C.
Mailing Address: P.O. Box 133, WV State Route 16
City: Bickmore **State:** WV **ZIP:** 25019 **Telephone No.:** (304) 587-6300
FEIN: 54-1860378 **Ownership/Control relationship to CONSOL Energy Inc.:** 6th Tier Subsidiary

Entity I.D.:	AMVEST West Virginia Coal, L.L.C.			Start Date	
Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	End Date
Nicholas-Clay Land & Mineral, Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 55-0719265	Shareholder	70%	
Terry Eagle Limited Partnership	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 31-0995566	Shareholder	30%	
Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009
Kenneth R. Gilliland	P.O. Box 133, WV State Route 16 Bickmore (304) 587-6300	WV 25019	Vice President	zero	08/28/2007
John A. Goroncy	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A	02/19/2009
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/21/2008
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009
Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/23/2008

Sep/28/2009

Entity I.D.: AMVEST West Virginia Coal, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	02/19/2009	
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	02/19/2009	
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/19/2009	
Reginald G. Roles	P. O. Box 133, WV State Route 16 Bickmore (304) 587-6300	WV 25019	Vice President	zero	08/28/2007	02/27/2009

Company Name: Central Ohio Coal Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 31-4356096 **Ownership/Control relationship to CONSOL Energy Inc.:** 2nd Tier Subsidiary

Entity I.D.:	Central Ohio Coal Company		Start Date		
Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	End Date
Consolidation Coal Company	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 13-2566594	Sole Shareholder	100%	
Daniel S. Cangilla	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	01/01/2006
Nicholas J. Deluilis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009
Rodney E. Ford	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	N/A	06/15/2003
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	07/02/2001
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chairman	zero	02/19/2009
Stephen W. Johnson	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	10/09/2007

Entity I.D.: Central Ohio Coal Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Dennis R. McCracken	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	06/01/2006	
Lloyd C. Price	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A	06/15/2003	
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	10/09/2007	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	N/A	03/01/2006	

Company Name: CONSOL Energy Inc.
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 51-0337383 **Ownership/Control relationship to CONSOL Energy Inc.:** Same

Entity I.D.:	CONSOL Energy Inc.	Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
		Randall M. Albert	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Senior Vice President	zero		02/05/2009
		Albert A. Aloia	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Senior Vice President	N/A		11/21/2005
		James E. Altmeyer	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A		11/07/2003
		Louis Barletta Jr.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		09/07/2006
		Philip W. Baxter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A		01/16/2009
		Robert M. Belesky	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		02/05/2009
		James A. Brock	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Senior Vice President	zero		12/03/2007
		William E. Davis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A		01/20/2004

Sep/28/2009

Entity I.D.: CONSOL Energy Inc.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Nicholas J. DeLuijs	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chief Operating Officer	zero	01/16/2009	
Nicholas J. DeLuijs	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Executive Vice President	zero	01/16/2009	
Cecil L. Delloma	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	09/01/2005	
Stephanie L. Gill	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	N/A	01/01/2006	
William D. Gillenwater	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/05/2009	
Raj K. Gupta	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A	02/23/2004	
Patricia A. Hammick	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A	06/11/2001	
David C. Hardesty, Jr.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A	10/18/2005	
M. Charles Hardoby	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/05/2009	
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chief Executive Officer	zero	01/01/1998	

Sep/28/2009

Entity I.D.: CONSOL Energy Inc.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	01/01/1998	
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	01/01/1998	
Thomas F. Hoffman	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Senior Vice President	N/A	02/02/2007	
Darryl M. Husenits	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/05/2009	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chief Operating Officer	zero	02/02/2007	
Stephen W. Johnson	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	General Counsel	zero	02/05/2009	
Stephen W. Johnson	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Senior Vice President	zero	02/05/2009	
Thomas O. Johnson	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	04/07/2008	
David W. Kelly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	01/16/2009	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Executive Vice President	zero	01/16/2009	

Entity I.D.: CONSOL Energy Inc.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chief Financial Officer	N/A		12/01/2000
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Executive Vice President	N/A		05/04/2005
James J. McCaffrey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Senior Vice President	zero		04/07/2008
Michael D. McLean	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		02/05/2009
John T. Mills	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A		03/10/2006
J. Michael Onifer	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Senior Vice President	zero		02/05/2009
William P. Powell	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A		01/20/2004
Robert F. Pusateri	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Executive Vice President	zero		01/16/2009
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	N/A		10/23/2002
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A		05/03/2005

Entity I.D.: CONSOL Energy Inc.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A		05/20/2008
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chief Legal Officer	zero		01/16/2009
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Executive Vice President	zero		01/16/2009
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero		03/01/2005
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	N/A		05/03/2005
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A		05/03/2005
George F. Rosato	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A		08/01/2006
Charles T. Shaynak	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		12/03/2007
Donna A. Spec	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero		07/09/2007
John L. Whitmire	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A		03/03/1999

Entity I.D.: CONSOL Energy Inc.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Joseph T. Williams	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A	01/20/2004	
Steven E. Winberg	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	12/03/2007	
Daniel Zajdel	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	03/23/2009	

Company Name: CONSOL Financial Inc.
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 51-0395375 **Ownership/Control relationship to CONSOL Energy Inc.:** 1st Tier Subsidiary

Entity I.D.:	CONSOL Financial Inc.	Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
		CONSOL Energy Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 51-0337383	Sole Shareholder	100%	11/24/1999	
		James A. Brock	1800 Washington Road Pittsburgh (412) 831-4000	PA 15241	Director	zero	12/13/2007	
		Donald J. Bromley	1800 Washington Road Pittsburgh (412) 831-4000	PA 15241	Director	zero	11/01/2006	
		Donald J. Bromley	1800 Washington Road Pittsburgh (412) 831-4000	PA 15241	President	zero	11/01/2006	
		Donald J. Bromley	1800 Washington Road Pittsburgh (412) 831-4000	PA 15241	Treasurer	zero	12/13/2007	
		Christopher C. Jones	1800 Washington Road Pittsburgh (412) 831-4000	PA 15241	Secretary	zero	12/13/2007	
		Christopher C. Jones	1800 Washington Road Pittsburgh (412) 831-4000	PA 15241	Vice President	zero	12/13/2007	
		William J. Lyons	1800 Washington Road Pittsburgh (412) 831-4000	PA 15241	Director	zero	12/01/2003	

Entity I.D.: CONSOL Financial Inc.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Lorraine L. Ritter	1800 Washington Road Pittsburgh (412) 831-4000	PA 15241	Assistant Secretary	zero		12/13/2007
Lorraine L. Ritter	1800 Washington Road Pittsburgh (412) 831-4000	PA 15241	Vice President	zero		11/01/2006

Company Name: CONSOL of Central Pennsylvania LLC
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 20-5105698 **Ownership/Control relationship to CONSOL Energy Inc.:** 1st Tier Subsidiary

Entity I.D.: CONSOL of Central Pennsylvania LLC

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
CONSOL Energy Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 51-0337383	Member	100%	06/22/2006	
Albert A. Aloia	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A	02/19/2009	
Louis Barletta Jr.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	04/17/2007	
James A. Brock	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	03/27/2009	
Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/21/2008	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009	
Stephen W. Johnson	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009	

Sep/28/2009

Entity I.D.: CONSOL of Central Pennsylvania LLC

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/21/2008	
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/21/2008	
Brian T. Murdy	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Controller	zero	03/27/2009	
Brian T. Murdy	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Treasurer	zero	03/27/2009	
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	06/22/2006	
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	06/22/2006	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/22/2006	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero	06/22/2006	

Company Name: CONSOL of Kentucky Inc.
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 94-2524120 **Ownership/Control relationship to CONSOL Energy Inc.:** 1st Tier Subsidiary

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
CONSOL Energy Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	51-0337383	Sole Shareholder	100%	01/01/1993	
Nicholas J. Deluilis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Director	zero	02/19/2009	
Rodney E. Ford	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Assistant Secretary	N/A	06/15/2003	
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Director	zero	08/31/1998	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		President	zero	10/09/2007	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Vice President	zero	08/21/2006	
James J. McCaffrey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Vice President	zero	02/19/2009	
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Treasurer	zero	09/01/1998	

Sep/28/2009

Entity I.D.: CONSOL of Kentucky Inc.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A		12/01/2003
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		03/01/2005
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero		03/01/2006
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	N/A		03/01/2006
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	N/A		01/01/2006
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A		01/01/2006

Company Name: CONSOL of Ohio LLC
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 20-8338255 **Ownership/Control relationship to CONSOL Energy Inc.:** 1st Tier Subsidiary

Entity I.D.:	CONSOL of Ohio LLC		Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
CONSOL Energy Inc.	PA	15317	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	51-0337383	Member	100%	01/26/2007	
Nicholas J. Deluiliis	PA	15317	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Manager	zero	02/19/2009	
Bart J. Hyita	PA	15317	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Chief Executive Officer	zero	02/19/2009	
Bart J. Hyita	PA	15317	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Manager	zero	08/21/2008	
Bart J. Hyita	PA	15317	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		President	zero	02/19/2009	
Steven W. Johnson	PA	15317	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Manager	zero	02/19/2009	
Robert P. King	PA	15317	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Manager	zero	06/23/2008	
Robert P. King	PA	15317	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Vice President	zero	02/19/2009	

Sep/28/2009

Entity I.D.: CONSOL of Ohio LLC

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/21/2008	
Brian T. Murdy	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Controller	zero	03/27/2009	
Brian T. Murdy	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Treasurer	zero	03/27/2009	
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	01/26/2007	
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	01/26/2007	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	01/26/2007	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero	01/26/2007	

Company Name: CONSOL of WV LLC
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317
FEIN: 20-2471235 **Telephone No.:** (724) 485-4000
Ownership/Control relationship to CONSOL Energy Inc.:
 1st Tier Subsidiary

Entity I.D.:	Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
	CONSOL Energy Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Member	100%	03/10/2005	
	Louis Barletta Jr.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	04/17/2007	
	Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009	
	Cecil L. Delloma	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	04/17/2007	
	Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	06/23/2008	
	Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009	
	Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	07/16/2008	
	Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/23/2008	

Entity I.D.: CONSOL of WV LLC

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	N/A	01/01/2006	
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	04/17/2007	
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/19/2009	

Company Name: Consol Pennsylvania Coal Company LLC
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 20-8732852 **Ownership/Control relationship to CONSOL Energy Inc.:** 1st Tier Subsidiary

Entity I.D.: Consol Pennsylvania Coal Company LLC

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
CONSOL Energy Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 51-0337383	Member	100%	06/01/2007	
Nicholas J. Delujis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009	
Rodney E. Ford	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/01/2007	
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	06/01/2007	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	10/09/2007	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/20/2009	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	06/01/2007	
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero	06/01/2007	

Sep/28/2009

Entity I.D.: Consol Pennsylvania Coal Company LLC

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	06/01/2007	
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	06/01/2007	
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	06/01/2007	
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	06/01/2007	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/01/2007	
Charles T. Shaynak	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009	

Company Name: Consolidation Coal Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 13-2566594 **Ownership/Control relationship to CONSOL Energy Inc.:** 1st Tier Subsidiary

Entity I.D.:	Consolidation Coal Company		Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
CONSOL Energy Inc.			1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	51-0337383 Sole Shareholder	100%	01/01/1992	
Louis Barletta Jr.			1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	01/01/2006	
James A. Brock			1 Bridge Street Monongah (304) 534-4700	WV 26554	Vice President	zero	09/12/2005	
Daniel S. Cangilla			1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	01/01/2006	
Nicholas J. Deluiliis			1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009	
Rodney E. Ford			1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/15/2003	
J. Brett Harvey			1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chairman	zero	10/09/2007	
J. Brett Harvey			1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chief Executive Officer	zero	10/09/2007	

Entity I.D.: Consolidation Coal Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	01/01/1998	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chief Operating Officer	zero	10/09/2007	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	01/01/2006	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009	
David W. Kelly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/20/2009	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	10/09/2007	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	08/21/2006	
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	09/30/2000	
Brian T. Murdy	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	02/20/2009	
Robert F. Pusateri	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/21/2008	

Entity I.D.: Consolidation Coal Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	10/09/2007	
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/20/2009	
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	03/01/2005	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	03/01/2006	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero	10/09/2007	
Charles T. Shaynak	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/20/2009	

Company Name: Eighty-Four Mining Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 25-1696903 **Ownership/Control relationship to CONSOL Energy Inc.:** 2nd Tier Subsidiary

Entity I.D.:	Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
	CONSOL Financial Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Sole Shareholder	100%		
	Albert A. Aloia	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	N/A	02/19/2009	
	Louis Barletta Jr.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A	01/01/2006	
	Daniel S. Cangilla	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	N/A	01/01/2006	
	Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009	
	Rodney E. Ford	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	N/A	06/15/2003	
	J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	N/A	09/22/1998	
	Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	11/01/2004	

Entity I.D.: Eighty-Four Mining Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		08/21/2006
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	N/A		10/09/2007
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		03/01/2005
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	N/A		03/01/2006

Company Name: Fola Coal Company, L.L.C.
Mailing Address: P.O. Box 180, WV State Route 16
City: Bickmore **State:** WV **ZIP:** 25019 **Telephone No.:** (304) 587-6300
FEIN: 54-1860378 **Ownership/Control relationship to CONSOL Energy Inc.:** 7th Tier Subsidiary

Entity I.D.:	Fola Coal Company, L.L.C.			Start Date	
Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	End Date
AMVEST West Virginia Coal, L.L.C.	P.O. Box 133, WV State Route 16 Bickmore (304) 587-6300	54-1860378	Sole Shareholder	100%	
Louis Barletta Jr.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	08/28/2007
Nicholas J. DelJulis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009
Kenneth R. Gilliland	P.O. Box 180, WV State Route 16 Bickmore (304) 587-6300	WV 25019	Vice President	zero	08/28/2007
John A. Goroncy	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A	02/19/2009
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009
Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/23/2008

Entity I.D.: Fola Coal Company, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	09/23/2008	
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/19/2009	
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	08/28/2007	

Company Name: Glamorgan Coal Company, L.L.C.
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 54-0696869 **Ownership/Control relationship to CONSOL Energy Inc.:** 3rd Tier Subsidiary

Entity I.D.: Glamorgan Coal Company, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
AMVEST Minerals Company, L.L.C.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	54-0696869	Sole Shareholder	100%		
Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	06/23/2008	
Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/23/2008	
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	08/28/2007	

Entity I.D.: Glamorgan Coal Company, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A		02/19/2009
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero		08/28/2007

Company Name: Helvetia Coal Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317
FEIN: 25-1180531 **Ownership/Control relationship to CONSOL Energy Inc.:**

Telephone No.: (724) 485-4000
 3rd Tier Subsidiary

Entity I.D.: Helvetia Coal Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Rochester & Pittsburgh Coal Company	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	25-0761480	Sole Shareholder	100%		04/07/1986
Daniel S. Cangjilla	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero		01/01/2006
Nicholas J. Deluljis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		02/19/2009
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		09/22/1998
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero		02/19/2009
Stephen W. Johnson	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		02/19/2009
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		10/09/2007
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero		10/09/2007

Sep/28/2009

Entity I.D.: Helvetia Coal Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero		03/01/2006
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero		10/09/2007

Company Name: Island Creek Coal Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 55-0479426 **Ownership/Control relationship to CONSOL Energy Inc.:** 2nd Tier Subsidiary

Entity I.D.:	Island Creek Coal Company	Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
		Consolidation Coal Company	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 13-2566594	Sole Shareholder	100%		
		Louis Barletta Jr.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	05/01/2006	
		Daniel S. Cangilla	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	01/01/2006	
		Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009	
		J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/31/1998	
		Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	10/09/2007	
		William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	11/01/2004	
		Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	10/09/2007	

Entity I.D.: Island Creek Coal Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/19/2009	
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	03/01/2005	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	03/01/2006	

Sep/28/2009

Entity I.D.: Keystone Coal Mining Corporation

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero		03/01/2006
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero		10/09/2007

Company Name: Laurel Run Mining Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 54-0892422 **Ownership/Control relationship to CONSOL Energy Inc.:** 3rd Tier Subsidiary

Entity I.D.:	Laurel Run Mining Company			Start Date	
Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	End Date
Island Creek Coal Company	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 55-0479426	Sole Shareholder	100%	
Louis Barletta Jr.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	05/01/2006
Daniel S. Cangilla	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	01/01/2006
Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/31/1998
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Chairman	zero	02/19/2009
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	10/09/2007
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009

Entity I.D.: Laurel Run Mining Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Stephen W. Johnson	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009	
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	10/09/2007	
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	10/09/2007	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	03/01/2006	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero	10/09/2007	

Company Name: Little Eagle Coal Company, L.L.C.
Mailing Address: P.O. Box 134, WV State Route 16
City: Bickmore **State:** WV **ZIP:** 25019 **Telephone No.:** (304) 587-6300
FEIN: 22-3864739 **Ownership/Control relationship to CONSOL Energy Inc.:**
 7th Tier Subsidiary

Entity I.D.: Little Eagle Coal Company, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
AMVEST West Virginia Coal, L.L.C.	P.O. Box 133, WV State Route 16 Bickmore (304) 587-6300	54-1860378	Sole Shareholder	100%		
Nicholas J. Delulius	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Manager	zero		02/19/2009
John A. Goroncy	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Vice President	N/A		02/19/2009
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Manager	zero		08/28/2007
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		President	zero		02/19/2009
Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Assistant Secretary	zero		06/23/2008
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Treasurer	zero		02/19/2009
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000		Secretary	zero		08/28/2007

Sep/28/2009

Entity I.D.: Little Eagle Coal Company, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A		02/19/2009

Company Name: McElroy Coal Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 25-1553551 **Ownership/Control relationship to CONSOL Energy Inc.:** 2nd Tier Subsidiary

Entity I.D.:	McElroy Coal Company	Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
		Consolidation Coal Company	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 13-2566594	Sole Shareholder	100%	06/30/1987	
		Daniel S. Cangilla	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	01/01/2006	
		Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009	
		J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/31/1998	
		Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	10/09/2007	
		David W. Kelly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009	
		Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009	
		Brian T. Murdy	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	02/19/2009	

Sep/28/2009

Entity I.D.: McElroy Coal Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		03/01/2005
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero		03/01/2006
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero		10/09/2007
Robert M. Vukas	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero		01/01/2006

Company Name: Nicholas-Clay Land & Mineral, Inc.
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 55-0719265 **Ownership/Control relationship to CONSOL Energy Inc.:** 4th Tier Subsidiary

Entity I.D.: Nicholas-Clay Land & Mineral, Inc.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
AMVEST Coal & Rail, L.L.C.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	54-0696869	Sole Shareholder	100%		
Nicholas J. Delulius	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009	
William D. Gillenwater	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/28/2007	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/28/2007	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009	
James J. McCaffrey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/21/2008	
Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/23/2008	

Entity I.D.: Nicholas-Clay Land & Mineral, Inc.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	02/19/2009	
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	08/28/2007	
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/19/2009	
Christopher S. Butler	2720 Pennsylvania Avenue Charleston (304) 345-2859	WV 25302	Vice President	zero	08/28/2007	04/30/2009

Company Name: Reserve Coal Properties Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 25-1582519 **Ownership/Control relationship to CONSOL Energy Inc.:**
 1st Tier Subsidiary

Entity I.D.:	Reserve Coal Properties Company	Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
		CONSOL Energy Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	51-0337383	Sole Shareholder	100%	01/01/2001	
		Lu Ann Datesh	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	03/01/2006	
		Rodney E. Ford	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/15/2003	
		William D. Gillenwater	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009	
		J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	11/01/1999	
		Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/21/2006	
		Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	08/21/2006	
		James J. McCaffrey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	10/09/2007	

Entity I.D.: Reserve Coal Properties Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Dennis R. McCracken	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		06/01/2006
Lloyd C. Price	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		06/15/2003
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero		11/01/2004
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero		03/01/2006
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero		01/01/2006

Company Name: Southern Ohio Coal Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 55-0403282 **Ownership/Control relationship to CONSOL Energy Inc.:** 2nd Tier Subsidiary

Entity I.D.: Southern Ohio Coal Company		Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Consolidation Coal Company	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	13-2566594	Sole Shareholder	100%		
Albert A. Aloia	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Vice President	N/A		02/19/2009
Louis Barletta Jr.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Vice President	zero		05/01/2006
Daniel S. Cangilla	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Treasurer	zero		01/01/2006
Nicholas J. Delujis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Chairman	zero		02/19/2009
Nicholas J. Delujis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Director	zero		02/19/2009
J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		Director	zero		07/02/2001
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317		President	zero		10/09/2007

Sep/28/2009

Entity I.D.: Southern Ohio Coal Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Stephen W. Johnson	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		02/19/2009
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		08/21/2006
Dennis R. McCracken	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		06/01/2006
Lloyd C. Price	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A		06/15/2003
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero		10/09/2007
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero		03/01/2006

Company Name: TEAGLE Company, L.L.C.
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 54-0698869 **Ownership/Control relationship to CONSOL Energy Inc.:** 4th Tier Subsidiary

Entity I.D.: TEAGLE Company, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
AMVEST Coal & Rail, L.L.C.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	54-0698869	Sole Shareholder	100%		
Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009	
William D. Gillenwater	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007	
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007	
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009	
Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/23/2008	

Entity I.D.: TEAGLE Company, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	02/19/2009	
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/19/2009	
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	08/28/2007	
Christopher S. Butler	2720 Pennsylvania Avenue Charleston (304) 345-2859	WV 25302	Vice President	zero	08/28/2007	04/30/2009

Company Name: TECPART Corporation
Mailing Address: 1000 CONSOL Energy Drive
 State: PA ZIP: 15317 Telephone No.: (724) 485-4000
FEIN: 13-3038238 Ownership/Control relationship
 to CONSOL Energy Inc.: 4th Tier Subsidiary

Entity I.D.:	TECPART Corporation		Start Date		
Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	End Date
AMVEST Coal & Rail, L.L.C.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 54-0696869	Sole Shareholder	100%	
Nicholas J. Delulius	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/28/2007
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/28/2007
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009
Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/23/2008
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	02/19/2009

Entity I.D.: **TECPART Corporation**

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A	02/19/2009	
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	08/28/2007	
Christopher S. Butler	2720 Pennsylvania Avenue Charleston (304) 345-2859	WV 25302	Vice President	zero	08/28/2007	04/30/2009

Company Name: Terry Eagle Coal Company, L.L.C.
Mailing Address: P.O. Box 157, WV State Route 16
City: Bickmore **State:** WV **ZIP:** 25019 **Telephone No.:** (304) 587-6300
FEIN: 54-1860378 **Ownership/Control relationship to CONSOL Energy Inc.:** 7th Tier Subsidiary

Entity I.D.:	Terry Eagle Coal Company, L.L.C.			Start Date	End Date
Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	
AMVEST West Virginia Coal, L.L.C.	P.O. Box 133, WV State Route 16 Bickmore (304) 587-6300	54-1860378	Sole Shareholder	100%	
Nicholas J. Deluiliis	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	02/19/2009
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007
Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Manager	zero	08/28/2007
Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009
Scott G. O'Mara	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/23/2008
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	08/28/2007

Sep/28/2009

Entity I.D.: Terry Eagle Coal Company, L.L.C.

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero		09/23/2008
Jack K. Richardson	10545 Riverside Drive Oakwood (276) 498-8200	VA 24631	Vice President	N/A		02/19/2009
Reginald G. Roles	P.O. Box 157, WV State Route 16 Bickmore (304) 587-6300	WV 25019	Vice President	zero		08/28/2007 02/27/2009
Christopher S. Butler	2720 Pennsylvania Avenue Charleston (304) 345-2859	WV 25302	Vice President	zero		08/28/2007 04/30/2009

Company Name: Terry Eagle Limited Partnership
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317
FEIN: 31-0995566 **Telephone No.:** (724) 485-4000
Ownership/Control relationship to CONSOL Energy Inc.: 5th Tier Subsidiary

Entity I.D.: Terry Eagle Limited Partnership

Entity Name	Address & Telephone No.	PA	SS # or FEIN #	Title	% Ownership	Start Date	End Date
TEAGLE Company, L.L.C.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA	15317	Shareholder	50%		
TECPART Corporation	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA	15317	Shareholder	50%		

Company Name: Windsor Coal Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 13-5488703 **Ownership/Control relationship to CONSOL Energy Inc.:** 2nd Tier Subsidiary

Entity I.D.:	Windsor Coal Company	Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
		Consolidation Coal Company	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317 13-2566594	Sole Shareholder	100%		
		Daniel S. Cangilla	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	01/01/2006	
		Nicholas J. Delulius	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	02/19/2009	
		Rodney E. Ford	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	06/15/2003	
		J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	07/02/2001	
		Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	10/09/2007	
		Bart J. Hyita	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	02/19/2009	
		Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	08/21/2006	

Entity I.D.: Windsor Coal Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		11/01/2004
Dennis R. McCracken	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		06/01/2006
Lloyd C. Price	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero		06/15/2003
Alexander J. Reyes	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero		10/09/2007
P. Jerome Richey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero		03/01/2005
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero		03/01/2006

Company Name: Wolfpen Knob Development Company
Mailing Address: 1000 CONSOL Energy Drive
City: Canonsburg **State:** PA **ZIP:** 15317 **Telephone No.:** (724) 485-4000
FEIN: 25-1391218 **Ownership/Control relationship to CONSOL Energy Inc.:** 1st Tier Subsidiary

Entity I.D.:	Wolfpen Knob Development Company	Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
		CONSOL Energy Inc.	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	51-0337383	Sole Shareholder	100%	01/01/1993	
		Lu Ann Datesh	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Secretary	zero	03/01/2006	
		Rodney E. Ford	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	N/A	06/15/2003	
		William D. Gillenwater	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	02/19/2009	
		J. Brett Harvey	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/31/1998	
		Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	08/21/2006	
		Robert P. King	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	President	zero	08/21/2006	
		William J. Lyons	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Director	zero	07/10/2002	

Entity I.D.: Wolfpen Knob Development Company

Entity Name	Address & Telephone No.	SS # or FEIN #	Title	% Ownership	Start Date	End Date
Dennis R. McCracken	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	zero	06/01/2006	
Lloyd C. Price	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Vice President	N/A	06/15/2003	
John M. Reilly	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Treasurer	zero	09/01/1998	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Assistant Secretary	zero	03/01/2006	
Lorraine L. Ritter	1000 CONSOL Energy Drive Canonsburg (724) 485-4000	PA 15317	Controller	zero	01/01/2006	

CONSOL Energy Inc. - Mining Permit Listing for All Subsidiaries

Mailing Address: 1000 CONSOL Energy Drive

City: Canonsburg **State:** PA **ZIP:** 15317

Telephone No.: (724) 485-4000

Permittee: Central Ohio Coal Company

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
OH						
D-1034	OH	DMRM	Brannon Fork	09/09/1993		
D-2047	OH	DMRM	Dinner Fork	05/12/2000		
D-322	OH	DMRM	Haulroad	04/30/1984		
D-378	OH	DMRM	Haulroad - N. Tipple Area	07/13/1984		
D-313	OH	DMRM	Haulroad- Complex to 3 m	04/17/1984		
D-1084	OH	DMRM	Horse Run	07/21/1994		
D-246	OH	DMRM	Interconnector Haulroad	12/01/1983		
D-839	OH	DMRM	Knowlton	05/15/1989		
D-56	OH	DMRM	North Tipple Area	08/16/1982		
D-420	OH	DMRM	OCTAD	10/11/1984		
D-678	OH	DMRM	Olive Green South	06/15/1987		
D-215	OH	DMRM	Preparation Plant	12/20/1983		
D-321	OH	DMRM	Skyline Drive Haulroad	04/30/1984		
D-261	OH	DMRM	State Route 340	01/13/1984		
D-559	OH	DMRM	Titton Run	03/13/1986		
D-820	OH	DMRM	Windy Hill	12/14/1988		

Permittee: CONSOL of Kentucky Inc.

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
413-0510	KY DSMR			12/09/1980		final bond release, no record in KYDSMRE SMIS
413-5057	KY DSMR			06/09/1988		final bond release, no record in KYDSMRE SMIS
867-0369	KY DSM			07/12/1988		former Fairbanks Coal 867-0299
867-0370	KY DSM	Fairbanks Coal Co Inc		05/11/1990		former Fairbanks Coal 867-0324
867-0441	KY DSMRE			08/27/2002		Application submitted 8/27/2002.
867-0428	KY DSMRE	Reedy Coal Co.	Area #70 - Reedy #15 UG	02/26/2002	02/26/2007	1 Abandoned Hz #4 UG Mine Site and 1 Abandoned WB &
860-0312	KY DSM		Big Springs #16 UG, #17	06/15/1993	06/15/2008	2 Abandoned Hz #4 UG Mine Sites and 1 inactive CT Mine
860-5181	KY DSM		Brushy 11	02/18/1994		closed mine
877-0166	KY DSMRE	Locust Grove Inc.	Bull Creek Strip	07/15/2005	07/15/2010	
877-0189	KY DSM		Bull Creek West	07/21/2008		Active
860-5257	KY DSMRE		Caney E-1 UG	03/01/2006	03/01/2011	
867-0456	KY DSMRE		Deane Area - Upper Sea	04/05/2005		Application submitted 04/05/2005.
860-5117	KY DSM		E-1 South	02/06/1991	02/06/2006	Jones Fork Office & Bath House Site
867-0407	KY DSMRE		Fairbanks - Cane Fork CT	06/09/2000	06/09/2005	Abandoned E-3, AM, WB, & Hz #4 CT Mine Site; Includes
867-0451	KY DSMRE		Fairbanks CT	10/06/2004	04/01/2006	Application permanently withdrawn April 2006. Submitted 1
867-0409	KY DSMRE		H&D Coal - Area #1	07/17/2002	07/17/2007	Abandoned WB & Hz #4 CT Mine Site; Permit approved 7/1
867-0446	KY DSMRE	H&D Coal Co. Inc.	H&D Coal - Taylor Metal	06/04/2004	06/04/2009	Active Hz #4 CT Mine Site; Application submitted 4/17/2003
836-5461	KY DSMRE		Hick's Branch Hz #4 UG	08/20/2004	10/18/2005	Idle Hz #4 UG Mine Site; Succession permit from AEP 836-
860-0333	KY DSM		Hunter Branch - MT-15	11/10/1993	11/10/1998	Abandoned MT & CT Mine Site
867-5225	KY DSM		Jarisa E-3 on Rt 317	08/23/1999	08/23/2009	Abandoned & Reclaimed E-3 UG Mine Site
836-6015	KY DSM		Jett Loadout	08/24/1987	08/24/2007	Idle Loadout Site
860-5263	KY DSMRE		Jones Fork - Beaver Gap			Appl Rec'd 8/1/07
860-0430	KY DSMRE		Jones Fork - Yellow Mtn	06/06/2007	06/06/2012	
860-9007	KY DSM		Jones Fork Coarse Refus	05/17/1999	05/17/2009	Active Coarse Refuse Fill Site
860-8005	KY DSM		Jones Fork Prep Plant	11/13/1990	11/13/2005	Active Preparation Plant Site

Permittee: CONSOL of Kentucky Inc.

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
860-9000	KY DSM		Jones Fork Slurry Impoun	02/06/1991	02/06/2006	Active Slurry Impoundment Site
836-5238	KY DSM	Murriell-Don Coal Inc.	Lick Fork UG Mine - Murri	08/06/1990	08/06/2005	1 Abandoned & 1 Active E-3 UG Mine Sites
867-5192	KY DSM		Loves Br. Hz #4 UG, Ree	02/29/1996	03/01/2006	2 Abandoned Hz #4 UG Mine Sites
867-0383	KY DSM	Fairbanks Coal Co Inc	Lower Appletree Br. CT	04/21/1997	04/21/2002	Abandoned E-2, E-3, & AM CT Mine Site
836-5455	KY DSMRE		Marshall Mining # 7 E-1 U	01/07/2004	01/07/2009	Active E-1 UG Mine Site
860-5278	KY DSM	Marshall Mining Inc.	Marshall Mining 4A	06/04/2007	06/04/2012	
867-5182	KY DSM		Mill Cr. E-3, Beaver Gap	02/04/1994	02/04/2004	4 Active E-3 UG Mine Sites
867-9007	KY DSM		Mill Creek Impoundment	07/21/1992	07/21/2012	Active Slurry Impoundment Site
867-8042	KY DSM		Mill Creek Loadout	03/02/1992	03/02/1997	Active Loadout Site
867-8041	KY DSM		Mill Creek Prep Plant	12/21/1990	12/12/2010	Active Preparation Plant Site
860-5147	KY DSM		Mott's Branch E-1 UG & B	11/23/1992	11/23/2002	2 Abandoned E-1 UG Mine Sites
860-5229	KY DSM		Mousie Hz #4 UG	03/19/1999	03/19/2004	(Jones Fork) Abandoned Hz #4 UG & CT Mine Sites
860-5303	KY DSMRE	Double A Mining Inc.	Mousie Hz 4; Mine #3 - T	02/05/2007	06/19/2009	Transferred from Motts Branch Coal Inc., P/N 860-5207
860-5212	KY DSM		Old Blazing Saddles	08/06/1984	08/06/1994	Abandoned E-3 & Hz #4 UG Mine Sites
867-5198	KY DSM	Cias Coal Co	Old Cias Hz #4 UG	10/11/1989	10/11/2004	Abandoned Hz #4 UG Mine Site
867-0400	KY DSM		Old Fairbanks - #867-036	04/05/2000		Abandoned Hz #4 CT Mine Site
867-5285	KY DSMRE	J&R Coal Inc.	Old J&R Coal #7 E-3	03/26/2004	03/26/2009	Idle UG Mine Site
860-5010	KY DSM	Marine Coal Co	Old J&R Coal Co., Mine #	01/04/1984	01/04/2004	Abandoned E-3 UG Mine Site
860-5202	KY DSM	Deane Mining LLC	Old Jarisa, Inc. E-3, Clas	12/11/1992	12/11/2007	2 Active UG E-3 Mine Sites and 1 Abandoned E-3 UG Mine
860-5255	KY DSMRE	Dennis Mining LLC	Old Leprechaun Coal, Inc.	01/29/2003	01/29/2008	Idle E-3 Mine Site; Permit issued 1/29/2003.
836-5327	KY DSM	North Star Mining Inc	Old Raccoon UG Mine - N	03/01/1995	03/01/2005	Abandoned Hz #4 UG Mine Site
860-5116	KY DSM		Old Right Fork E-3 - Emb	04/02/1991	04/02/2006	Active E-3 UG Mine Site
836-5452	KY DSMRE		Old Salyer's Branch Hz #	04/01/2004	04/01/2009	Abandoned Hz #4 UG Mine Site
860-7007	KY DSMRE	Deane Mining LLC	Puncheon Br. To Big Br.	10/25/2001	10/25/2011	Active Haul Road; Permit approved 10/25/2001; Application
867-5184	KY DSM		Rhoades Br. Hz #4 UG	08/03/1989	08/03/2004	Abandoned Hz #4 UG Mine Site
860-7008	KY DSMRE		Route 80 to Jones Fork Pl	01/05/2004	01/05/2009	Not Disturbed Haul Road

Permittee: CONSOL of Kentucky Inc.

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
860-5218	KY DSM		Salltick #10 - North Star #	09/11/1998	09/11/2003	Active Hz #4 UG Mine Site
860-5221	KY DSM		Shanty Br. - E-3 Slope Po	05/05/1998	05/05/2003	2 Active E-3 UG Mine Sites
860-5260	KY DSMRE		Slone Br. - Nobel CT, Spu	06/19/2003	06/19/2008	2 Active Hz #4 UG Mine Sites & an Idle Hz #4 CT Mine Site
460-5092	KY DSM		Sycamore Fork - Hz #4 P	06/10/1983	06/10/1998	Inactive Hz #4 UG Punch Out Site
867-0404	KY DSM		Wiley - Big John & Shelby	01/13/2000	01/13/2010	Idle No. 7 Block MT & CT Mine Site and Abandoned AM, W
867-0394	KY DSM		Wiley - Indian Cr. CT	08/11/1998	08/11/2003	Abandoned Hz #4 CT Mine Site
867-0447	KY DSMRE		Wiley - Meadow Br. & Coll	12/28/2004	12/28/2009	Active Hz #4 CT Mine Site
867-0391	KY DSM		Wiley - Mill Cr. CT	10/02/1997	10/02/2002	Abandoned Hz #4 CT Mine Site
860-0390	KY DSMRE	Deane Mining LLC	Wiley - Punccheon Branch	08/30/2001	08/30/2011	Active WB & Hz #4 CT Mine Site
860-0349	KY DSM		Wiley - Triplett Branch -	06/13/1996	06/13/2001	Abandoned MT Mine Site
867-0405	KY DSMRE		Wiley - Upper Appletree	08/28/2000	08/28/2005	Abandoned AM, WB, & Hz #4 CT Mine Site
860-5154	KY DSM		Wiley CT - Triplett Branch	05/25/1993	05/25/1998	Abandoned Hz #4 CT Mine Site

WV

S-71-82	WV DEP			04/11/1996	07/16/2002	trans from Fremont Coal Company
U-5007-05	WV DEP		Alma Deep Mine	03/21/2006		Application approved 3/21/2006; submitted 5/26/05.
P-5034-07	WV DEP		Bronzite Prospect			Prospect Release Appl. Submitted 11/21/07
S-5018-07	WV DEP		Buffalo MIn. Surface Mine			King Coal Hwy.
O-24-82	WV DEP		Haulroad	05/21/1982	05/21/2007	trans from Fremont Coal Company
S-94-85	WV DEP		Little Rd Branch Contour	04/11/1996	10/27/2003	Phase 3 release 10/27/2003; trans from Fremont Coal Com
O-25-82	WV DEP		Loadout	05/21/1982	05/21/2007	trans from Fremont Coal Company
S-5038-93	WV DEP	Miller Brothers Coal Inc.	Miller Creek MT-11	04/14/1997		MSHA 1211-WV4-0240-01 (formerly Fremont Coal Co.)
S-5039-93	WV DEP	Miller Brothers Coal Inc.	Miller Creek MT-13	04/14/1997		Trans. from Appalachian Fuels LLC on 6/1/04; MSHA 121
S-5040-93	WV DEP	Miller Brothers Coal Inc.	Miller Creek MT-34	04/14/1997		MSHA 1211-WV4-0240-01 (formerly Fremont Coal Co.)
O-5036-93	WV DEP	Miller Brothers Coal Inc.	Miller Creek Prep Plant &	04/14/1997	04/14/2012	MSHA 1211-WV4-0240-01 (formerly Fremont Coal Co.)
U-5038-86	WV DEP	North Star Contractors	Mine No. CB-7	04/11/1996		trans from Fremont Coal Company
U-5001-08	WV DEP		MT-41 Deep Mine	10/14/2008		

Permittee: CONSOL of Kentucky Inc.

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
S-5009-05	WV DEP		MT-500	07/13/2006	07/13/2011	
S-5018-06	WV DEP		Peg Fork Surface Mine	02/07/2008	02/07/2013	
S-5004-02	WV DEP		WV Surface Mine No. 2	02/08/2005		Application submitted 1/24/2002. Permit issued 2/8/2005.

Permittee: Consol Pennsylvania Coal Company LLC

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
PA						
30810703	PA DEP		Bailey	02/27/1986		Bailey Refuse Permit
30841316	PA DEP		Bailey	01/09/1990		
30841317	PA DEP		Enlow Fork	03/08/1996		trans from Enlow Fork Mining Co 03/08/96
WV						
Y-1007-99	WV DEP		Bailey	03/20/1999		Out of state tracking permit, no bond has been posted.
U-2006-01	WV DEP		Bailey	03/11/2003		Application submitted 4/4/01. Approved 3-11-2003.
Pending	WV DEP		Bailey 5 South #1			WV Prospecting

Permittee: Consolidation Coal Company

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
IL						
258	IL	DMM	Burning Star #2			
70	IL	DMM	Burning Star #2	08/13/1984		
67	IL	DMM	Burning Star #2	10/30/1984		
68	IL	DMM	Burning Star #2	09/10/1986		
71	IL	DMM	Burning Star #3	03/28/1985		
74	IL	DMM	Burning Star #4	08/01/1984		
73	IL	DMM	Burning Star #4	10/30/1984		
152	IL	DMM	Burning Star #4	05/08/1986		
120	IL	DMM	Burning Star #4	08/04/1987	07/19/2005	Phase III final bond released on 7/19/2005.
262	IL	DMM	Burning Star #4	11/13/1992		
112	IL	DMM	Burning Star #5	09/23/1983	11/24/2003	Final bond released 11/24/2003.
77	IL	DMM	Burning Star #5	05/25/1984	11/24/2003	Final bond released 11/24/2003.
75	IL	DMM	Burning Star #5	06/11/1984	09/26/2004	Final bond released 9/26/2004.
199	IL	DMM	Burning Star #5	06/09/1989	05/17/2004	Final bond released 5/17/2004.
281	IL	DMM	Rend Lake			
IL-004	IL	DMM	Rend Lake	08/01/1984		
162	IL	DMM	Rend Lake	11/27/1985		
43	IL	DMM	Rend Lake	01/14/1986		
202	IL	DMM	Rend Lake	12/02/1987		
217	IL	DMM	Rend Lake	08/01/1988		
264	IL	DMM	Rend Lake	06/10/1992		
274	IL	DMM	Rend Lake	01/03/1994		
44	IL	DMM	Wheeler Creek	08/11/1986		
NM						
8	NM	SMC	Burnham	12/16/1977		

Permittee: Consolidation Coal Company

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
OH						
D-0357	OH	DOR				bond release pending
D-2238	OH	DMRM Consolidation Coal Company	Dutton Gas Line	06/02/2005	06/01/2010	
D-0174	OH	DOR	Franklin			
D-0323	OH	DOR	Franklin			bond release pending
D-0102	OH	DOR	Georgetown 24			bond release pending
D-0334	OH	DOR	Georgetown 24			inactive
D-192	OH	DOR	Georgetown P.P.			
D-0054	OH	DOR	Mahoning Valley #33			bond release pending
D-0051	OH	DOR	Mahoning Valley #33			
D-0414	OH	DOR	Mahoning Valley #33			bond release pending
D-0452	OH	DOR	Mahoning Valley #33			bond release pending
D-2100	OH	DMRM	Mahoning Valley #33	04/20/2001		
D-2100-2	OH	DMRM	Mahoning Valley #33	06/10/2005		
D-2100-1	OH	DMRM	Mahoning Valley #33	12/12/2005		
D-0784	OH	DOR Charlotte Coal Co.	Mahoning Valley #36			
D-0826	OH	DOR Charlotte Coal Co.	Mahoning Valley #36			
Application #1	OH	DMRM	Red Wing Mine	09/24/2004	01/01/2005	Application withdrawn in 2005; submitted 9/24/2004.
PA						
02733702	PA	DER				pre-SMCRA permit, mine closed
65881701	PA	DER				pre-SMCRA permit, mine closed
30743702	PA	DEP	Blacksville #1	12/23/1983		
30841319	PA	DEP	Blacksville #1	02/27/1986		
D30-033A	PA	DEP	Blacksville #1	06/30/1987		
30841312	PA	DEP	Blacksville #2	02/27/1986		
30830701	PA	DEP	Dilworth	07/23/1984		

Permittee: Consolidation Coal Company

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
30841313	PA DEP		Dilworth	08/13/1986		
30841302	PA DEP		Humphrey #7	02/27/1986		
6377302 (IW)	PA DER		Montour #4			Pre-SMCRA permit, mine closed
30841601	PA DEP		Robena Prep Plant	09/04/1986		
30733707(R)	PA DEP		Robena Refuse Disposal	11/25/1986		Robena refuse disposal area
63981301	PA DEP		Shoemaker	05/27/1999		
63851702	PA DER		Westland #2			Pre-SMCRA permit, mine closed
63831301	PA DEP		Westland #2	08/13/1986		
TN						
2449	TN OSMRE		Mathews P.P.	02/11/1986		Inc. 2 Ph. I bond release - 6/29/2001; Inc. 1 Ph. I & II releas
UT						
ACT/015/007	UT DOGM					
ACT/015/015	UT DOGM		Emery			
VA						
1301107	VA DMLR			03/29/1983		
1201325	VA DMLR			03/27/1991		
1201754	VA DMLR		Amonate - Hipoe #8	08/09/2000		
1200360	VA DMLR		Amonate Dunford	12/08/1983		Dunford portal
1300410	VA DMLR		Amonate P.P.	12/21/1983		Refuse area
1200727	VA DMLR		Ball Creek (B-1)	07/01/1985		Transferred from Permac Inc./Raven Coal Co.
1201193	VA DMLR		Ball Creek (B-3)	02/24/1989		Transferred from Permac Inc./Raven Coal Co.
1201311	VA DMLR		Ball Creek (B-4)	01/23/1991		Transferred from Permac Inc./Raven Coal Co.
1201412	VA DMLR		Ball Creek (B-5)	04/28/1992		Transferred from Permac Inc./Raven Coal Co.
1201145	VA DMLR		Ball Creek (O-3)	02/22/1996		Transferred from Permac Inc./Raven Coal Co.
1301365	VA DMLR		Bandy #1 Scalp Rock	07/22/1991	12/11/2002	Phase III bond released - 12/11/2002
1301149	VA DMLR		Bishop P.P.	12/28/1983		includes permit 1300464

Permittee:	Consolidation Coal Company					
-------------------	-----------------------------------	--	--	--	--	--

Permit Number	State Regulatory Authority	Operator (if different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
1201502	VA DMLR		Black Eagle	07/20/1994		
1201653	VA DMLR	East Star Mining, Inc.	Black Eagle II (North Bran	08/13/1998		
1201367	VA DMLR	Pigeon Branch Coal	Brave Heart Inc./ Kens Co	07/23/1991		Operator - Pigeon Branch Coal
1400047	VA DMLR		Buchanan	03/08/1993		
1201057	VA DMLR		C-4	10/08/1986		Transferred from Permac Inc./Raven Coal Co.
1201154	VA DMLR		Clifton Creek (E-10)	10/06/1988		Transferred from Permac Inc./Raven Coal Co.
1200839	VA DMLR		Clifton Fork (E-9)	04/18/1986		Transferred from Permac Inc./Raven Coal Co.
1201761	VA DMLR	Harvest-Time Coal, Inc.	Corbadd Inc.	11/02/2000		
1200308	VA DMLR		Dismal Creek (E-2)	11/23/1983		Transferred from Permac Inc./Raven Coal Co.
1301461	VA DMLR		Fiddle Scalp			Pending application #0301991 issued 4/17/93; scalped rock
1201477	VA DMLR		Gum Branch (P-33)	09/03/1993		Trans. from Permac Inc./Raven Coal Co.; Mine is off Rt. 63
1200070	VA DMLR		Hale Branch (P-14)	06/01/1983		Transferred from Permac Inc./Raven Coal Co.
1200369	VA DMLR		Hale Branch (P-28)	12/09/1983		Transferred from Permac Inc./Raven Coal Co.
1200700	VA DMLR		Hale Branch (P-31)	04/17/1985		Transferred from Permac Inc./Raven Coal Co.
1201651	VA DMLR	Consolidation Coal Company	Hioppe #7	07/22/1998	07/22/2008	04/03/2007 - Identified on Controllers AML Fees list
1201772	VA DMLR		Jawbone Mine #2	03/29/2001		Succession of 1201557 from New Life Energy (Rheinbraun)
1201974	VA DMLR		Laurel Fork Mine	06/14/2006	06/14/2011	04/03/2007 - Identified on Controllers AML Fees list
1201511	VA DMLR		Little Hurricane (E-11)	08/02/1989		Transferred from Permac. Mine is off Rt. 628.
1201129	VA DMLR		Miles Branch Mine	11/23/1983		includes permit 1200315
1201625	VA DMLR		Nine Mile Branch (P-32)	08/20/1990		Transferred from Permac Inc./Raven Coal Co.
1300338	VA DMLR		Prep Plant (P-18)	12/02/1983		Transferred from Permac Inc./Raven Coal Co.
1700864	VA DMLR		Prep Plant New Refuse Fi	06/23/1986		Trans. from Permac Inc./Raven Coal; MSHA Impoundment I
1500384	VA DMLR		Prep Plant Old Refuse Fill	12/15/1983		Trans. from Permac Inc./Raven Coal; MSHA Impoundment I
1200636	VA DMLR		Robinson Fork (E-4)	12/13/1984		Transferred from Permac Inc./Raven Coal Co.
1201407	VA DMLR		Slate Creek (O-2)	03/13/1992		Transferred from Permac Inc./Raven Coal Co.
1401825	VA DMLR	A&N Coal Co., Inc	War Creek Mine #1	02/20/2003		Previous permit 1401581 issued 11/12/96 to Knox Creek C

Permittee: Consolidation Coal Company

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
WV						
U-209-83	WV DEP		Amonate	11/14/1983		
S-4004-03	WV DEP	Double M. Mining, L.C.	Amonate Auger #2	11/21/2003		Operator assignment to Bundy Auger Mining, Inc. pending.
S-4005-01	WV DEP	Double M. Mining, L.C.	Amonate Auger No. 1	09/06/2001		Phase I release 10/29/2004. Cease operator assignment pe
U-4002-98	WV DEP		Amonate No. 5 Seam	06/10/1998		
O-150-83	WV DEP	Double M. Mining, L.C.	Amonate plant	11/14/1983		
U-70-83	WV DEP		Arkwright	03/31/1983		
U-12-84	WV DEP	Tazewell McDowell Coal Inc.	Beechfork	01/17/1984		Cease operator assignment pending - 1/21/04
U-35-85	WV DEP		Bentley #2	06/29/1987		trans from Bentley Coal; phase II release - 6/5/1998
U-4016-96	WV DEP	Slyx River Coal Co	Big Creek No. 2	02/27/1997		Phase I release - 10/18/2000
U-214-83	WV DEP	Corbin Coal Inc.	Bishop	11/21/1983		also MSHA 46-01888, 46-02369
U-45-84	WV DEP		Blacksville #1	05/30/1984		mine closed
U-46-84	WV DEP		Blacksville #2	05/03/1984		
O-1011-93	WV DEP		Blacksville #2 - Hughes H	05/17/1995		
I-539	WV DEP		Booth Tipple	11/17/1988		
UO-692	WV DEP		Crane Creek #9	06/11/1983		Phase I release - 12/16/1996
O-136-83	WV DEP		Crane Creek plant	10/26/1983		
U-100-83	WV DEP		Four States	05/18/1983		
U-4021-89	WV DEP		Gordy #3	01/17/1990		Phase I release - 5/4/00. Transferred from Katelyn Coal Co.
U-11-85	WV DEP	Vica Coal Company, Inc.	Greasy Creek #2	12/19/1995		
U-119-83	WV DEP		Humphrey #138	06/10/1983		
O-1022-92	WV DEP		Humphrey refuse	11/22/1993		
U-191-83	WV DEP		Ireland	12/26/1983		
U-15-84	WV DEP		Itmann #1	08/10/1995		name change from Itmann Coal Company 08/10/95
U-16-84	WV DEP		Itmann #2	08/10/1995		name change from Itmann Coal Company 08/10/95
U-17-84	WV DEP		Itmann #3	08/10/1995		name change from Itmann Coal Company 08/10/95

Permittee: Consolidation Coal Company

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
O-11-85	WV DEP		Itmann plant	08/10/1995		name change from Itmann Coal Company 08/10/95
U-78-83	WV DEP		Loveridge	09/18/1983		
O-1044-91	WV DEP		Loveridge	06/17/1992		
UO-431	WV DEP		Nailler	06/28/1979		
U-4018-88	WV DEP	Omega Square	Omega Square	02/07/1989		Phase I release - 1/31/2001
U-4015-86	WV DEP		Omega Square haulroad	10/10/1986		Phase I release - 1/30/2001
U-53-83	WV DEP		Osage	03/02/1983		
U-86-83	WV DEP		Pursglove	05/04/1983		
U-104-83	WV DEP		Robinson Run #95	06/10/1983		incl. old D-67-82, O-108-83
U-1025-92	WV DEP		Robinson Run #95	03/03/1993		
U-1045-91	WV DEP		Shoemaker	12/23/1991		
U-1025-91	WV DEP		Shoemaker	12/31/1991		
O-1001-00	WV DEP		Shoemaker	01/11/2000		Cunningham Hollow Refuse application approved 4/19/200
U-2003-06	WV DEP		Shoemaker - Boggs Run	09/06/2006	09/06/2011	Application submitted 02/14/2006.
SMA# S-2007	WV DEP		Shoemaker Boggs Run St	03/22/2006		Application submitted 03/22/2006.
U-4003-04	WV DEP		Squire Jim #2	10/17/2005		Application approved 10/17/2005.
U-4004-04	WV DEP		Squire Jim #3	10/17/2005		Application approved 10/17/2005.
U-4004-91	WV DEP	Hoipe Mining Inc	Squire Jim No. 1 Mine	12/11/1991		Operator assignment to Joshua Fuel, Inc. pending - 1/21/04
U-11-84	WV DEP		Turkey Gap	01/17/1984		
UO-584	WV DEP		Turkey Gap shaft	01/17/1984	03/02/2005	Phase III final bond released 3/2/2005. Phase I bond rel. 11/

Permittee: Eighty Four Mining Company

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
PA						
63831302	PA DEP		Eighty Four Mine	03/30/1987		
63743702	PA DEP		Eighty Four Refuse	12/27/1985		

Permittee: Fola Coal Company, L.L.C.

Permit Number	State Regulatory Authority	Operator <i>(if different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
WV						
O-2001-93	WV DEP					
SMA-2004-99	WV DEP					
O-3022-92	WV DEP		Big Branch Coal Refuse D	12/15/1994	12/15/2009	
S-2007-98	WV DEP		Bulpen Fork Surface Min	02/16/1999	02/16/2009	
S-2006-05	WV DEP		Cannel Coal Point Remov	11/03/2006	11/03/2011	
U-2007-97	WV DEP		Fola Eagle Deep Mine #1	01/14/1999	01/14/2009	
O-2008-93	WV DEP		Haulroad #2	03/01/1994	03/01/2009	
S-2012-98	WV DEP		Ike Fork #1 Surface Mine	07/30/2001	07/30/2011	
S-2005-99	WV DEP		Ike Fork #2 Surface Mine	02/28/2002	02/28/2007	
S-6019-89	WV DEP		Monoc #2 Surface Mine	12/11/1989	12/11/2004	
S-6014-89	WV DEP		Monoc #3 Surface Mine	09/11/1989	09/11/2004	
U-2012-99	WV DEP		Monoc #4 - Big Dragon D	08/05/2002	08/05/2007	
S-2003-96	WV DEP		Monoc #4 Surface Mine	10/11/1996	10/11/2011	
O-2001-94	WV DEP		Peachorchard Loadout &	07/18/1994	07/18/2009	
O-2011-93	WV DEP		Peachorchard Preparation	03/31/1994	03/31/2009	
S-2013-98	WV DEP		Peachorchard Surface Mi	05/24/2004	05/24/2009	
O-3008-93	WV DEP		Primary Haulroad #1	09/28/1993	09/28/2008	
O-2008-97	WV DEP		Primary Haulroad #3	01/14/1999	01/14/2009	
S-3013-93	WV DEP		Surface Mine #1	11/17/1993	11/17/2003	
S-2012-93	WV DEP		Surface Mine #2	07/20/1994	07/20/2009	
S-2014-96	WV DEP		Surface Mine #2A	04/23/1997	04/23/2007	
S-2009-95	WV DEP		Surface Mine #3	05/13/1996	05/13/2011	
S-2005-02	WV DEP		Surface Mine #4A	06/03/2003	06/03/2008	
S-2011-99	WV DEP		Surface Mine #6	06/02/2000	06/02/2005	
U-2006-94	WV DEP		Winoc #1 Deep Mine	02/26/1996	02/26/2001	

Permittee: Fola Coal Company, L.L.C.

Permit Number	State Regulatory Authority	Operator (if different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
S-2004-94	WV DEP		Winoc #1 Surface Mine	02/14/1995	02/14/2005	
S-2006-97	WV DEP		Winoc #2 Surface Mine	08/20/1997	08/20/2007	
O-3033-91	WV DEP		Winoc Preparation Plant	11/12/1992	11/12/2007	
O-3009-92	WV DEP		Winoc Raw Coal Facility	08/09/1994	08/09/2009	

Permittee: Glamorgan Coal Company, L.L.C. d/b/a Indian Gap Co

Permit Number	State Regulatory Authority	Operator <i>(if different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
1201231	VA DMRL		Mine #1	08/09/1989	08/09/1999	

Permittee: Glamorgan Coal Company, L.L.C. d/b/a Lower Clintwo

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
1101247	VA DMRL		Mine #7	01/26/1990	01/26/2010	

Permittee: Glamorgan Coal Company, L.L.C. d/b/a Porter Coal Co

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
VA						
1200233	VA DMRL	Dorchester Coal Company, Inc.	Sunny Side #1 & #2	11/04/1983	11/04/2003	
1200233	VA DMRL	Navajo Coal Company	Sunny Side #1 & #2	11/04/1983	11/04/2003	
1200233	VA DMRL	Navajo Coal Company	Sunny Side #1 & #2	11/04/1983	11/04/2003	

Permittee: Glamorgan Coal Company, L.L.C. d/b/a Rocky Coal Co

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
1401321	VA	DMRL		Rocky Refuse Disposal Ar	03/01/1991	03/01/2006
1401321	VA	DMRL		Rocky Refuse Disposal Ar	03/01/1991	03/01/2006

Permittee: Glamorgan Coal Company, L.L.C. d/b/a Taggart Coal C

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
1201628	VA	DMRL	Marker Mine #1	01/26/1998	01/26/2003	

Permittee: Glamorgan Coal Company, L.L.C. d/b/a Wise Dock Co

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
1400324	VA	DMRL		11/30/1998	11/30/2003	

Permittee: Helvetia Coal Company

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
PA						
32743710	PA DEP		Helvetia #1	04/12/1985		Refuse disposal area
32743711	PA DEP		Helvetia #2	10/03/1985		Refuse disposal area
32851302	PA DEP		Lucerne #6 Extension	02/02/1987		Mining inactive, water treatment continues.
32841303	PA DEP		Lucerne #6 Mine	09/15/1986		Mining inactive, water treatment continues.
32841320	PA DEP		Lucerne #8 Mine	04/15/1986		Mining inactive, water treatment continues.
32841317	PA DEP		Lucerne #9 Mine	08/08/1985		Mining inactive, water treatment continues. (2nd MSHA #: 3
32921302	PA DEP		Marshall Run Deep	08/13/1993		Mining inactive

Permittee: Island Creek Coal Company

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
KY						
713-5002	KY	DSMRE	Hamilton #1			
713-5001	KY	DSMRE	Hamilton #2			
713-5000	KY	DSMRE	Ohio 11			
VA						
1400493	VA	DMLR	Beatrice Mine			Transferred from Beatrice Pocahontas on 2/29/2000
1400496	VA	DMLR	Mine #3			
1300341	VA	DMLR	Saw Mill Storage Area			
1400492	VA	DMLR	VP 1			
1401232	VA	DMLR	VP 2			
1400498	VA	DMLR	VP 4			
1401489	VA	DMLR	VP 8 (Deskins)			Permit 1400497 transferred from VP5 Mining Co. & reissue
1401531	VA	DMLR	VP 8 (Garden)			Also MSHA # 44-04517
WV						
O-2012-96	WV	DEP			08/15/2005	Transferred to Meltiki Coal (WV) LLC on 8/15/2005.
U-5076-86	WV	DEP	Abb's #3	10/29/1993		Inactive, trans. from Abb's Resources Inc. 10/29/93; phase I
I-700	WV	DEP	Beaver Creek/Alpine AMD			
P-590	WV	DEP	Elk Creek #10 plant	01/04/1993		
H-456	WV	DEP	Elk Creek haulroad	01/04/1993		
I-678	WV	DEP	North AMD			
EM-69	WV	DEP	North Branch Airshaft	02/24/1988		
O-129-83	WV	DEP	North Branch Fuel Supply	10/26/1988		
EM-100	WV	DEP	North Portal, 11A airshaft			
P-672	WV	DEP	North Prep Plant			
U-5050-91	WV	DEP	Old 10K Mine	03/01/1994		
U-5029-92	WV	DEP	Pine Creek Mining IV, Inc Pine Creek IV, Mine #1	09/24/1993		Phase I bond release - 12/1/1998

Permittee: Island Creek Coal Company

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
U-5051-87	WV DEP	Pine Creek Mining IV Inc.	Pine Creek IV, Mine #2	12/13/1994		Transferred from Thunder Mountain Energy, phase I releas
U-5056-87	WV DEP	Pine Creek IV	Pine Creek IV, Mine #3	10/29/1993		
U-5061-86	WV DEP		S&M #7	01/01/1996		Phase I bond release 3/16/99. Transferred from S & M Coal
U-5026-97	WV DEP		School House Alma	12/15/1997		Not Started
U-5042-91	WV DEP	Stonecoal Branch Mining Inc	Stonecoal Branch, Mine #	07/07/1993		
U-5025-96	WV DEP	Stonecoal Branch Min. Inc	Stonecoal Branch, Mine #	02/10/1997		
U-5014-97	WV DEP		Turkeypen #2 Gas	11/19/1997		Not Started
UO-30	WV DEP		West Portal subsidence			
P-674	WV DEP		West Prep Plant	02/24/1988		
O-130-83	WV DEP		West Refuse Area #1	10/26/1988		
U-5074-87	WV DEP	Brandy Mining Inc Mine #2	Wynchester #21-C	10/29/1993		Inactive, from Wynchester Mining; also MSHA 46-07776(11

Permittee: Jeffco Coal Company

Permit Number	State Regulatory Authority	Operator <i>(if different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
33723006	PA DEP		Wilson #7 Mine	07/01/1985		transferred from Maud Mining Co. 1/17/2002.

Permittee: Kent Coal Mining Company

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
PA						
03850105R	PA DEP		Brickchurch #3 Mine	06/19/1984		
2869BSM13	PA DEP		Iselin #6	02/13/1975		Completed/ Stage II/ Water Quality
32803037	PA DEP		Kent #53	06/27/1984		Completed/ Stage II
03890113	PA DEP		Margaret #50	01/25/1991		Completed/ Stage II

Permittee: Keystone Coal Mining Corp.

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
PA						
32941301	PA DEP		Crooked Creek	01/09/1995		
32931301	PA DEP		Dutch Run	04/09/1996		
03841307	PA DEP		Emilie #4 Mine	07/28/1986		Mining inactive, water treatment continues.
03773706	PA DEP		Emilie #4 Refuse	05/28/1985		Refuse disposal area
03841305	PA DEP		Emilie Mine	08/11/1986		
03793072C	PA DEP		Iselin #10	02/15/1985		Transferred from Kent on 9/3/2002. Completed, water treat
3279103	PA DEP		Iselin #11			Transferred from Kent 8/8/2002. Completed/ Stage II/ Wate
03831305	PA DEP		Jane Mine	01/03/1986		Mining inactive, water treatment continues.
32860106	PA DEP		Kent #55	07/13/1987		Transferred from Kent 8/8/2002. Completed/ Water Quality
32803010	PA DEP		Kent #56	08/06/1984		Transferred from Kent 8/16/2002. Completed, water treatme
32890109	PA DEP		Kent #57	10/15/1990		Transferred from Kent 8/16/2002. Completed, water treatme
03813704	PA DEP		Keystone #1	06/28/1985		Refuse disposal area
03970701	PA DEP		Keystone #2			Refuse disposal area
03940701	PA DEP		Keystone #2 CRD	01/04/1996		
03951601	PA DEP		Keystone Cleaning Plant	02/29/1996		
32803712	PA DEP		Lewisville Recovery Plant	01/16/1986		Transferred from Kent 8/26/2002. Completed, water treatme
32940105	PA DEP		Lucerne #2	05/09/1995		Transferred from Kent 8/16/2002. Completed/ Water Qualit
0380302	PA DEP		Margaret #7	02/25/1987		Mining inactive, water treatment continues.
03841304	PA DEP		Margaret 11	08/27/1985		
03851304	PA DEP		Margaret 11	04/07/1993		
03891301	PA DEP		Margaret 11 - No 2 Portal	02/21/1991		Mining inactive
500121	PA DEP		Margaret Refuse			Refuse disposal area
3576SM24	PA DEP		Margaret Refuse Recover			Mining inactive, water treatment continues.
32920102	PA DEP		Marshall Run Mine #1	04/14/1993		Transferred from Kent 8/16/2002. Completed/ Stage II
32970103	PA DEP		Marshall Run Mine #2	08/15/1997		Transferred from Kent 8/8/2002. Completed/ Stage II

Permittee: Keystone Coal Mining Corp.

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
3274301	PA DEP		O'Donnell #4 - Manor 8	09/05/1974		Mining inactive, water treatment continues.
32841321	PA DEP		O'Donnell Mine #3	11/15/1995		Mining inactive
32921301	PA DEP		Plumcreek #1 Mine	11/07/1993		Mining inactive. Phase II & partial phase III release on 4/10/
32841313	PA DEP		Urling #2 Mine	02/20/1986	02/19/2004	Transferred 2/19/04 to Rosebud Mining. Mining inactive, wa
32841323	PA DEP		Urling #3-E	02/20/1986		Permitted reserve
32841312	PA DEP		Urling Nos. 1 & 3 Mines	06/10/1986	02/19/2004	Transferred 2/19/04 to Rosebud Mining. Mining inactive, wa
03753705	PA DEP		Urling Nos. 1 & 3 Refuse	09/26/1985	02/19/2004	Transferred 2/19/04 to Rosebud Mining. Refuse disposal ar
32813031	PA DEP		Waterman #1	06/19/1984		Transferred from Kent 8/8/2002. Completed, water treatmen

Permittee: Laurel Run Mining Company

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
PA						
63841304	PA DEP		Vesta	12/22/1998		transfer from Massey; reclamation only
WV						
O-1039-90	WV DEP		Alpine Refuse #2			
S-4020-96	WV DEP		Coal Mountain No. 1	05/07/1997	08/30/2004	Transferred to Dynamic Energy Inc. on 8/30/2004.
S-4021-96	WV DEP		Coal Mountain Valley Fill	05/07/1997	08/30/2004	Transferred to Dynamic Energy Inc. on 8/30/2004.
H-477	WV DEP		Coal Mtn #9 road	03/02/1990	11/16/2004	Final bond released on 11/16/2004.
P-586	WV DEP	Childress Service Corp	Coal Mtn. plant	03/02/1990	08/30/2004	Transferred to Dynamic Energy Inc. on 8/30/2004.
UO-432	WV DEP		Double E	04/17/1995	08/30/2004	Reclaimed; trans from Double E Mining 4/17/95; transferred
EM-74	WV DEP		Marcus #4	04/17/1995	08/30/2004	Trans from Marcus Coal 4/17/95; transferred to Dynamic E
U-139-83	WV DEP		Potomac			also MSHA 46-04190 (12/20/78), 1211WV30102 (12/75)
O-31-82	WV DEP		ROM loadout - Twin Bran	01/19/1994		Transfer from Twin Branch Coal Co
U-5013-93	WV DEP		Spring Branch	02/04/1997		

Permittee: Little Eagle Coal Company, L.L.C.

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
UO-288	WV DEP		Lick Branch #2 Mine	05/29/1978	11/10/2008	
U-2014-95	WV DEP		Peachorchard #1 Deep Mi	07/08/1996	07/08/2011	
U-2004-05	WV DEP		Rocklick Coalburg Deep	04/12/2006	04/12/2011	

Permittee: McElroy Coal Company

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
<hr/>						
U-1026-92	WV DEP		Blakes Ridge - McElroy	05/04/1993		
U-33-83	WV DEP		McElroy	02/10/1983		
O-1023-92	WV DEP		McElroy refuse area	02/10/1996		

Permittee: McGlothlin Coal Co

Permit Number	State Regulatory Authority	Operator <i>(if different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
1200588	VA DMLR		Mine #13		12/18/2002	

Permittee: Powellton Coal Company, L.L.C.

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
WV						
U-72-84	WV DEP			09/04/1984		
S-3004-00	WV DEP		Bridge Fork Surface Mine	06/19/2001	06/19/2006	
S-3003-01	WV DEP		Bridge Fork West Surface	01/21/2004	01/21/2009	
S-3002-07	WV DEP		Gauley Knob Surface Min	07/30/2007	07/30/2012	
O-3007-00	WV DEP		Rich Creek Haulroad	06/19/2001	06/19/2011	
O-3005-00	WV DEP		Sugarcamp Loadout	07/18/2001	07/18/2011	

Permittee: Quarto Mining Company

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
OH						
D-433	OH	DMRM	Powhatan #4	11/29/1984		
D-422	OH	DMRM	Powhatan #7	10/19/1984		

Permittee: Southern Ohio Coal Company

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
<hr/>						
OH						
D-354	OH	DMRM	Meigs #1	06/12/1984		
D-355	OH	DMRM	Meigs #2	06/12/1984		
D-463	OH	DMRM	Raccoon #3	04/09/1985		

Permittee: Terry Eagle Coal Company, L.L.C.

Permit Number	State Regulatory Authority	Operator (If different from permittee)	Mine Name	Permit Issue Date	End Date	Comments
---------------	----------------------------	--	-----------	-------------------	----------	----------

WV

S-3033-92 WV DEP

S-3022-88 WV DEP

U-3002-90 WV DEP

U-160-83 WV DEP

U-3032-92 WV DEP

P-68-82 WV DEP

H-561 WV DEP Bald Eagle Haulroad 01/07/1993 01/07/2003

U-6016-88 WV DEP Bell Creek Deep Mine #1 10/19/1988 10/19/2008

D-106-82 WV DEP Cari Eagle Mine #2 09/07/1982 09/07/1997

D-106-82 WV DEP Cari Eagle Mine #2 09/07/1982 09/07/1997

U-3057-89 WV DEP Cari Eagle Mine #3 03/29/1991 03/29/2001

U-6001-90 WV DEP Harrison Mine #1 05/01/1990 05/01/2005

S-3029-87 WV DEP Meadow Creek Strip #1 07/17/1987 07/17/1997

S-3069-87 WV DEP Meadow Creek Strip #2 04/13/1988 04/13/1998

U-3-84 WV DEP Otter Creek Mine #1 01/12/1984 01/12/2004

O-3037-86 WV DEP Peters Creek Refuse Area 08/01/1986 08/01/2011

S-6010-89 WV DEP Ramp Run Mine #1 10/03/1989 10/03/1999

S-6010-89 WV DEP Ramp Run Mine #1 10/03/1989 10/03/1999

S-3017-94 WV DEP Ramp Run Mine #2 12/29/1994 12/29/1999

S-3017-94 WV DEP Ramp Run Mine #2 12/29/1994 12/29/1999

UO-652 WV DEP Robert Eagle #2 11/06/1980 02/24/2003

P-569 WV DEP Terry Eagle Preparation P 11/19/1980 05/31/2008

D-41-81 WV DEP Warren Eagle Mine #3 11/16/1981 08/02/2008

Permittee: Windsor Coal Company

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
WV						
O-485	WV DEP				01/17/1985	
E-128-00	WV DEP				01/26/1988	
P-744	WV DEP				01/26/1988	

Permittee: Wolfpen Knob Development Company

Permit Number	State Regulatory Authority	Operator <i>(If different from permittee)</i>	Mine Name	Permit Issue Date	End Date	Comments
WV						
O-1052-91	WV DEP				01/28/1998	
U-2015-92	WV DEP				01/28/1998	

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 1 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 060-E475 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-1891 DATE VIOL. ISSUED: 10/14/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code OT: Permittee began exploration core drilling before the exploration was permitted.

 CURRENT STATUS: TERMINATED STATUS DATE: 10/21/2008
 REQUIRED ACTIONS: Cease all core drilling until the time that the exploration permit has been issued.

 ABATEMENT ACTIONS: Violation Terminated - 10/21/2008.

PERMIT NO: 460-5092 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2306 DATE VIOL. ISSUED: 5/11/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code SC: Failed to maintain sediment control structure #1 according to approved plan. This is in reference to sediment clean-out levels & obstructions found in principal spillway.

 CURRENT STATUS: PENDING STATUS DATE:
 REQUIRED ACTIONS: Implement approved sediment clean-out plan, remove obstructions from within principal spillway, reestablish rip-rap for emergency spillway and remove all tree growths from upstream & downstream embankments.

 ABATEMENT ACTIONS: Extended to 10-07-2009

PERMIT NO: 836-5238 MSHA NO: 15-18296 MSHA DATE: 10/31/00
 VIOLATION NO: 43-2278 DATE VIOL. ISSUED: 1/16/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code AP: Company and operator has allowed fugitive dust and/or coal dust to occur in an uncontrolled manner from the coal belt line and the coal stock pile area.

 CURRENT STATUS: TERMINATED STATUS DATE: 2/2/2009
 REQUIRED ACTIONS: Company must supply an adequate amount of water, consistently maintain the water sprinkler system, and follow the permitted and approved dust control plans at all times.

 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: 836-5238 MSHA NO: 15-18296 MSHA DATE: 10/31/00
 VIOLATION NO: 43-2277 DATE VIOL. ISSUED: 12/23/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code AP: Allowed fugitive dust in an uncontrolled manner.
 2) Code SC: Failed to maintain the principle spillway according to plan
 3) Code DS: Failed to properly maintain diversion ditches.

 CURRENT STATUS: TERMINATED STATUS DATE: 4/8/2009
 REQUIRED ACTIONS: 1) Control all fugitive dust.
 2) Remove debris from principle spillway.
 3) Regrade diversion ditches

 ABATEMENT ACTIONS: Required work complete: Violation 1 Terminated
 Required work completed; Violation 2 Terminated
 Required work completed; Violation 2 Terminated

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 2 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 836-5238 MSHA NO: 15-18296 MSHA DATE: 10/31/00
 VIOLATION NO: 43-0827 DATE VIOL. ISSUED: 12/1/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code AP: Company and or operator has allowed fugitive dust to occur in an uncontrolled manner from the coal belt line and coal stock pile area.
 CURRENT STATUS: TERMINATED STATUS DATE: 12/15/2008
 REQUIRED ACTIONS: Add additional sprinklers to the coal belt line, coal stock pile area, and add additional gravel within the coal stock pile area.
 ABATEMENT ACTIONS: Required action completed: Violation terminated 12/15/2008

PERMIT NO: 836-5238 MSHA NO: 15-18296 MSHA DATE: 10/31/00
 VIOLATION NO: 43-0826 DATE VIOL. ISSUED: 9/25/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code UO: Failed to comply with all terms & conditions of permit.
 2) Code BG: Failed to properly handle or dispose of toxic chemicals.
 3) Code AP: Allowed fugitive dust to occur in an uncontrolled manner.
 CURRENT STATUS: TERMINATED STATUS DATE: 1/5/2009
 REQUIRED ACTIONS: 1) Remove operator and/or comply with permit and/or subit operator change. 2) Remove and properly dispose of chemicals. 3) Follow the approved and permitted plans to prevent air born dust.
 ABATEMENT ACTIONS: Violation 1&2: Terminated
 Violation 3: Terminated 10/22/2008

PERMIT NO: 836-5238 MSHA NO: 15-18296 MSHA DATE: 10/31/00
 VIOLATION NO: 43-2273 DATE VIOL. ISSUED: 6/23/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code AP: Company and/or Operator has allowed fugitive dust to occur in an uncontrolled manner from the coal belt line and the coal stock pile area.
 CURRENT STATUS: TERMINATED STATUS DATE: 7/8/2008
 REQUIRED ACTIONS: Company needs maintain the water sprinklers at all times to control dust.
 Non-correctable because the dust has already occurred
 ABATEMENT ACTIONS: Required work completed; violation terminated 07/08/2008.

PERMIT NO: 836-5452 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2272 DATE VIOL. ISSUED: 6/10/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) Code SM: Company failed to post and/or maintain the perimeter markers within the permitted area. (2) Code BG: A slip or unstable area has occurred on the down slope area below the coal stock pile.
 CURRENT STATUS: TERMINATED STATUS DATE: 8/20/2008
 REQUIRED ACTIONS: (1) Post perimeter markers along the entire permitted area.
 (2) Complete all necessary backfilling & grading to eliminate & stabilize the unstable area below the coal stock pile & seed and mulch area.
 ABATEMENT ACTIONS: Required work completed; Violation terminated 8/20/2008

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 3 of 57

Entity to whom violation(s) were issued: **CONSOL of Kentucky Inc.**

PERMIT NO: 836-6015 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-1871 DATE VIOL. ISSUED: 11/26/2007 ISSUED BY: KY DMER
 VIOLATION DESCRIPTION: Permittee delinquent in submitting mid-term modifications.

CURRENT STATUS: TERMINATED STATUS DATE: 12/3/2007
 REQUIRED ACTIONS: Submit mid-term modifications within 30 days.

ABATEMENT ACTIONS: Required work completed, violation terminated 12/03/2007.

PERMIT NO: 860-0333 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2298 (3-4) DATE VIOL. ISSUED: 5/9/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 3) Code EL: Allowed substandard discharge to leave permit area.
 4) Code HR: Approximately one acre of drainage corridor located within County Line Hollow has been impacted by excess sediment.
 CURRENT STATUS: TERMINATED STATUS DATE: 5/20/2009
 REQUIRED ACTIONS: 3) Immediately cease all substandard discharge from permit area.
 4) Restore referenced drainage corridor to pre-existing condition.

ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: 860-0333 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2298 (1-2) DATE VIOL. ISSUED: 5/9/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code BG: A slide had developed along the downslope of increment 6 located within County Line Hollow.
 2) Code WQ: Allowed substandard discharge to leave permitted area.
 CURRENT STATUS: PENDING STATUS DATE:
 REQUIRED ACTIONS: 1) Stabilize, seed and mulch all disturbed areas. Establish temp. sediment control for all disturbed areas.
 2) Immediately cease all substandard discharge from permitted area.
 ABATEMENT ACTIONS: Violation 1 extended to 08/28/2009
 Violations 2-5 Terminated 5-20-09

PERMIT NO: 860-0333 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2298 (5) DATE VIOL. ISSUED: 5/9/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 5) Code OD: Off permit material has been deposited around a citizen's residence located near the head waters of County Line Hollow.
 CURRENT STATUS: TERMINATED STATUS DATE: 5/20/2009
 REQUIRED ACTIONS: 5) Retrieve all off permit materials and return to permitted area.
 Seed and mulch all disturbed areas.

ABATEMENT ACTIONS: Required work completed; Violation terminated

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 4 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 860-0333 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-1846 DATE VIOL. ISSUED: 4/26/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: A section of backfilled contour is unstable and moving downslope.

CURRENT STATUS: TERMINATED STATUS DATE: 8/7/2007
 REQUIRED ACTIONS: Stabilize, regrade and revegetate unstable area.

ABATEMENT ACTIONS: Required work completed; violation terminated 8/07/2007.

PERMIT NO: 860-0390 MSHA NO: N/A MSHA DATE: 00/00/00
 VIOLATION NO: 53-2552 DATE VIOL. ISSUED: 4/30/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Non-coal waste was disposed of improperly.

CURRENT STATUS: TERMINATED STATUS DATE: 7/28/2008
 REQUIRED ACTIONS: All waste must be removed and properly disposed of. Disturbed areas must be seeded and mulched.

ABATEMENT ACTIONS: Required work completed; Violation terminated 07/28/2008

PERMIT NO: 860-0390 MSHA NO: N/A MSHA DATE: 00/00/00
 VIOLATION NO: 53-0634 DATE VIOL. ISSUED: 2/26/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) Slide occurred below permitted contour mining area.

(2) Failed to maintain sediment structure Dugout 11 to approved designs.
 CURRENT STATUS: TERMINATED STATUS DATE:
 REQUIRED ACTIONS: (1) Stabilize, seed, & mulch disturbed area; submit revision.
 (2) Repair leaks in sediment structure; apply seed and mulch to disturbed areas.

ABATEMENT ACTIONS: (1) Required work completed; violation terminated 2/13/2008.
 (2) Required work completed; violation terminated 5/29/2007.

PERMIT NO: 860-5148 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2308 (1-2) DATE VIOL. ISSUED: 5/11/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code HR: A blow out has occurred within Sycamore Fork & deposited excessive amounts of sediment. 2) Code OD: A high velocity flow eroded portions of downslope below blow out area.

CURRENT STATUS: PENDING STATUS DATE:
 REQUIRED ACTIONS: 1) Construct & maintain an adequate wet seal. Remove all deposited material and return to pre-existing conditions. 2) Restore all referenced areas to pre-existing conditions. Reclaim eroded area.

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 5 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 860-5148 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2308 (3-4) DATE VIOL. ISSUED: 5/11/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 3) Code WQ: Discharge from blow-out area has exceeded max daily allowances for Iron. 4) Code EL: Discharge from blow-out area has exceeded max daily allowances for Iron.
 CURRENT STATUS: PENDING STATUS DATE:
 REQUIRED ACTIONS: 3) Treat blow-out discharge to ensure compliance.
 4) Treat blow-out discharge to ensure compliance.
 ABATEMENT ACTIONS:

PERMIT NO: 860-5154 MSHA NO: N/A MSHA DATE:
 VIOLATION NO: 43-1444 DATE VIOL. ISSUED: 7/27/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Three to six feet of the discharge end of the principal spillway on sediment structure P-4A has eroded through to the embankment.
 CURRENT STATUS: PENDING STATUS DATE:
 REQUIRED ACTIONS: Repair and/or replace the principal spillway. Ascertain all woody vegetation is removed from the embankment and the principal and emergency spillway areas.
 ABATEMENT ACTIONS:

PERMIT NO: 860-5154 MSHA NO: unknown MSHA DATE: unknown
 VIOLATION NO: 43-1821 DATE VIOL. ISSUED: 1/29/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) Code BG. Backfill material unstable, exposed highwall. (2) Code AC. Failed to maintain Road G. (3) Code SC Failed to maintain sediment structure P-11. (4) Code DS. Failed to maintain Hollow Fills 1, 2 & 3.
 CURRENT STATUS: TERMINATED STATUS DATE: 1/26/2009
 REQUIRED ACTIONS: (1) Stabilize backfill material & eliminate exposed high-wall. (2) Maintain Road G. (3) Maintain sediment structure P-11. (4) Stabilize eroded side drains in Hollow Fills #1, #2 & #3.
 ABATEMENT ACTIONS: Violations 1 terminated: 10/07/2008
 Violation 3 terminated 07/03/2008
 Violation 2 & 4: terminated 01/26/2009

PERMIT NO: 860-5202 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-0803 DATE VIOL. ISSUED: 10/28/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code EL: 2) Code WQ: Water is discharging from an underground mine area & leaving the permitted area. The water is not within allowable limits for Iron and pH.
 CURRENT STATUS: TERMINATED STATUS DATE:
 REQUIRED ACTIONS: 1) & 2): The discharge area should be added as a KPDMRS monitoring point. Appropriate actions should be taken to ensure the discharge is brought back within allowable limits.
 ABATEMENT ACTIONS: Permit transferred to Deane Mining Co. 10-30-2008

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 6 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 860-5202 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-2043 DATE VIOL. ISSUED: 12/20/2007 ISSUED BY: KY DMER
 VIOLATION DESCRIPTION: Code SB. Subsidence cracks have occurred above mined area

CURRENT STATUS: TERMINATED STATUS DATE: 11/11/2008
 REQUIRED ACTIONS: Areas affected should be sealed, graded, seeded & mulched.

ABATEMENT ACTIONS: Required work completed, violation terminated 11/11/2008

PERMIT NO: 860-5202 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2036 DATE VIOL. ISSUED: 6/19/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 2005 annual underground mine maps have been repeatedly submitted with incorrect information

CURRENT STATUS: TERMINATED STATUS DATE: 7/25/2007
 REQUIRED ACTIONS: Submit correct map

ABATEMENT ACTIONS: Required work completed; violation terminated 7/25/2007.

PERMIT NO: 860-5202 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-0695 DATE VIOL. ISSUED: 4/20/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) High pH & Iron water left permitted area.
 (2) High pH & Iron water left permitted area.
 (3) High pH & Iron water left permitted area.

CURRENT STATUS: TERMINATED STATUS DATE: 4/20/2007
 REQUIRED ACTIONS: (1) Ensure water being discharged is within allowable levels.
 (2) Ensure water being discharged is within allowable levels.
 (3) Ensure water being discharged is within allowable levels.

ABATEMENT ACTIONS: Required work completed; violation terminated 4/20/2007.

PERMIT NO: 860-5202 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-1668 DATE VIOL. ISSUED: 4/20/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) Code EL. High pH & Iron water left permitted area.
 (2) Code WQ. High pH & Iron water left permitted area.
 (3) Code HR. High pH & Iron water left permitted area.

CURRENT STATUS: TERMINATED STATUS DATE: 7/16/2008
 REQUIRED ACTIONS: (1) Ensure water being discharged is within allowable levels.
 (2) Ensure water being discharged is within allowable levels.
 (3) Ensure water being discharged is within allowable levels.

ABATEMENT ACTIONS: Required work completed; Violation terminated 07/16/2008

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 7 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 860-5202 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-1665 DATE VIOL. ISSUED: 3/16/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) Permittee has allowed water above allowable levels for both pH and Iron to leave permitted area.
 (2) Water above pH and Iron levels left permitted area.
 CURRENT STATUS: TERMINATED STATUS DATE: 4/2/2007
 REQUIRED ACTIONS: (1) Bring water back to allowable levels.
 (2) Bring water back to allowable levels.
 ABATEMENT ACTIONS: Required work completed; violation terminated 4/02/2007

PERMIT NO: 860-5218 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2290 (3) DATE VIOL. ISSUED: 5/27/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 3) Code SC: Failed to properly maintain embankment of silt pond #1 according to approved plans. Allowed water to over flow down embankment and caused erosion.
 CURRENT STATUS: TERMINATED STATUS DATE: 8/10/2009
 REQUIRED ACTIONS: 3) Regrade area of embankment affected by erosion. Seed & mulch affected area.
 ABATEMENT ACTIONS:

PERMIT NO: 860-5218 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2290 (1-2) DATE VIOL. ISSUED: 5/27/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code AC: Failed to maintain Access Road #1 accord to plan. Allowed severe erosion and surface water runoff.
 2) Code OD: Allowed dirt & debris to leave permitted area.
 CURRENT STATUS: TERMINATED STATUS DATE: 8/10/2009
 REQUIRED ACTIONS: 1) Repair and unstop culverts and ditch lines. Seed & mulch affected areas.
 2) Clean up dirt & debris. Seed & mulch affected area.
 ABATEMENT ACTIONS: Required work completed; Violation Terminated

PERMIT NO: 860-5221 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-2238 DATE VIOL. ISSUED: 6/11/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code EL 2) Code WQ: Exceeded effluent limitations by allowing substandard water to discharge from sediment structure #2 into Turtle Branch Creek.
 CURRENT STATUS: TERMINATED STATUS DATE: 6/12/2009
 REQUIRED ACTIONS: 1&2) Immediately initiate all reasonable measures to stop the discharge of the substandard water into Turtle Branch Creek and bring all additional discharges into compliance with KPDES standards.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 8 of 57

Entity to whom violation(s) were issued: **CONSOL of Kentucky Inc.**

PERMIT NO: 860-5221 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2129 DATE VIOL. ISSUED: 3/4/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code DS) Failure to submit critical stage certification and quarterly certification for temporary Side Hill Fill #4 for all quarters of '05, '06, '07 and '08. Failure to submit final certification for Side Hill Fill #4.
 CURRENT STATUS: TERMINATED STATUS DATE: 4/2/2009
 REQUIRED ACTIONS: Submit the final certification for Side Hill Fill #4.

ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: 860-5221 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2128 DATE VIOL. ISSUED: 3/4/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code HR) Failure to minimize disturbance to hydrologic balance by diminishing the water supply of households located on Hummingbird Lane.
 CURRENT STATUS: Non-Correctable STATUS DATE: 3/4/2009
 REQUIRED ACTIONS: Violation non-correctable because permittee has adversely affected the water supply of homes on Hummingbird Lane.

ABATEMENT ACTIONS:

PERMIT NO: 860-5221 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-2068 DATE VIOL. ISSUED: 12/29/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code EL: Discharge of substandard water from Pond #2.
 2) Code WQ: Discharge of substandard water from Pond #2.
 CURRENT STATUS: Non-Correctable STATUS DATE: 12/29/2008
 REQUIRED ACTIONS: 1) Non-Correctable
 2) Non-Correctable

ABATEMENT ACTIONS: Violation Non-Correctable

PERMIT NO: 860-5221 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-1893 DATE VIOL. ISSUED: 12/18/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code: OM. Permittee has failed to follow approved plans in Amendment #4 by not reconstructing Ponds #3 & #4, which were approved to be slightly relocated and enlarged.
 CURRENT STATUS: VACATED STATUS DATE: 1/21/2009
 REQUIRED ACTIONS: Permittee must either construct Ponds #3 & #4 according to approved plans in the AM #4 or submit, obtain and secure a Revision reflecting the infield condition of said ponds.

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 9 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 860-5221 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-1815 DATE VIOL. ISSUED: 4/11/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) Code SC: Failed to certify sediment structure #6.
 (2) Code WM: Failed to submit quarterly water monitoring reports.
 (3) Code SW: Failed to submit quarterly water monitoring reports.
 CURRENT STATUS: TERMINATED STATUS DATE: 5/13/2008
 REQUIRED ACTIONS: (1) Submit certification of construction for sediment structure #6.
 (2) Non-Correctable
 (3) Non-Correctable
 ABATEMENT ACTIONS: Required work completed, violation terminated 05/13/2008.

PERMIT NO: 860-5221 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-1811 DATE VIOL. ISSUED: 2/26/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) Code EL. Discharge of substandard water from Pond #4.
 (2) Code WQ. Discharge of substandard water from Pond #4.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/29/2008
 REQUIRED ACTIONS: (1 & 2) Must immediately stop discharge of substandard water and bring
 all additional discharges into compliance.
 ABATEMENT ACTIONS: Required work completed; violation terminated 2/29/2008

PERMIT NO: 860-5229 MSHA NO: 15-18166 MSHA DATE: 05/18/1999
 VIOLATION NO: 43-2324 DATE VIOL. ISSUED: 8/3/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Mining activities have caused several large subsidence cracks and
 surface openings on CRI # 08-04-0065 Ralph Martin Property.
 CURRENT STATUS: PENDING STATUS DATE:
 REQUIRED ACTIONS: Prevent public access to cracks and openings. Take appropriate
 measures to restore land. Seed and mulch immediately after
 reclamation. Submit & obtain permit revision for mitigation plan.
 ABATEMENT ACTIONS:

PERMIT NO: 860-5260 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-2381 DATE VIOL. ISSUED: 11/12/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Permittee mined into the outcrop barrier at the following approximate
 locations, North of Face up #2, Northwest of Face up #3, North of
 Face up #4, and West of Face up #1.
 CURRENT STATUS: TERMINATED STATUS DATE: 9/2/2009
 REQUIRED ACTIONS: An appropriate permitting action should be submitted and obtained
 addressing the removal of the unmined outcrop barrier.
 ABATEMENT ACTIONS: Required work completed; Violation terminated 09/02/2009.

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 10 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 860-5278 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-1847 DATE VIOL. ISSUED: 7/5/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code OM. Mining within 100 feet of a stream

CURRENT STATUS: TERMINATED STATUS DATE: 9/25/2008
 REQUIRED ACTIONS: Submit, secure & obtain a revision

ABATEMENT ACTIONS: Required work complete; Violation terminated 09/25/2008

PERMIT NO: 860-8005 MSHA NO: 15-17021 MSHA DATE:
 VIOLATION NO: 43-2047 DATE VIOL. ISSUED: 3/17/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code EL. Permittee allowed substandard discharge from Pond 005.

CURRENT STATUS: TERMINATED STATUS DATE: 3/25/2008
 REQUIRED ACTIONS: 2) Code WQ. Permittee allowed substandard discharge from Pond 005
 3) Code SC. Permittee allowed Pond 005 to exceed sediment capacity.

ABATEMENT ACTIONS: 1) Cease discharge of substandard water.
 2) Cease discharge of substandard water.
 3) Remove sediment from Pond 005; return pond to original capacity.
 Required work completed; violations 1&2 terminated 3/18/2008
 Required work completed; violation 3 terminated 3/25/2008

PERMIT NO: 860-8005 MSHA NO: 15-17021 MSHA DATE: 11/30/90
 VIOLATION NO: 43-1844 DATE VIOL. ISSUED: 4/11/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) Substandard water from ponds 2 & 5 has been discharged into stream at Fourmile Branch of Jones Fork

CURRENT STATUS: TERMINATED STATUS DATE: 4/17/2007
 REQUIRED ACTIONS: (2) See Above
 (1) Prevent discharge of substandard water into stream
 (2) Prevent discharge of substandard water into stream

ABATEMENT ACTIONS: Required work completed; violations (1)&(2) completed

PERMIT NO: 867-0404 MSHA NO: N/A MSHA DATE: 00/00/00
 VIOLATION NO: 53-0646 DATE VIOL. ISSUED: 3/15/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Permittee failed to have on the mine site the required "Blast Plan."

CURRENT STATUS: TERMINATED STATUS DATE: 3/20/2007
 REQUIRED ACTIONS: Have "Blast Plan" on site before blasting resumes.

ABATEMENT ACTIONS: Required work completed; violation terminated 3/20/2007.

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 11 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 867-0404 MSHA NO: N/A MSHA DATE: 00/00/00
 VIOLATION NO: 53-2060 DATE VIOL. ISSUED: 12/18/2006 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: (1) Permittee has exposed highwall on the Hazard #4 coal seam;
 (2) Permittee has constructed an unapproved sump/pond, which is
 impounding water on spoil material.
 CURRENT STATUS: TERMINATED STATUS DATE:
 REQUIRED ACTIONS: (1) Eliminate all exposed highwall; conduct backfill and grading
 (2) Drain and conduct grading operations to eliminate sump/pond.
 ABATEMENT ACTIONS: Required work complete, violations terminated 8/21/2006.

PERMIT NO: 867-0446 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 53-2550 DATE VIOL. ISSUED: 4/2/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code: CR. Exposed Highwall
 CURRENT STATUS: Non-Correctable STATUS DATE: 6/16/2008
 REQUIRED ACTIONS: Begin reclamation work to eliminate all highwalls.
 ABATEMENT ACTIONS: Violation changed to Non-Correctable due to the transfer to Deane
 Mining Co.

PERMIT NO: 867-0446 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 53-2057 DATE VIOL. ISSUED: 12/14/2006 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code CR. Permittee has exposed highwall.
 CURRENT STATUS: TERMINATED STATUS DATE: 4/2/2008
 REQUIRED ACTIONS: Begin reclamation work to eliminate all highwalls; seed and mulch
 disturbed areas.
 ABATEMENT ACTIONS: Required work complete, violation terminated 4/02/2008

PERMIT NO: 867-5182 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 53-2555 DATE VIOL. ISSUED: 6/25/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code OD: Personnel working on behalf of Deane Mining LLC, have
 transported material to an area not permitted.
 CURRENT STATUS: TERMINATED STATUS DATE: 10/27/2008
 REQUIRED ACTIONS: Immediately provide temporary sediment control for the disturbed
 area and begin measures to reclaim the disturbance.
 ABATEMENT ACTIONS: Violation deemed non-correctable because a transfer from Consol of
 Kentucky Permit #867-5182 to Deane Mining, LLC Permit
 #867-5300 has been issued.

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 12 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 867-5182 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 53-2554 DATE VIOL. ISSUED: 6/10/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code WQ: Permittee has allowed a substandard discharge.
 2) Code EL: Permittee has allowed a substandard discharge.

CURRENT STATUS: TERMINATED STATUS DATE: 10/27/2008

REQUIRED ACTIONS: 1 & 2) Must immediately begin measures to stop the substandard discharge and install temp. treatment at the site. Must also submit a Revision that will allow an approved "designed pond."

ABATEMENT ACTIONS: Violation deemed non-correctable because a transfer from Consol of Kentucky Permit #867-5182 to Deane Mining, LLC Permit #867-5300 has been issued.

PERMIT NO: 867-5182 MSHA NO: MSHA DATE:
 VIOLATION NO: 53-0647 DATE VIOL. ISSUED: 8/17/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Failed to properly dispose and/or store non-coal waste

CURRENT STATUS: TERMINATED STATUS DATE: 11/15/2007

REQUIRED ACTIONS: Must recover and properly dispose of all non-coal waste

ABATEMENT ACTIONS: Required work completed, violation terminated 11/15/2006.

PERMIT NO: 867-5182 MSHA NO: 15-18505 MSHA DATE:
 VIOLATION NO: 53-2547 DATE VIOL. ISSUED: 10/30/2006 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Unapproved Operator - Murriell-Don Coal (failure to comply with permit term and conditions).

CURRENT STATUS: TERMINATED STATUS DATE: 3/8/2007

REQUIRED ACTIONS: Remove Operator and/or comply with permit terms and conditions and/or obtain "Operator Change Revision"

ABATEMENT ACTIONS: Required work completed; violation terminated 3/8/2007.

PERMIT NO: 867-5184 MSHA NO: MSHA DATE:
 VIOLATION NO: 53-2317 DATE VIOL. ISSUED: 3/28/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code: OM. Failed to follow plans for the sealing of "punch-outs."
 Plans requires pipes to be installed within punch-out openings

CURRENT STATUS: TERMINATED STATUS DATE:

REQUIRED ACTIONS: Must install pipes as required by permit or obtain revision that deletes this requirement.

ABATEMENT ACTIONS: Modified to Non-Correctable - 12/08/2008

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 13 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 867-9007 MSHA NO: MSHA DATE: N/A
 VIOLATION NO: 53-2870 DATE VIOL. ISSUED: 6/24/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code WQ: Failed to pass all surface drainage through sediment control. Allowed water to pass through breach in Diversion Ditch #3.
 2) Code DV: Allowed large breach in Diversion Ditch #3.
 CURRENT STATUS: TERMINATED STATUS DATE: 8/20/2009
 REQUIRED ACTIONS: 1&2) Install temp. sediment control. Reconstruct/repair breach. Retrieve as much material as possible without creating additional environmental damage. Seed & mulch disturbed areas.
 ABATEMENT ACTIONS: Extended to 8/23/09
 Required work completed; Violation Terminated

PERMIT NO: 867-9007 MSHA NO: MSHA DATE: N/A
 VIOLATION NO: 53-2314 DATE VIOL. ISSUED: 2/3/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code EL: Permittee has allowed substandard water to be discharged from Pond #5. 2) Code WQ: Permittee has allowed substandard water to be discharged from Pond #5.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/6/2009
 REQUIRED ACTIONS: 1&2) Permittee shall take any and all measures necessary to bring discharge of Pond #5 into compliance with KPDES Permit Limitations.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: 867-9007 MSHA NO: MSHA DATE: N/A
 VIOLATION NO: 53-2305 DATE VIOL. ISSUED: 1/21/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Permittee has failed to remove junk equipment, equipment parts, etc from an area designated as a "topsoil storage area."
 CURRENT STATUS: TERMINATED STATUS DATE: 4/8/2009
 REQUIRED ACTIONS: Permittee shall immediately begin measures to remove all junk equipment, etc. from area in violation and dispose of in approved manner. Permittee must also seed and mulch all disturbed areas.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: 867-9007 MSHA NO: MSHA DATE: N/A
 VIOLATION NO: 53-0664 DATE VIOL. ISSUED: 11/30/2007 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Failed to maintain adequate drainage for the Coal Waste Dam
 CURRENT STATUS: TERMINATED STATUS DATE: 12/14/2007
 REQUIRED ACTIONS: Establish adequate drainage and repair damage
 ABATEMENT ACTIONS: Required work completed, violation terminated 12/14/2007.

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 14 of 57

Entity to whom violation(s) were issued: **CONSOL of Kentucky Inc.**

PERMIT NO: 877-0166 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-2279 DATE VIOL. ISSUED: 2/2/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code AC: Permittee and/or operator has failed to properly maintain access road #1 according to approved plans. 2) Code OD: Permittee and operator has allowed mud and debris to be tracked off permit area.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/11/2009
 REQUIRED ACTIONS: 1) Regrade the surface of access road.
 2) Remove, return and properly dispose of the mud and debris.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: 877-0166 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-0791 DATE VIOL. ISSUED: 8/1/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code OD: Material has been tracked from Haul Road #3 onto state road 3336.
 CURRENT STATUS: TERMINATED STATUS DATE: 8/4/2008
 REQUIRED ACTIONS: Retrieve all material which has been tracked onto 3336 and return it to the permitted area.
 ABATEMENT ACTIONS: Required work completed: violation terminated 08/04/2008.

PERMIT NO: 877-0166 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-2079 DATE VIOL. ISSUED: 6/24/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code CR: Failed to eliminate high-wall in timely manner.
 2) Code OD: Created surface disturbances outside permitted area.
 3) Code OO: Operator extended past underground permit boundary
 CURRENT STATUS: TERMINATED STATUS DATE: 2/26/2009
 REQUIRED ACTIONS: 1) Eliminate all remaining high-wall.
 2) Obtain a revision which will bring this area within permit boundary.
 3) Obtain a revision which will bring this area within permit boundary.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: 877-0166 MSHA NO: N/A MSHA DATE: N/A
 VIOLATION NO: 43-1934 DATE VIOL. ISSUED: 3/27/2008 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: Code: UE. Failed to maintain blasting records.
 CURRENT STATUS: Non-Correctable STATUS DATE: 3/27/2008
 REQUIRED ACTIONS: Contract blasting company no longer operating on site.
 ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 15 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: 877-0189 MSHA NO: MSHA DATE:
 VIOLATION NO: 43-2280 DATE VIOL. ISSUED: 2/2/2009 ISSUED BY: KY DSMRE
 VIOLATION DESCRIPTION: 1) Code AC: Permittee and/or operator has failed to properly maintain access road #1 according to approved plans. 2) Code OD: Permittee and operator has allowed mud and debris to be tracked off permit area.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/11/2009
 REQUIRED ACTIONS: 1) Regrade the surface of access road.
 2) Remove, return and properly dispose of the mud and debris.
 ABATEMENT ACTIONS: Required work completed; Violation terminated.

PERMIT NO: S-5009-05 MSHA NO: MSHA DATE:
 VIOLATION NO: S-5009-05 (12) DATE VIOL. ISSUED: 6/29/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to provide 0.125 ac/ft of sediment storage volume per acre.
 CURRENT STATUS: TERMINATED STATUS DATE: 6/29/2009
 REQUIRED ACTIONS: Construct sediment containment to 0.125 ac/ft as per regulations.

ABATEMENT ACTIONS:

PERMIT NO: S-5009-05 MSHA NO: 46-08904 MSHA DATE:
 VIOLATION NO: S-5009-05 (11) DATE VIOL. ISSUED: 1/15/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to protect off-site areas during surface mining by not preventing waste accumulations outside the permit area, in that wet coal from trucks was despositing black water onto highway 119.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/6/2009
 REQUIRED ACTIONS: Permittee is to load coal in a manner that will insure that it is not saturated with pit water. Permittee is to submit a statement on how material will be done to prevent this in the future.

ABATEMENT ACTIONS:

PERMIT NO: S-5009-05 MSHA NO: 46-08904 MSHA DATE:
 VIOLATION NO: S-5009-05 (10) DATE VIOL. ISSUED: 1/13/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to prevent air pollution and fugitive dust in that a blast from permit shot dust over highway 119, 1200 feet north of the permit.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/6/2009
 REQUIRED ACTIONS: Permittee is to place wind socks at edge of permit on operator and permittee work zones. Blasting is to only occur when wind direction is towards the permit.

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 16 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: S-5009-05 MSHA NO: 46-08904 MSHA DATE:
 VIOLATION NO: S-5009-05 (9) DATE VIOL. ISSUED: 1/13/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to prevent damage from occurring off permitted areas in that rocks were below SD 22 area of permit. Some of these were above residences but are stable at their present location.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/6/2009
 REQUIRED ACTIONS: Remove rocks from offsite areas or place them in the nearby subsidence cracks of Bronzite mine.

ABATEMENT ACTIONS:

PERMIT NO: S-5009-05 MSHA NO: 46-08904 MSHA DATE:
 VIOLATION NO: S-5009-05 (8) DATE VIOL. ISSUED: 1/7/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to construct and maintain sediment control systems in that pond 6 was unable to pass less than a 1 year storm event without erosion of the embankment around the spillway.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/6/2009
 REQUIRED ACTIONS: Stabilize eroded area around the spillway and provide erosion protection. Reconstruct spillway riprap and grout upon completion.

ABATEMENT ACTIONS:

PERMIT NO: S-5009-05 MSHA NO: MSHA DATE:
 VIOLATION NO: S-5009-05 (7) DATE VIOL. ISSUED: 8/21/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to certify drainage before disturbance in that Drainage Area SD 11 & SD 12 did not have drainage certified prior to disturbance.
 CURRENT STATUS: TERMINATED STATUS DATE: 9/23/2008
 REQUIRED ACTIONS: Remove all equipment except what may be required to maintain sediment control in area. Certify sediment control for Drainage areas.

ABATEMENT ACTIONS: Violated terminated - 09/23/2008

PERMIT NO: S-5009-05 MSHA NO: MSHA DATE:
 VIOLATION NO: S-5009-05 (6) DATE VIOL. ISSUED: 7/24/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to prevent damage from occurring off permitted area in that area below the Coalburg has been disturbed north of Fill 1033.
 CURRENT STATUS: TERMINATED STATUS DATE: 10/14/2008
 REQUIRED ACTIONS: Enlarge the berm of pit drainage at box cut area north of Fill 1033. Remove any material from mining area that is on below the Coalburg seam. Hydroseed disturbed areas & provide updated map of areas.

ABATEMENT ACTIONS: Violated terminated - 10/14/2008

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 17 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: S-5009-05 MSHA NO: MSHA DATE:
 VIOLATION NO: S-5009-05 (5) DATE VIOL. ISSUED: 5/19/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to prevent damage from occurring off permitted area
 in that area below the Coalburg has been disturbed near Fill 1033.

CURRENT STATUS: TERMINATED STATUS DATE: 5/28/2008
 REQUIRED ACTIONS: Submit an IBR to add disturbed area onto the permit.

ABATEMENT ACTIONS:

PERMIT NO: S-5009-05 MSHA NO: MSHA DATE:
 VIOLATION NO: S-5009-05 (4) DATE VIOL. ISSUED: 4/2/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to minimize the disturbance of the hydrologic
 balance within the permit during the construction of pond 2.

CURRENT STATUS: TERMINATED STATUS DATE: 4/3/2008
 REQUIRED ACTIONS: Floc Pond 2. Pump down pond 2 after flocculent is added and
 grout the spillway of pond 2.

ABATEMENT ACTIONS: Violation terminated 04/03/2008

PERMIT NO: S-5018-06 MSHA NO: MSHA DATE:
 VIOLATION NO: S-5018-06 (1) DATE VIOL. ISSUED: 8/18/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee conducted surface mining activities in a component
 drainage area without certifying a sediment control structure for
 said drainage area.

CURRENT STATUS: TERMINATED STATUS DATE: 8/19/2009
 REQUIRED ACTIONS: Permittee is to cease disturbances in component drainage areas of
 Valley Fill 1 until ponds are properly constructed & certified.

ABATEMENT ACTIONS:

PERMIT NO: S-5038-93 MSHA NO: 46-01938 MSHA DATE: n/a
 VIOLATION NO: S-5038-93 (20) DATE VIOL. ISSUED: 6/3/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to protect off-site areas from slides or damages
 during surface mining operations.

CURRENT STATUS: PENDING STATUS DATE:
 REQUIRED ACTIONS: Permittee is to reconstruct portion of SC-II and re-install outfall 008;
 remove slide from off-site area and reclaim all disturbances.

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 19 of 57

Entity to whom violation(s) were issued: **CONSOL of Kentucky Inc.**

PERMIT NO: S-5038-93 MSHA NO: 46-09138 MSHA DATE: n/a
 VIOLATION NO: S-5038-93 (15) DATE VIOL. ISSUED: 4/24/2007 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: (1) Failed to properly construct sediment control system.

CURRENT STATUS: TERMINATED STATUS DATE: 5/15/2007
 REQUIRED ACTIONS: Construct and certify sediment control system.

ABATEMENT ACTIONS:

PERMIT NO: S-5038-93 MSHA NO: 46-09138 MSHA DATE: n/a
 VIOLATION NO: S-5038-93 (14) DATE VIOL. ISSUED: 2/13/2007 ISSUED BY: WV DEP

VIOLATION DESCRIPTION: Permittee failed to maintain haulroads in result mud and debris was tracked across paved area of haulroad and onto Rt. 52.

CURRENT STATUS: TERMINATED STATUS DATE: 2/28/2007
 REQUIRED ACTIONS: Upgrade drainage and provide durable surface for length of haulroad; grade road so water drains into ditches.

ABATEMENT ACTIONS: Required work completed; violation terminated 2/28/2007.

PERMIT NO: S-5039-93 MSHA NO: 46-09035 MSHA DATE: N/A
 VIOLATION NO: S-5039-93 (22) DATE VIOL. ISSUED: 2/13/2007 ISSUED BY: WV DEP

VIOLATION DESCRIPTION: Permittee failed to maintain haulroads in which the haulroad was extremely muddy and water was not draining properly.

CURRENT STATUS: TERMINATED STATUS DATE: 2/28/2007
 REQUIRED ACTIONS: Upgrade drainage and provide durable surface for entire length of haulroad.

ABATEMENT ACTIONS: Required work completed; violation terminated 2/28/2007.

PERMIT NO: S-5039-93 MSHA NO: na MSHA DATE: na
 VIOLATION NO: S-5039-93 (21) DATE VIOL. ISSUED: 12/5/2006 ISSUED BY: WV DEP

VIOLATION DESCRIPTION: Permittee failed to completely reclaim DRF 1301 before entering phase 4.

CURRENT STATUS: TERMINATED STATUS DATE: 3/14/2007
 REQUIRED ACTIONS: Reclaim DRF 1301 and all other areas; submit final certification.

ABATEMENT ACTIONS: Required work completed; violation terminated 3/14/2007.

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 20 of 57

Entity to whom violation(s) were issued: **CONSOL of Kentucky Inc.**

PERMIT NO: S-5039-93 MSHA NO: na MSHA DATE: na
 VIOLATION NO: S-5039-93 (20) DATE VIOL. ISSUED: 12/5/2006 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to control runoff and divert surface from the face of DRF 1301.

CURRENT STATUS: TERMINATED STATUS DATE: 1/2/2007
 REQUIRED ACTIONS: Divert surface off of the face of fill and work erosion gullies.

ABATEMENT ACTIONS: Required actions completed. Violation terminated.

PERMIT NO: S-5040-93 MSHA NO: 46-09035 MSHA DATE: na
 VIOLATION NO: S-5040-93 (10) DATE VIOL. ISSUED: 4/25/2007 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: (1) Failed to protect offsite areas from surface mining operations; material is outside permit area.

CURRENT STATUS: TERMINATED STATUS DATE: 6/1/2007
 REQUIRED ACTIONS: Remove material from offsite area.

ABATEMENT ACTIONS:

PERMIT NO: S-5040-93 MSHA NO: 46-09035 MSHA DATE: na
 VIOLATION NO: S-5040-93 (9) DATE VIOL. ISSUED: 2/13/2007 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to maintain haulroads in which the haulroad was extremely muddy and water was not draining properly.

CURRENT STATUS: TERMINATED STATUS DATE: 2/28/2007
 REQUIRED ACTIONS: Upgrade drainage and provide durable surface for entire length of haulroad.

ABATEMENT ACTIONS: Required work completed; violation terminated 2/28/2007.

PERMIT NO: S-5040-93 MSHA NO: na MSHA DATE: na
 VIOLATION NO: S-5040-93 (8) DATE VIOL. ISSUED: 10/17/2006 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee had spoil, debris, trees, and rock on the downslope.

CURRENT STATUS: TERMINATED STATUS DATE: 12/5/2006
 REQUIRED ACTIONS: Remove all debris, trees, and rock; regrade; seed. Update map.

ABATEMENT ACTIONS: Required work completed; violation terminated 12/5/2006

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 21 of 57

Entity to whom violation(s) were issued: **CONSOL of Kentucky Inc.**

PERMIT NO: U-5001-08 MSHA NO: 46-09307 MSHA DATE:
 VIOLATION NO: U-5001-08 (2) DATE VIOL. ISSUED: 3/10/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to properly construct/maintain access road. This allowed runoff without sediment control.

CURRENT STATUS: TERMINATED STATUS DATE: 3/26/2009
 REQUIRED ACTIONS: Properly surface access roadway and construct suitable sediment control for any roadway runoff.

ABATEMENT ACTIONS:

PERMIT NO: U-5001-08 MSHA NO: 46-09307 MSHA DATE:
 VIOLATION NO: U-5001-08 (3) DATE VIOL. ISSUED: 3/10/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to place material in a controlled manner in fill 2 area.

CURRENT STATUS: TERMINATED STATUS DATE: 3/26/2009
 REQUIRED ACTIONS: Complete all clearing and grubbing and removal of organics, trash and other deliterious materials prior to fill placement. Permittee must also install curtains in Pond 1 to alleviate short-circuiting of fill runoff.

ABATEMENT ACTIONS:

PERMIT NO: U-5001-08 MSHA NO: MSHA DATE:
 VIOLATION NO: U-5001-08 (1) DATE VIOL. ISSUED: 11/5/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to construct and certify sediment control structures prior to any surface mining activities in the component drainage area of Pond 1.

CURRENT STATUS: TERMINATED STATUS DATE: 11/18/2008
 REQUIRED ACTIONS: Cease cutting of trees within drainage areas controlled by Pond 1. Complete and certify Pond 1.

ABATEMENT ACTIONS: Required action complete; Violation terminated.

PERMIT NO: U-5038-86 MSHA NO: 46-06760 MSHA DATE: 1/16/1987
 VIOLATION NO: U-5038-86 (15) DATE VIOL. ISSUED: 1/16/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to prevent tacking off permit in that coal fines are being carried onto 119 by trucks.

CURRENT STATUS: TERMINATED STATUS DATE: 1/17/2008
 REQUIRED ACTIONS: Stop coal haulage from haulroad. Clean haulroad.

ABATEMENT ACTIONS:

28-Sep-09

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 22 of 57

Entity to whom violation(s) were issued: CONSOL of Kentucky Inc.

PERMIT NO: U-5038-86 MSHA NO: 46-06760 MSHA DATE:
VIOLATION NO: U-5038-86 (14) DATE VIOL. ISSUED: 9/6/2007 ISSUED BY: WV DEP
VIOLATION DESCRIPTION: Permittee failed to follow the approved mining limits of the permit.

CURRENT STATUS: TERMINATED STATUS DATE: 10/1/2009
REQUIRED ACTIONS: Cease activity outside approved mining limits.

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History**September 28, 2006 - September 28, 2009**

Attachment Page 23 of 57

Entity to whom violation(s) were issued: Consol Pennsylvania Coal Company

PERMIT NO: U-2006-01 MSHA NO: 36-07230 MSHA DATE: 10/01/81
 VIOLATION NO: U-2006-01 (3) DATE VIOL. ISSUED: 5/1/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to properly maintain the approved drainage system. Silt fence near the beginning of interceptor ditch failed and caused erosion shaft site on the 4J airshaft.
 CURRENT STATUS: TERMINATED STATUS DATE: 5/29/2008
 REQUIRED ACTIONS: Remove sediment material from silt fence and revegetate disturbed area below silt fence.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: U-2006-01 MSHA NO: 36-07230 MSHA DATE: 10/01/81
 VIOLATION NO: U-2006-01 (01) DATE VIOL. ISSUED: 1/7/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to minimize the disturbance to the prevailing hydrologic balance at the 12H Shaft site by allowing tailings water with a heavy sediment load to run off permit.
 CURRENT STATUS: TERMINATED STATUS DATE: 1/7/2008
 REQUIRED ACTIONS: Stop the flow of water off the permit
 ABATEMENT ACTIONS: Required work completed. Violation terminated 1/7/2008.

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 24 of 57

Entity to whom violation(s) were issued: **Consol Pennsylvania Coal Company, LLC**

PERMIT NO: 30841316 MSHA NO: 36-07230 MSHA DATE: 10/01/81
 VIOLATION NO: DATE VIOL. ISSUED: 5/9/2009 ISSUED BY: PA DEP
 VIOLATION DESCRIPTION: Failed to report damage within 10 days of being advised of subsidence damage to a structure or surface feature for the Finnegan Property.
 CURRENT STATUS: TERMINATED STATUS DATE:
 REQUIRED ACTIONS:

ABATEMENT ACTIONS:

PERMIT NO: 30841316 MSHA NO: 36-07230 MSHA DATE: 10/01/81
 VIOLATION NO: DATE VIOL. ISSUED: 5/8/2009 ISSUED BY: PA DEP
 VIOLATION DESCRIPTION: Failure to notify within 24 hours of being advised of water supply contamination, diminution or interruption for the property owner (Doug Tharp & Jennifer Gilbert) above or near Bailey Mine.
 CURRENT STATUS: TERMINATED STATUS DATE:
 REQUIRED ACTIONS:

ABATEMENT ACTIONS:

PERMIT NO: 30841316 MSHA NO: 36-07230 MSHA DATE: 10/01/81
 VIOLATION NO: DATE VIOL. ISSUED: 3/19/2008 ISSUED BY: Fish & Boat C
 VIOLATION DESCRIPTION: Black water, laden with coal fines, was flowing directly out of the emergency spillway and discharging directly into the Enlow Fork of Wheeling Creek.
 CURRENT STATUS: TERMINATED STATUS DATE:
 REQUIRED ACTIONS:

ABATEMENT ACTIONS:

PERMIT NO: CMAP 30841317 MSHA NO: MSHA DATE:
 VIOLATION NO: 242847 DATE VIOL. ISSUED: 2/13/2009 ISSUED BY: PA DEP
 VIOLATION DESCRIPTION: Failed to locate and identify a structure which has appeared since the permit application on the current submitted Enlow Fork 6 month map.
 CURRENT STATUS: STATUS DATE:
 REQUIRED ACTIONS: Submit a revised 6 month map, sheet 2-614. Revised map must show the location of the above mentioned structure.

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History**September 28, 2006 - September 28, 2009**

Attachment Page 25 of 57

Entity to whom violation(s) were issued: Consol Pennsylvania Coal Company, LLC

PERMIT NO: CMAP 30841317 MSHA NO: MSHA DATE:
 VIOLATION NO: 242444 DATE VIOL. ISSUED: 2/1/2009 ISSUED BY: PA DEP
 VIOLATION DESCRIPTION: Unauthorized discharge of drill water into Crafts Creek.

CURRENT STATUS: Terminated STATUS DATE:
 REQUIRED ACTIONS:

ABATEMENT ACTIONS:

PERMIT NO: CMAP 30841317 MSHA NO: MSHA DATE:
 VIOLATION NO: 240127 DATE VIOL. ISSUED: 2/1/2009 ISSUED BY: PA DEP
 VIOLATION DESCRIPTION: Mining induced changes to the streambed; After mining under the stream sections went dry; Approximately 200 fish died.

CURRENT STATUS: STATUS DATE:
 REQUIRED ACTIONS:

ABATEMENT ACTIONS:

PERMIT NO: CMAP 30841317 MSHA NO: MSHA DATE:
 VIOLATION NO: DATE VIOL. ISSUED: 12/16/2008 ISSUED BY: PA DEP
 VIOLATION DESCRIPTION: Failed to notify PA DEP within 10 days of being advised of the claim of subsidence damage.

CURRENT STATUS: Terminated STATUS DATE:
 REQUIRED ACTIONS:

ABATEMENT ACTIONS:

PERMIT NO: CMAP 30841317 MSHA NO: MSHA DATE:
 VIOLATION NO: DATE VIOL. ISSUED: 12/26/2006 ISSUED BY: PA DEP
 VIOLATION DESCRIPTION: Failed to notify PA DEP within 24 hours of being advised of water supply contamination, diminution or interruption for Richard & Laura Dorsey property.

CURRENT STATUS: Terminated STATUS DATE:
 REQUIRED ACTIONS:

ABATEMENT ACTIONS:

28-Sep-09

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 26 of 57

Entity to whom violation(s) were issued: Consol Pennsylvania Coal Company, LLC

PERMIT NO: CMAP 30841317 MSHA NO: MSHA DATE:
VIOLATION NO: DATE VIOL. ISSUED: 12/26/2006 ISSUED BY: PA DEP
VIOLATION DESCRIPTION: Failed to perform a structure survey on the Tim McCann residence
prior to the time that the structure fell within a 30 degree angle of
draw of underground mining.
CURRENT STATUS: Terminated STATUS DATE:
REQUIRED ACTIONS:

ABATEMENT ACTIONS:

PERMIT NO: U-2006-01 MSHA NO: 36-07230 MSHA DATE: 10/01/81
VIOLATION NO: U-2006-01 (4) DATE VIOL. ISSUED: 7/30/2009 ISSUED BY: WV DEP
VIOLATION DESCRIPTION: Failed to provide certification for drainage and sediment designs.

CURRENT STATUS: PENDING STATUS DATE:
REQUIRED ACTIONS: Submit certifications for drainage and sediment control designs.

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 27 of 57

Entity to whom violation(s) were issued: Consolidation Coal Company

PERMIT NO: 1400047 MSHA NO: MSHA DATE:
 VIOLATION NO: KXH0006465 DATE VIOL. ISSUED: 2/3/2009 ISSUED BY: VA DMLR
 VIOLATION DESCRIPTION: The Poly pipe that carries mine water from Buch#1 - VP3 failed to function as described in approved application. This resulted in an unauthorized discharge.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/18/2009
 REQUIRED ACTIONS: Re-Evaluate the Chloride water transmission system and submit the evaluation to DMLR prior to the resumption of pumping.

ABATEMENT ACTIONS:

PERMIT NO: 1400047 MSHA NO: 44-04856 MSHA DATE: n/a
 VIOLATION NO: WHW0004813 DATE VIOL. ISSUED: 11/13/2006 ISSUED BY: VA DMLR
 VIOLATION DESCRIPTION: Destroyed berm at vent shaft 12-development area, restricting the surface drainage from passing through an approved siltation structure.
 CURRENT STATUS: TERMINATED STATUS DATE: 11/13/2006
 REQUIRED ACTIONS: N/A - operator fixed berm during inspection

ABATEMENT ACTIONS: Required work completed; violation terminated 11/13/2006

PERMIT NO: 30841312 MSHA NO: 46-01968 MSHA DATE: n/a
 VIOLATION NO: DATE VIOL. ISSUED: 10/16/2006 ISSUED BY: PA DEP
 VIOLATION DESCRIPTION: Failure to notify the department of the subsidence damage claim.
 CURRENT STATUS: TERMINATED STATUS DATE: 10/21/2006
 REQUIRED ACTIONS: Complete a Mine Operator's Fax Report.

ABATEMENT ACTIONS:

PERMIT NO: 30841313 MSHA NO: 36-04281 MSHA DATE: 08/13/86
 VIOLATION NO: DATE VIOL. ISSUED: 11/13/2006 ISSUED BY: PA DEP
 VIOLATION DESCRIPTION: Failed to provide copies of water analysis.
 CURRENT STATUS: TERMINATED STATUS DATE: 11/17/2006
 REQUIRED ACTIONS: Provide copies of water analysis.

ABATEMENT ACTIONS: Required work completed; violation terminated.

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 29 of 57

Entity to whom violation(s) were issued: Consolidation Coal Company

PERMIT NO: O-2018-06 MSHA NO: MSHA DATE:
 VIOLATION NO: O-2018-06 (2) DATE VIOL. ISSUED: 2/18/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to minimize disturbance to hydrologic balance in that discharge in violation of 46-CRS-1-3-2(a) which caused condition not allowable in state water (Boggs Run) below Fill #3.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/26/2009
 REQUIRED ACTIONS: Clean out sedimentation sump at the toe of disturbance and contribute additional measures for erosion control and sedimentation retention.
 ABATEMENT ACTIONS: Required work completed; Violation terminated
 Sedimentation controls were maintained and added to site.

PERMIT NO: O-2018-06 MSHA NO: MSHA DATE:
 VIOLATION NO: O-2018-06 (1) DATE VIOL. ISSUED: 7/2/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Water was flowing off the permitted area with suspended solids, discoloring the receiving stream, Boggs Run.
 CURRENT STATUS: TERMINATED STATUS DATE: 7/3/2008
 REQUIRED ACTIONS: Control the carry over of sediment off the permitted area during construction.
 ABATEMENT ACTIONS: Required work completed; Violation terminated.

PERMIT NO: P-2021-07 MSHA NO: MSHA DATE:
 VIOLATION NO: P-2021-07 (1) DATE VIOL. ISSUED: 1/31/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to install haybales & sediment fences to control soil erosion
 CURRENT STATUS: TERMINATED STATUS DATE: 4/17/2008
 REQUIRED ACTIONS: Correctly install haybales & silt fences. Stbilize any disturbed areas.
 ABATEMENT ACTIONS:

PERMIT NO: P-2034-07 MSHA NO: MSHA DATE:
 VIOLATION NO: P-2034-07 (1) DATE VIOL. ISSUED: 1/22/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to notify Environmental Inspector 5 days prior to operation
 CURRENT STATUS: TERMINATED STATUS DATE: 2/1/2008
 REQUIRED ACTIONS: Notify inspector prior to moving drilling equipment.
 ABATEMENT ACTIONS: Violation Terminated: 2/01/2008

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 33 of 57

Entity to whom violation(s) were issued: Consolidation Coal Company

PERMIT NO: U-104-83 MSHA NO: 46-013318 MSHA DATE:
 VIOLATION NO: U-104-83 (76) DATE VIOL. ISSUED: 5/22/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to certify that an approved drainage system was constructed as designed prior to commencement of surface-mining operations. 18A Bleeder Shaft.
 CURRENT STATUS: TERMINATED STATUS DATE: 6/23/2009
 REQUIRED ACTIONS: Certify the following structures: Drainage System 18A Bleeder Shaft Access Road, Sed Detention Pond 18A Shaft Site, Relocated Stream Channel 18A Shaft, Diversion Ditches 1&2, Flumes 1&2 at 18A.
 ABATEMENT ACTIONS:

PERMIT NO: U-104-83 MSHA NO: 46-013318 MSHA DATE:
 VIOLATION NO: U-104-83 (75) DATE VIOL. ISSUED: 5/22/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Discharged water from areas disturbed by surface mining that caused a violation of applicable water quality standards. Water in Rob. Run was discolored by fine coal particles.
 CURRENT STATUS: TERMINATED STATUS DATE: 5/22/2009
 REQUIRED ACTIONS: Cease discharge of black water containing coal fines immediately. Locate and correct the cause of the non-compliant discharge.
 ABATEMENT ACTIONS: Black water discharge ceased and was replaced by fresh water discharge. Culvert has been cleaned.

PERMIT NO: U-104-83 MSHA NO: 46-013318 MSHA DATE:
 VIOLATION NO: U-104-83 (74) DATE VIOL. ISSUED: 9/23/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to submit all information required by the director in the application for permit renewal prior to the expiration of the valid Article 3 Surface Mining Permit.
 CURRENT STATUS: TERMINATED STATUS DATE: 1/15/2009
 REQUIRED ACTIONS: Complete requirements and obtain approval of permit renewal.
 ABATEMENT ACTIONS: Extension granted to 12/23/2008. Required work completed; Violation terminated

PERMIT NO: U-104-83 MSHA NO: 46-013318 MSHA DATE:
 VIOLATION NO: U-104-83 (73) DATE VIOL. ISSUED: 6/21/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Conducted surface mining operations in such a manner as to create an imminent danger to the safety of the public in that material rolled down-slope beyond the permit boundary into a citizen's yard.
 CURRENT STATUS: PENDING STATUS DATE: 9/19/2008
 REQUIRED ACTIONS: Remove materials from citizen's yard, Stabilize outcrops, Guard area, Submit a report explaining why this danger occurred and what measures will be taken to prevent further occurrences.
 ABATEMENT ACTIONS: Extension granted to 05/17/2009

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 34 of 57

Entity to whom violation(s) were issued: Consolidation Coal Company

PERMIT NO: U-104-83 MSHA NO: 46-013318 MSHA DATE:
 VIOLATION NO: U-104-83 (72) DATE VIOL. ISSUED: 6/19/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Conducted surface mining operations in such a manner as to create an imminent danger to the safety of the public in that material rolled down-slope beyond the permit boundary into a citizen's yard.
 CURRENT STATUS: Modified to NOV STATUS DATE: 6/21/2008
 REQUIRED ACTIONS: Remove materials from citizen's yard, Stabilize outcrops, Guard area, Submit a report explaining why this danger occurred and what measures will be taken to prevent further occurrences.
 ABATEMENT ACTIONS:

PERMIT NO: U-104-83 MSHA NO: 46-013318 MSHA DATE:
 VIOLATION NO: U-104-83 (71) DATE VIOL. ISSUED: 6/4/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to maintain effluent limitations as set forth in the NPDES permit.
 CURRENT STATUS: TERMINATED STATUS DATE: 6/5/2008
 REQUIRED ACTIONS: Treat effluent.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: U-119-83 MSHA NO: 46-01453 MSHA DATE: 00/00/00
 VIOLATION NO: U-119-83 (28) DATE VIOL. ISSUED: 12/7/2006 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Seep at Bethel Pump has caused stream pollution.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/28/2007
 REQUIRED ACTIONS: Get electricity and install pumps at Bethel Pump site, collect seep water and dispose of collected water properly.
 ABATEMENT ACTIONS: Required work completed; violation terminated 2/28/2007.

PERMIT NO: U-46-84 MSHA NO: 46-01968 MSHA DATE:
 VIOLATION NO: U-46-84 (28) DATE VIOL. ISSUED: 12/19/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Operator conducted mining operations outside the permitted area in between the Velone Shaft and the Houghs Hollow access road.
 CURRENT STATUS: TERMINATED STATUS DATE: 1/8/2009
 REQUIRED ACTIONS: Submit an IBR application to bond the disturbed area.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 35 of 57

Entity to whom violation(s) were issued: Consolidation Coal Company

PERMIT NO: U-46-84 MSHA NO: 46-01968 MSHA DATE:
 VIOLATION NO: U-46-84 (26) DATE VIOL. ISSUED: 6/25/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to timely report within 24 hours a water or slurry discharge spill in accordance with NPDES and Groundwater Protection Permits.

CURRENT STATUS: TERMINATED STATUS DATE: 7/25/2008
 REQUIRED ACTIONS: Must timely report all spills.

ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: U-46-84 MSHA NO: 46-01968 MSHA DATE:
 VIOLATION NO: U-46-84 (27) DATE VIOL. ISSUED: 6/25/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Caused off-site damages to Consolidation Coal and M. Staggers properties located behind the Fresh water Impoundment in that you allowed a discharge of slurry water into a creek.

CURRENT STATUS: TERMINATED STATUS DATE: 8/14/2008
 REQUIRED ACTIONS: 1) Must immediately install monitoring system. 2) Must submit proof of notification of landowner. 3) Must initiate and continue remedial efforts to clean up mess. 4) Must clean headwaters of impoundment.

ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: U-70-83 MSHA NO: 01452 MSHA DATE:
 VIOLATION NO: U-70-83 (41) DATE VIOL. ISSUED: 7/13/2007 ISSUED BY: WVDEP
 VIOLATION DESCRIPTION: Failed to minimize the disturbance to the hydrologic balance of Little Indian Creek due to a leak in the pipeline.

CURRENT STATUS: TERMINATED STATUS DATE:
 REQUIRED ACTIONS: Shut down pump and repair leak.

ABATEMENT ACTIONS: Required work completed: violation terminated 7/17/2007

PERMIT NO: U-70-83 MSHA NO: 01452 MSHA DATE:
 VIOLATION NO: U-70-83 (39) DATE VIOL. ISSUED: 6/5/2007 ISSUED BY: WVDEP
 VIOLATION DESCRIPTION: Failed to follow permit conditions

CURRENT STATUS: TERMINATED STATUS DATE: 11/2/2007
 REQUIRED ACTIONS: Implement and complete the modifications approved in Revision 25

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History**September 28, 2006 - September 28, 2009**

Attachment Page 36 of 57

Entity to whom violation(s) were issued: Consolidation Coal Company

PERMIT NO: U-70-83 MSHA NO: 01452 MSHA DATE:
 VIOLATION NO: U-70-83 (40) DATE VIOL. ISSUED: 6/5/2007 ISSUED BY: WVDEP
 VIOLATION DESCRIPTION: Failed to certify that the drainage system was constructed and installed in accordance with the approved plan.

CURRENT STATUS: TERMINATED STATUS DATE:
 REQUIRED ACTIONS: Submit drainage certification.

ABATEMENT ACTIONS: Required work completed: violation terminated 7/18/2007

PERMIT NO: U-70-83 MSHA NO: 46-01452 MSHA DATE: n/a
 VIOLATION NO: U-70-83 (38) DATE VIOL. ISSUED: 4/3/2007 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: (1)Failed to maintain approved drainage system.

CURRENT STATUS: TERMINATED STATUS DATE: 5/17/2007
 REQUIRED ACTIONS: (1) Repair, dress, seed and mulch drainage ditches and gullies.
 Regrade and dress haul road.

ABATEMENT ACTIONS:

PERMIT NO: U-78-83 MSHA NO: 46-01433 MSHA DATE: n/a
 VIOLATION NO: U-78-83 (42) DATE VIOL. ISSUED: 4/16/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to follow permit conditions in that a pre-subsidence survey, or waiver was not conducted and approved for the Dodd's property.

CURRENT STATUS: TERMINATED STATUS DATE: 4/17/2009
 REQUIRED ACTIONS: Before mining begins in an area, verify that a pre-subsidence survey or waiver has been approved for each owner and resident listed in the U007883 permit.

ABATEMENT ACTIONS: Required work completed, violation terminated.

PERMIT NO: U-78-83 MSHA NO: 46-01433 MSHA DATE: n/a
 VIOLATION NO: U-78-83 (41) DATE VIOL. ISSUED: 7/3/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to maintain effluent limitations as set forth in the NPDES Program at Outlets 024 & 025 in that the AI was above the limit.

CURRENT STATUS: TERMINATED STATUS DATE: 7/18/2008
 REQUIRED ACTIONS: Meet effluent limits at Outlets 024 & 025.

ABATEMENT ACTIONS: Required work completed, violation terminated.

28-Sep-09

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 38 of 57

Entity to whom violation(s) were issued: **Consolidation Coal Company**

PERMIT NO:	UO-431	MSHA NO:	46-05620	MSHA DATE:	n/a
VIOLATION NO:	UO-431 (3)	DATE VIOL. ISSUED:	7/3/2008	ISSUED BY:	WV DEP
VIOLATION DESCRIPTION:	Failed to maintain effluent limitations as set forth in the NPDES Program at Outlet 002 in that the AI was 1.48 ppm which is above the allowed limit of 0.75 ppm.				
CURRENT STATUS:	TERMINATED	STATUS DATE:	7/18/2008		
REQUIRED ACTIONS:	Meet effluent limits at Outlet 002.				
ABATEMENT ACTIONS:	Required work completed; Violation terminated.				

28-Sep-09

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 39 of 57

Entity to whom violation(s) were issued: Eighty Four Mining Company

PERMIT NO: CMAP 63831302 MSHA NO: MSHA DATE:
VIOLATION NO: 244939 DATE VIOL. ISSUED: 4/13/2009 ISSUED BY: PA DEP
VIOLATION DESCRIPTION: Failed to notify PA DEP within 24 hours of being advised of water
supply contamination, diminuation or interruption for the property of
JoAnn Standish 2-11-5.4.
CURRENT STATUS: Non-Correctable STATUS DATE:
REQUIRED ACTIONS:

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 40 of 57

Entity to whom violation(s) were issued: Fola Coal Company, L.L.C.

PERMIT NO: O-2011-93 MSHA NO: 46-08376 MSHA DATE:
 VIOLATION NO: O-2011-93 (20) DATE VIOL. ISSUED: 2/25/2009 ISSUED BY: WV DEP

VIOLATION DESCRIPTION: Operator failed to maintain effluent limits for AL @ Outfall 003.
 Sample was taken on 01/07/2009 during a complete inspection. Lab results shows 2.27 ppm and flow was < 10 GPM.

CURRENT STATUS: PENDING STATUS DATE:

REQUIRED ACTIONS:

Operator needs to maintain effluent limits.

ABATEMENT ACTIONS:

PERMIT NO: S-2005-02 MSHA NO: 46-08377 MSHA DATE:
 VIOLATION NO: S-2005-02 (17) DATE VIOL. ISSUED: 1/7/2009 ISSUED BY: WV DEP

VIOLATION DESCRIPTION: Operator failed to minimize the disturbance to the prevailing hydrologic balance at outfall 025 & 026.

CURRENT STATUS: TERMINATED STATUS DATE: 1/20/2009

REQUIRED ACTIONS:

Operator needs to construct additional sumps along internal haul roads and divert water from haul road to constructed sediment cells.

ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: S-2005-99 MSHA NO: MSHA DATE:
 VIOLATION NO: S-2005-99 (4) DATE VIOL. ISSUED: 9/10/2009 ISSUED BY: WV DEP

VIOLATION DESCRIPTION: Failed to maintain effluent limits in that Outlet #003 discharged water that exceeded the max limit for Al.

CURRENT STATUS: PENDING STATUS DATE:

REQUIRED ACTIONS:

Take action to bring the Outlet into compliance.

ABATEMENT ACTIONS:

PERMIT NO: S-2006-05 MSHA NO: MSHA DATE:
 VIOLATION NO: S-2006-05 (4) DATE VIOL. ISSUED: 7/10/2009 ISSUED BY: WV DEP

VIOLATION DESCRIPTION: Failed to follow approved mining and reclamation plan. All surface operations shall be conducted so as to comply with approved plan. Exceeded the allowed disturbed acreage of 30.8.

CURRENT STATUS: PENDING STATUS DATE:

REQUIRED ACTIONS:

1) Must revise and submit mining and reclamation plan to include disturbed acres on SM#4. 2) Provide inspector with a new progress map within 30 days.

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 41 of 57

Entity to whom violation(s) were issued: Fola Coal Company, L.L.C.

PERMIT NO:	S-2007-98	MSHA NO:	46-08727	MSHA DATE:	
VIOLATION NO:	S-2007-98 (20)	DATE VIOL. ISSUED:	2/27/2009	ISSUED BY:	WV DEP
VIOLATION DESCRIPTION:	Operator failed to properly maintain haulroad sumps. Sump was discharging muddy water into Right Fork of Leatherwood.				
CURRENT STATUS:	TERMINATED			STATUS DATE:	3/16/2009
REQUIRED ACTIONS:	Clean haul road sumps and re-grade road so that water flows through all constructed sumps. Place hay bales at the exit channel of truck wash and maintain.				
ABATEMENT ACTIONS:					
PERMIT NO:	S-2012-98	MSHA NO:		MSHA DATE:	
VIOLATION NO:	S-2012-98 (2)	DATE VIOL. ISSUED:	2/6/2009	ISSUED BY:	WV DEP
VIOLATION DESCRIPTION:	Failed to follow the approved Pre-Plan (Permit) in that several roads were built off bonded area.				
CURRENT STATUS:	TERMINATED			STATUS DATE:	4/17/2009
REQUIRED ACTIONS:	Submit Permit Revision to include all disturbed areas and incorporate these areas into the Reclamation Plan.				
ABATEMENT ACTIONS:	Required work completed; Violation terminated				
PERMIT NO:	S-2012-98	MSHA NO:		MSHA DATE:	
VIOLATION NO:	S-2012-98 (1)	DATE VIOL. ISSUED:	2/5/2009	ISSUED BY:	WV DEP
VIOLATION DESCRIPTION:	Failed to submit surface and groundwater monitoring reports for the 4th Quarter 2008.				
CURRENT STATUS:	TERMINATED			STATUS DATE:	2/10/2009
REQUIRED ACTIONS:	Submit Article 3 water monitoring data for the 4th Quarter 2008.				
ABATEMENT ACTIONS:					
PERMIT NO:	S-2013-98	MSHA NO:	46-08754	MSHA DATE:	
VIOLATION NO:	S-2013-98 (12)	DATE VIOL. ISSUED:	2/19/2009	ISSUED BY:	WV DEP
VIOLATION DESCRIPTION:	Operator has failed to follow permit conditions in that, operator has exceeded the 300' wing dumping of spoil material in Valley Fill 3.				
CURRENT STATUS:	TERMINATED			STATUS DATE:	3/20/2009
REQUIRED ACTIONS:	Operator must follow the approved preplan and fix areas disturbed by the excess wing dumping.				
ABATEMENT ACTIONS:	Required work completed; Violation terminated				

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 42 of 57

Entity to whom violation(s) were issued: Fola Coal Company, L.L.C.

PERMIT NO: S-2013-98 MSHA NO: 46-08754 MSHA DATE:
 VIOLATION NO: S-2013-98 (13) DATE VIOL. ISSUED: 2/19/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Operator has placed spoil material on the downslope. Spoil material is located between Valley Fill #1 and below the coalburg seam.
 CURRENT STATUS: TERMINATED STATUS DATE: 3/20/2009
 REQUIRED ACTIONS: Operator needs to recover material, reclaim and vegetate area.

ABATEMENT ACTIONS:

PERMIT NO: S-2013-98 MSHA NO: 46-08754 MSHA DATE:
 VIOLATION NO: S-2013-98 (11) DATE VIOL. ISSUED: 1/30/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: During construction, operator has failed to maintain in such a manner as to prevent water from discharging over the face of the Valley Fill (Fill #4)
 CURRENT STATUS: TERMINATED STATUS DATE: 4/15/2009
 REQUIRED ACTIONS: Operator needs to configure the top of the Fill to prevent water from discharging over the face and construct groin ditches to minimize erosion.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: S-2013-98 MSHA NO: 46-08754 MSHA DATE:
 VIOLATION NO: S-2013-98 (10) DATE VIOL. ISSUED: 1/30/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to handle material that is potentially toxic and/or acid producing within 30 days after initial exposure. Area above Valley Fill #4 and the right side of Valley Fill #1.
 CURRENT STATUS: TERMINATED STATUS DATE: 4/15/2009
 REQUIRED ACTIONS: Must follow the approved preplan. Any and all material determined to be toxic/acid producing will be placed in the backfill within 30 days after exposure. Remove all pit cleanings from Valley Fill #1 & #4.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: S-2013-98 MSHA NO: 46-08754 MSHA DATE:
 VIOLATION NO: S-2013-98 (9) DATE VIOL. ISSUED: 1/30/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to keep operations current; mining operations and reclamation operations were not coordinated to minimize total disturbance and did not keep reclamation contemporaneous as possible.
 CURRENT STATUS: TERMINATED STATUS DATE: 6/29/2009
 REQUIRED ACTIONS: Must reclaim areas to keep reclamation operations current and coordinate mining operations to minimize total disturbance. Must backfill and grade highwall at the head of Valley Fill #1.
 ABATEMENT ACTIONS:

28-Sep-09

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 43 of 57

Entity to whom violation(s) were issued: Island Creek Coal Company

PERMIT NO: U-5025-96 MSHA NO: 46-08665 MSHA DATE:
VIOLATION NO: U-5025-96 (3) DATE VIOL. ISSUED: 1/5/2007 ISSUED BY: WV DEP
VIOLATION DESCRIPTION: Permittee ceased mining operations for more than 30 days
in that the refuse area has not been reclaimed

CURRENT STATUS: TERMINATED STATUS DATE: 5/3/2007
REQUIRED ACTIONS: Immediately submit an IBR for a topsoil borrow area to reclaim the
refuse area.

ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 45 of 57

Entity to whom violation(s) were issued: Little Eagle Coal Company, L.L.C.

PERMIT NO: U028800 MSHA NO: MSHA DATE:
 VIOLATION NO: U028800 (27) DATE VIOL. ISSUED: 11/13/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to maintain haulroad sumps to meet the performance standards of this part and any additional criteria specified by the Secretary.

CURRENT STATUS: TERMINATED STATUS DATE: 11/26/2008
 REQUIRED ACTIONS: Maintain and/or clean haulroad sumps as per your approved application and/or the regulations.

ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: U200405 MSHA NO: MSHA DATE:
 VIOLATION NO: U200405 (3) DATE VIOL. ISSUED: 6/17/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Operator failed to follow the approved subsidence control plan. Operator has failed to notify owners of property and residents within the area above the underground workings.

CURRENT STATUS: TERMINATED STATUS DATE: 8/11/2008
 REQUIRED ACTIONS: Operator needs to follow the approved SCP and submit a revision to show the area outside the permit boundary. Must notify Lyle & Maxine Exline of the underground mining & notify other property owners.

ABATEMENT ACTIONS: Required work completed; Violation terminated.

PERMIT NO: U-2004-05 MSHA NO: MSHA DATE:
 VIOLATION NO: U-2004-05 (4) DATE VIOL. ISSUED: 1/12/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Operator failed to maintain effluent limits for AL @ Outfall 001. Sample was taken on 12/12/08 during a complete inspection. Lab results showed a 1.195 mg/l and the flow was <20 gpm.

CURRENT STATUS: TERMINATED STATUS DATE: 6/12/2009
 REQUIRED ACTIONS: Operator needs to maintain limits.

ABATEMENT ACTIONS: Maintained Effluent Limits at Outfall 001

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 46 of 57

Entity to whom violation(s) were issued: McElroy Coal Company

PERMIT NO: U-1026-92 MSHA NO: 46-01437 MSHA DATE: 00/00/00
 VIOLATION NO: U-1026-92 (4) DATE VIOL. ISSUED: 4/16/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to install and certify the proper extension of Collection Ditch #1
 Sediment 3C in accordance with the approved preplan.

CURRENT STATUS: TERMINATED STATUS DATE:
 REQUIRED ACTIONS: Install drainage control for disturbed area and reclaim disturbance
 in accordance with the approved preplan.

ABATEMENT ACTIONS: Required work completed, violation terminated.

PERMIT NO: U-2007-07 MSHA NO: 4601437 MSHA DATE:
 VIOLATION NO: U-2007-07 (1) DATE VIOL. ISSUED: 6/24/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to protect off site areas from damage resulting from mine
 operations. Used unbonded access road to enter site.

CURRENT STATUS: TERMINATED STATUS DATE: 7/1/2009
 REQUIRED ACTIONS: Revegetate access route that's been disturbed or obtain IBR to
 allow use of area.

ABATEMENT ACTIONS: Unbonded access road blocked off, disturbed area seeded, mulched.

PERMIT NO: U-33-83 MSHA NO: 46-01437 MSHA DATE: n/a
 VIOLATION NO: U-33-83 (67) DATE VIOL. ISSUED: 11/13/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to maintain effluent limitations set forth in the NPDES permit.
 Fish Creek Portal outlet 002 discharging 3.51 pH and +10ppm Fe.

CURRENT STATUS: TERMINATED STATUS DATE: 11/14/2008
 REQUIRED ACTIONS: Treat the discharge in order to meet effluent limits or eliminate
 discharge.

ABATEMENT ACTIONS: Required work completed; Violation terminated.

PERMIT NO: U-33-83 MSHA NO: 46-01437 MSHA DATE: n/a
 VIOLATION NO: U-33-83 (66) DATE VIOL. ISSUED: 11/12/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to maintain effluent limitations set forth in the NPDES permit.
 Fish Creek Portal outlet 002 discharging 3.51 pH and +10ppm Fe.

CURRENT STATUS: Violation modified to Cessation Order #67 STATUS DATE: 11/13/2008
 REQUIRED ACTIONS: Treat the discharge in order to meet effluent limits or eliminate
 discharge.

ABATEMENT ACTIONS: Violation modified to Cessation Order #67

CONSOL Energy and Related Companies - Violation History

September 28, 2006 - September 28, 2009

Attachment Page 48 of 57

Entity to whom violation(s) were issued: **McElroy Coal Company**

PERMIT NO: U-33-83 MSHA NO: 46-01437 MSHA DATE: n/a
 VIOLATION NO: U-33-83 (61) DATE VIOL. ISSUED: 2/23/2007 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to perform a pre-mining subsidence survey, obtain a waiver, or submit an affidavit for the James Thomas structure.

CURRENT STATUS: TERMINATED STATUS DATE: 2/23/2007
 REQUIRED ACTIONS: Submit and obtain approval of a pre-subsidence survey, waiver, or affidavit for the James Thomas structure.

ABATEMENT ACTIONS: Required work completed; violation terminated 2/23/2007

PERMIT NO: U-33-83 MSHA NO: 46-01437 MSHA DATE: n/a
 VIOLATION NO: U-33-83 (60) DATE VIOL. ISSUED: 2/22/2007 ISSUED BY: WV DEP

VIOLATION DESCRIPTION: Failure to maintain approved drainage control system; failed to install silt fence on the north outslope of the reclamation work on the cuttings pond.

CURRENT STATUS: TERMINATED STATUS DATE: 10/4/2007
 REQUIRED ACTIONS: Dewater structure and maintain until outslope is repaired and stable; Recertify structure; Install silt fence in accordance with permit plan.

ABATEMENT ACTIONS:

PERMIT NO: U-33-83 MSHA NO: 46-01437 MSHA DATE: n/a
 VIOLATION NO: U-33-83 (59) DATE VIOL. ISSUED: 10/18/2006 ISSUED BY: WV DEP

VIOLATION DESCRIPTION: Failed to maintain effluent limitations at Outlet 020 - Coal Stockpile Pond.

CURRENT STATUS: TERMINATED STATUS DATE: 10/19/2006
 REQUIRED ACTIONS: Provide adequate treatment and/or control measures to return Coal Stockpile Pond to required water quality standards.

ABATEMENT ACTIONS: Required work completed; violation terminated 10/19/2006

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 49 of 57

Entity to whom violation(s) were issued: Powellton Coal Company, L.L.C.

PERMIT NO: O-3005-00 MSHA NO: MSHA DATE:
 VIOLATION NO: O-3005-00 (5) DATE VIOL. ISSUED: 4/22/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Discharged water form areas disturbed by surface mining in violation of effluent limitations as governed by your NPDES permit at Outlet001. Aluminum 0.474
 CURRENT STATUS: TERMINATED STATUS DATE: 5/20/2009
 REQUIRED ACTIONS: Maintain effluent limits at Outlet 001.

ABATEMENT ACTIONS: Maintained Effluent Limits at Outfall 001

PERMIT NO: O-3007-00 MSHA NO: MSHA DATE:
 VIOLATION NO: O-3007-00 (18) DATE VIOL. ISSUED: 4/30/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to maintain haulroad as per approved application and/or the regulations in that various sumps were full and/or various pipes were crushed and/or and and/or all comments as listed in the annual cert.
 CURRENT STATUS: TERMINATED STATUS DATE: 5/27/2009
 REQUIRED ACTIONS: Maintain haulroad as per approved application and/or the regulations and address any and/or all comments in the annual certification.

ABATEMENT ACTIONS: Company has addressed all maintenance issues of the haulroad and has submitted a new annual certification.

PERMIT NO: O-3007-00 MSHA NO: MSHA DATE:
 VIOLATION NO: O-3007-00 (17) DATE VIOL. ISSUED: 11/13/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to erect and maintain permanent monument throughout the life of the permit at points of ingress and egress on the permit area from public roads and highways.
 CURRENT STATUS: TERMINATED STATUS DATE: 11/26/2008
 REQUIRED ACTIONS: Erect and maintain permanent monument (sign) at points in ingress and egress on the permit area from public roads and highways.

ABATEMENT ACTIONS: Required work completed; Violation terminated.

PERMIT NO: S-3002-07 MSHA NO: MSHA DATE:
 VIOLATION NO: S-3002-07 (13) DATE VIOL. ISSUED: 4/29/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to maintain effluent limits in areas disturbed by surface mining at outlet 012 in that you violated the effluent limits as governed by the standards set forth in your NPDES permit.
 CURRENT STATUS: TERMINATED STATUS DATE: 5/26/2009
 REQUIRED ACTIONS: Maintain effluent limits at outlet 012.

ABATEMENT ACTIONS: Treated water to maintain Effluent Limits

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

28-Sep-09

Attachment Page 50 of 57

Entity to whom violation(s) were issued: Powellton Coal Company, L.L.C.

PERMIT NO: S-3002-07 MSHA NO: MSHA DATE:
 VIOLATION NO: S-3002-07 (12) DATE VIOL. ISSUED: 3/11/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to protect off site areas from slides and/or damage in the vicinity of sediment ditches 5 & 6 during surface mining operations in that you placed and/or caused spoil material outside the permit area.
 CURRENT STATUS: PENDING STATUS DATE:
 REQUIRED ACTIONS: Gather and remove spoil material or any part of the operations from outside the permitted area. Stabilize, seed and mulch all affected area and add the slide area to your current pending IBR application.
 ABATEMENT ACTIONS: Extended to 4/27/2009

PERMIT NO: S-3002-07 MSHA NO: MSHA DATE:
 VIOLATION NO: S-3002-07 (11) DATE VIOL. ISSUED: 9/12/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to conduct all surface coal mining operations only as described in your approved application in that you failed to construct berm, road and ditch in drainage area 5 as per your approved application.
 CURRENT STATUS: TERMINATED STATUS DATE: 10/29/2008
 REQUIRED ACTIONS: Construct berm, road and ditch in drainage area 5 as per your approved application
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: S-3002-07 MSHA NO: MSHA DATE:
 VIOLATION NO: S-3002-07 (10) DATE VIOL. ISSUED: 7/10/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to construct and certify permanent sediment control ditches and/or sediment control structures in drainage area 4, 1000 linear ft. or less from the active pit.
 CURRENT STATUS: TERMINATED STATUS DATE: 9/11/2008
 REQUIRED ACTIONS: Construct, certify, and have certification accepted by DEP of permanent sediment ditches and/or sediment control structures in drainage area 4 as measured on 1000 linear ft. or less from active pit.
 ABATEMENT ACTIONS: Required work completed: Violation terminated.

PERMIT NO: S-3002-07 MSHA NO: MSHA DATE:
 VIOLATION NO: S-3002-07 (9) DATE VIOL. ISSUED: 7/10/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Discharged water from areas disturbed by surface mining in violation of effluent limitations as governed by the standards as set forth in your approved NPDES permit.
 CURRENT STATUS: TERMINATED STATUS DATE: 7/15/2008
 REQUIRED ACTIONS: Treat water at Outlets 010 and 013 so as to cease the discharging of non-compliant water from said outlets and/or bonded area.
 ABATEMENT ACTIONS: Required work completed: Violation terminated.

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

28-Sep-09

Attachment Page 51 of 57

Entity to whom violation(s) were issued: Powellton Coal Company, L.L.C.

PERMIT NO: S-3002-07 MSHA NO: MSHA DATE:
 VIOLATION NO: S-3002-07 (6) DATE VIOL. ISSUED: 6/11/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Created a disturbance by surface mining activities in drainage area 5 between outlet 011 and 012 prior to certifying the sediment control structure for this area.
 CURRENT STATUS: TERMINATED STATUS DATE: 6/12/2008
 REQUIRED ACTIONS: Cease all mining activities in drainage area 5 between outlets 011 and 012 until such time that said drainage structure/sediment ditch 5 is certified.
 ABATEMENT ACTIONS: Required work completed: Violation terminated.

PERMIT NO: S-3002-07 MSHA NO: MSHA DATE:
 VIOLATION NO: S-3002-07 (7) DATE VIOL. ISSUED: 6/11/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to conduct and submit a complete list of surface and ground water monitoring reports as per your approved application for the months of Sept. Oct. Nov. and Dec. 2007.
 CURRENT STATUS: TERMINATED STATUS DATE: 6/27/2008
 REQUIRED ACTIONS: Conduct and submit a complete list of surface and ground water monitoring reports as per your approved application or obtain a waiver to discontinue monitoring.
 ABATEMENT ACTIONS: Required work completed: Violation terminated.

PERMIT NO: S-3003-01 MSHA NO: 46-48889 MSHA DATE:
 VIOLATION NO: S-3003-01 (26) DATE VIOL. ISSUED: 4/21/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to construct and/or maintain sediment control structures, Pond 1 and sediment ditches near outlets 001, 002 & 004 in that structures are full and/or have reached capacity.
 CURRENT STATUS: PENDING STATUS DATE:
 REQUIRED ACTIONS: Construct and/or maintain sediment control structures, Pond 1 & sediment ditches near Outlets 001, 002, & 004 as per the regulations and/or your approved application.
 ABATEMENT ACTIONS:

PERMIT NO: S-3003-01 MSHA NO: 46-48889 MSHA DATE:
 VIOLATION NO: S-3003-01 (27) DATE VIOL. ISSUED: 4/21/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to follow approved application in that you failed to construct Valley Fills A, B, C & D so as to minimize infiltration of surface water in that you allowed water to flow over the face of the Fills.
 CURRENT STATUS: WITHDRAWN STATUS DATE: 7/21/2009
 REQUIRED ACTIONS: Construct Valley Fills A, B, C & D with all associated drainage structures as per your approved application and/or remove all material from Valley Fills and regrade to natural ground, seed & mulch affected areas.
 ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Entity to whom violation(s) were issued: Powellton Coal Company, L.L.C.

PERMIT NO:	S-3003-01	MSHA NO:	46-48889	MSHA DATE:	
VIOLATION NO:	S-3003-01 (25)	DATE VIOL. ISSUED:	1/15/2009	ISSUED BY:	WV DEP
VIOLATION DESCRIPTION:	Failed to protect off-site areas from slides and/or damage during surface mining in that you placed and/or caused to be placed spoil material on part of the outside permitted area.				
CURRENT STATUS:	TERMINATED	STATUS DATE:			2/1/2009
REQUIRED ACTIONS:	Gather and/or remove spoil material and/or any part of the operation from outside of the permitted area, stabilize and seed all affected area and construct and/or maintain any sediment control structures affected.				
ABATEMENT ACTIONS:					
PERMIT NO:	S-3003-01	MSHA NO:	46-48889	MSHA DATE:	
VIOLATION NO:	S-3003-01 (24)	DATE VIOL. ISSUED:	10/8/2008	ISSUED BY:	WV DEP
VIOLATION DESCRIPTION:	Permittee failed to conduct surface coal mining and reclamation operations only on land specifically designated as the permit area.				
CURRENT STATUS:	PENDING	STATUS DATE:			1/7/2009
REQUIRED ACTIONS:	Reclaim, stabilize, seed & mulch all affected areas of disturbance outside approved bonded area & submit an IBR to cover all disturbances.				
ABATEMENT ACTIONS:	Extension granted to 7/08/2009				
PERMIT NO:	S-3003-01	MSHA NO:	46-48889	MSHA DATE:	
VIOLATION NO:	S-3003-01 (23)	DATE VIOL. ISSUED:	3/20/2008	ISSUED BY:	WV DEP
VIOLATION DESCRIPTION:	Failed to protect off-site areas from slides and damage during surface mining activities at sediment ditch 5 in the vicinity of outlet 005 & 006. Spoil material, mud, rock & debris was deposited out of permitted area.				
CURRENT STATUS:	TERMINATED	STATUS DATE:			7/18/2008
REQUIRED ACTIONS:	Gather and remove all material that resulted from off-site damage, stabilize, seed and mulch all affected areas and submit an updated progress map showing the limits of off-site damage.				
ABATEMENT ACTIONS:	Required work completed; Violation terminated.				
PERMIT NO:	S-3004-00	MSHA NO:	46-48889	MSHA DATE:	
VIOLATION NO:	S-3004-00 (78)	DATE VIOL. ISSUED:	4/23/2009	ISSUED BY:	WV DEP
VIOLATION DESCRIPTION:	Failed to follow approved application in that you failed to construct Valley Fill D so as to minimize infiltration of surface water. Failed to construct and/or use temp. ditches, sumps.				
CURRENT STATUS:	TERMINATED	STATUS DATE:			7/22/2009
REQUIRED ACTIONS:	Construct Valley Fill D with all associated drainage structures as per approved application and/or remove all material from valley fill and regrade, seed & mulch.				
ABATEMENT ACTIONS:					

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 53 of 57

Entity to whom violation(s) were issued: Powellton Coal Company, L.L.C.

PERMIT NO: S-3004-00 MSHA NO: 46-48889 MSHA DATE:
 VIOLATION NO: S-3004-00 (79) DATE VIOL. ISSUED: 4/23/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to construct and/or certify outcrop barriers on the permit and/or parts thereof in which the natural barrier was mined and/or removed as per the regulations.
 CURRENT STATUS: TERMINATED STATUS DATE: 7/22/2009
 REQUIRED ACTIONS: Construct and/or certify all parts of the permit in which the natural barriers were removed, If natural barriers were not removed on all and/or parts of the permit then certify which of those barriers remain.
 ABATEMENT ACTIONS:

PERMIT NO: S-3004-00 MSHA NO: 46-48889 MSHA DATE:
 VIOLATION NO: S-3004-00 (77) DATE VIOL. ISSUED: 3/25/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to maintain and/or construct sediment ditch 11 as per the regulations and/or your approved application in that the ditch is leaking.
 CURRENT STATUS: TERMINATED STATUS DATE: 3/30/2009
 REQUIRED ACTIONS: Maintain and/or construct sediment ditch 11 as per the regulations and/or your approved application.
 ABATEMENT ACTIONS:

PERMIT NO: S-3004-00 MSHA NO: 46-48889 MSHA DATE:
 VIOLATION NO: S-3004-00 (76) DATE VIOL. ISSUED: 1/15/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to construct and/or maintain sediment control structures and/or other water retention structures as per the regulations and/or approved application in that sediment ditch has developed a breach.
 CURRENT STATUS: TERMINATED STATUS DATE: 1/21/2009
 REQUIRED ACTIONS: Construct and/or maintain sediment control structures and/or other water retention structures as per the regulations and/or your approved application.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: S-3004-00 MSHA NO: 46-48889 MSHA DATE:
 VIOLATION NO: S-3004-00 (75) DATE VIOL. ISSUED: 7/31/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to keep operable regrading equipment on permit area until satisfactory completion of grading of all disturbed areas was complete.
 CURRENT STATUS: TERMINATED STATUS DATE: 8/14/2008
 REQUIRED ACTIONS: Place operable regrading equipment on permit area and keep there until such time that all regrading of all disturbed areas is satisfactorily completed, including all highway elimination.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

Attachment Page 54 of 57

Entity to whom violation(s) were issued: Powellton Coal Company, L.L.C.

PERMIT NO: S-3004-00 MSHA NO: 46-48889 MSHA DATE:
 VIOLATION NO: S-3004-00 (74) DATE VIOL. ISSUED: 7/15/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to keep operable regrading equipment on permit area until
 satisfactory completion of grading of all disturbed areas was complete.

CURRENT STATUS: Modified to CO STATUS DATE: 7/31/2008
 REQUIRED ACTIONS: Place operable regrading equipment on permit area and keep there
 until such time that all regrading of all disturbed areas is
 satisfactorily completed, including all highway elimination.

ABATEMENT ACTIONS:

PERMIT NO: S-3004-00 MSHA NO: 46-48889 MSHA DATE:
 VIOLATION NO: S-3004-00 (73) DATE VIOL. ISSUED: 3/21/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Failed to construct and/or maintain sediment control structures in that
 sediment ditch 12 in the vicinity of outlet 022, 023 and sediment ditch
 5 in the vicinity of outlet 005 failed and are not functioning properly.

CURRENT STATUS: TERMINATED STATUS DATE: 3/26/2008
 REQUIRED ACTIONS: Construct and/or maintain sediment ditches 12 and 5 as per your
 approved permit and/or application and/or as the regulations.

ABATEMENT ACTIONS: Required work completed; Violation terminated

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

28-Sep-09

Attachment Page 55 of 57

Entity to whom violation(s) were issued: Southern West Virginia Resources, LLC

PERMIT NO: O-5031-88 MSHA NO: 46-06089 MSHA DATE:
 VIOLATION NO: O-5031-88 (15) DATE VIOL. ISSUED: 2/27/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to maintain a haul road to meet the performance standards specified by the secretary in that, mud was being tracked off of the bonded area.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/27/2009
 REQUIRED ACTIONS: Permittee must gravel the haulroad to prevent mud from being tracked on to Laurel Creek Road.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

PERMIT NO: O-8-85 MSHA NO: MSHA DATE:
 VIOLATION NO: O-8-85 (65) DATE VIOL. ISSUED: 5/26/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to certify Pond H in accordance with the plans, designs, and specifications set forth in the approved IBR.
 CURRENT STATUS: WITHDRAWN STATUS DATE: 5/29/2009
 REQUIRED ACTIONS: Permittee must complete and certify Pond H before completing any more construction on the Aldrich Branch truck dump.
 ABATEMENT ACTIONS:

PERMIT NO: O-8-85 MSHA NO: MSHA DATE:
 VIOLATION NO: O-8-85 (64) DATE VIOL. ISSUED: 2/24/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to maintain a haul road to meet performance standards. Surface of the haul road is not graded to allow run-off to reach sediment control structure.
 CURRENT STATUS: TERMINATED STATUS DATE: 3/26/2009
 REQUIRED ACTIONS: Permittee must gravel and grade the haulroad to allow run-off to reach the sediment control structures and to prevent mud from staying on the road surface.
 ABATEMENT ACTIONS:

PERMIT NO: S-5062-91 MSHA NO: MSHA DATE:
 VIOLATION NO: S-5062-91 (16) DATE VIOL. ISSUED: 12/30/2008 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Permittee failed to maintain effluent limits as set forth in the NPDES permit in that Outlet 001 was discharging water with a pH of 9.5.
 CURRENT STATUS: TERMINATED STATUS DATE: 1/5/2009
 REQUIRED ACTIONS: Permittee must bring the discharge of Outlet 001 into compliance with the effluent limits set forth in the NPDES permit.
 ABATEMENT ACTIONS: Required work completed; Violation terminated

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

28-Sep-09

Attachment Page 56 of 57

Entity to whom violation(s) were issued: Southern West Virginia Resources, LLC

PERMIT NO: UO-646 MSHA NO: 46-05978 MSHA DATE:
VIOLATION NO: UO-646 (24) DATE VIOL. ISSUED: 1/15/2009 ISSUED BY: WV DEP
VIOLATION DESCRIPTION: Permittee failed to protect off-site areas from slides or damage
occurring during surface mining in that seepage from the outcrop
created a slide on Marrowbone Creek.
CURRENT STATUS: WITHDRAWN STATUS DATE:
REQUIRED ACTIONS: Permittee is to submit and obtain approval of an IBR which bonds all
off-site disturbances. Permittee is to reclaim and stabilize all off-site
disturbances. Permittee is to control the flow of water from this source.
ABATEMENT ACTIONS:

CONSOL Energy and Related Companies - Violation History
September 28, 2006 - September 28, 2009

28-Sep-09

Attachment Page 57 of 57

Entity to whom violation(s) were issued: Terry Eagle Coal Company, L.L.C.

PERMIT NO: O-3037-86 MSHA NO: 46-02245 MSHA DATE:
 VIOLATION NO: O-3037-86 (40) DATE VIOL. ISSUED: 6/10/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Discharged water from area disturbed by surface mining at Outlet 006 in violation of water quality standards. Caused deposits and/or sludge banks and/or discoloration of the creek
 CURRENT STATUS: TERMINATED STATUS DATE: 6/24/2009
 REQUIRED ACTIONS: Cease discharge of water and/or treat the water that is discharging from Outlet 006 so as to stop the deposits and/or sludge banks on the bottom of the creek and/or discoloration.
 ABATEMENT ACTIONS: Company ceased discharging water from Outlet 006

PERMIT NO: O-3037-86 MSHA NO: 46-02245 MSHA DATE:
 VIOLATION NO: O-3037-86 (39) DATE VIOL. ISSUED: 3/11/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Discharged water from areas disturbed by surface mining at Outlet 006 in violation of water quality standards. You caused and/or placed deposits and/or sludge on the bottom of the creek.
 CURRENT STATUS: PENDING STATUS DATE: 3/11/2009
 REQUIRED ACTIONS: Cease the discharge of water and/or treat the water from Outlet 006 so as to stop the placing of deposits on the bottom of the creek and/or staining of the creek.
 ABATEMENT ACTIONS:

PERMIT NO: O-3037-86 MSHA NO: 46-02245 MSHA DATE:
 VIOLATION NO: O-3037-86 (38) DATE VIOL. ISSUED: 2/18/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Discharged water from areas disturbed by surface mining at Outlet 006 in violation of water quality standards. You caused and/or placed deposits and/or sludge on the bottom of the creek.
 CURRENT STATUS: Modified to CO STATUS DATE: 3/11/2009
 REQUIRED ACTIONS: Cease the discharge of water and/or treat the water from Outlet 006 so as to stop the placing of deposits on the bottom of the creek and/or staining of the creek.
 ABATEMENT ACTIONS:

PERMIT NO: O-3037-86 MSHA NO: 46-02245 MSHA DATE:
 VIOLATION NO: O-3037-86 (37) DATE VIOL. ISSUED: 1/6/2009 ISSUED BY: WV DEP
 VIOLATION DESCRIPTION: Discharged water from areas disturbed by surface mining at Outlet 006 in violation of water quality standards. You caused and/or placed deposits and/or sludge on the bottom of the creek.
 CURRENT STATUS: TERMINATED STATUS DATE: 2/5/2009
 REQUIRED ACTIONS: Cease the discharge of water and/or treat the water from Outlet 006 so as to stop the placing of deposits on the bottom of the creek and/or staining of the creek.
 ABATEMENT ACTIONS: