

0005



United States Department of the Interior  
OFFICE OF SURFACE MINING  
Reclamation and Enforcement  
BROOKS TOWERS  
1020 15TH STREET  
DENVER, COLORADO 80202

File  
Folder No. 2  
Below Mines  
w/Attach.

JIM

NOV 21 1983

November 17, 1983

Mr. James W. Smith, Jr.  
Coordinator, Mined Land Development  
Division of Oil, Gas and Mining  
4241 State Office Building  
Salt Lake City, Utah 84114

ACT/015/009

Dear Mr. Smith:

Enclosed are copies of comments from other Federal agencies received since our last mailing of such material on September 15, 1983. These comments concern the Huntington No. 4, Convulsion Canyon, Gordon Creek No. 2, Sunnyside, Emery Deep, and Trail Mountain mines.

As always, if you have any questions on this material, please contact either Louis Hamm or Walter Swain at (303) 837-3806.

Sincerely,

Stephen F. Manger  
Task Force Leader

Enclosures

- cc: Bob Hagen, OSM - Albuquerque Field Office
- Sue Linner, UDOGM
- Tom Munson, UDOGM
- Steve Cox, UDOGM
- Lynn Kunzler, UDOGM
- Pam Grubaugh-Littig, UDOGM

RECEIVED  
NOV 21 1983

DIVISION OF  
OIL, GAS & MINING



United States Department of the Interior  
OFFICE OF SURFACE MINING  
Reclamation and Enforcement  
BROOKS TOWERS  
1020 15TH STREET  
DENVER, COLORADO 80202

File  
Folder No. 2  
Below Mines  
w/Attach.

JIM

NOV 21 1983

November 17, 1983

Mr. James W. Smith, Jr.  
Coordinator, Mined Land Development  
Division of Oil, Gas and Mining  
4241 State Office Building  
Salt Lake City, Utah 84114

ACT/015/009

Dear Mr. Smith:

Enclosed are copies of comments from other Federal agencies received since our last mailing of such material on September 15, 1983. These comments concern the Huntington No. 4, Convulsion Canyon, Gordon Creek No. 2, Sunnyside, Emery Deep, and Trail Mountain mines.

As always, if you have any questions on this material, please contact either Louis Hamm or Walter Swain at (303) 837-3806.

Sincerely,

Stephen F. Manger  
Task Force Leader

Enclosures

cc: Bob Hagen, OSM - Albuquerque Field Office  
Sue Linner, UDOGM  
Tom Munson, UDOGM  
Steve Cox, UDOGM  
Lynn Kunzler, UDOGM  
Pam Grubaugh-Littig, UDOGM

RECEIVED  
NOV 21 1983

DIVISION OF  
OIL, GAS & MINING

File  
Folder No. 2  
IN REPLY REFER TO  
3400 Below  
U-082996 Mine  
(U-921)



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
UTAH STATE OFFICE  
136 E. SOUTH TEMPLE  
SALT LAKE CITY, UTAH 84111

October 14, 1983

Memorandum

To: Utah Senior Project Manager, OSM, Denver

From: Chief, Branch of Solid Minerals  
State Office, BLM, Salt Lake City

Subject: Natomas Coal Company, Trail Mountain Mine,  
Emery County, Utah, Mining and Reclamation Plan (MRP)

*ATT/015/009*

The information transmitted with your letter dated September 15, 1983, has been reviewed, as requested, for completeness and technical adequacy. The Post Mining Contour-Topsoil Map (Figure 8-2), the one page of soil nutrient and additive guidelines (page 21a), and the three pages of soil analysis (pages 21b through 21d) are supplements to the subject MRP plan. This data is compatible to the Resource Recovery and Protection Plan part of the MRP plan and the new 30 CFR 211.10(c) rules effective August 30, 1982.

The supplemental data has been inserted in our copy of the MRP plan.

*Jackson W. Moffitt*

OSM-VTC  
1983 OCT 19 AM 11:25  
WESTERN TECHNICAL CENTER