

April 28, 1983

Inspection Memo  
to Coal File:

RE: Natomas Trail Mtn. Coal Co.  
Trail Mountain Coal Mine  
ACT/015/009  
Folder No. 7  
Emery County, Utah

A partial inspection was conducted at the above mentioned minesite on April 14, 1983 by Division Inspector David Lof. He was accompanied on the inspection by Allen Childs and Joe Fielder of Natomas Trail Mountain Coal Company. The primary purpose of this inspection was to briefly acquaint the inspector with the minesite and to check on the condition of the sediment control structures along the entire east side of the disturbed area.

The berm protecting Cottonwood Creek from the disturbed area was well maintained. The disturbed area runoff diversion which runs the entire length of the east side of the minesite was in very good condition. The truck access points to the minesite and their associated culverts and water bars were properly maintained in order to insure that disturbed area runoff would not leave the permit area prior to passing through the sediment pond.

Some materials which had been cleaned from the sediment pond were stockpiled on the east side of the sediment pond. The operator had constructed a diversion on the east side of this material to insure that runoff would pass through the sediment pond. The operator was informed that the Act and Regulations require that these materials be disposed of in an approved manner within the permit area.



DAVID LOF  
FIELD SPECIALIST

DL/lm

cc: Tom Ehmett, OSM  
Allen Childs, Natomas  
Joe Helfrich, DOGM

Statistics:

Vehicle: EX #66853 - 462 miles  
Per Diem: 1 person X 2 days, 10 1/2 hours = \$106.31  
Grant: A & E