



0019

file ACT/015/009 #12

United States Department of the Interior 3482

BUREAU OF LAND MANAGEMENT

U-082996
(U-067)Moab District
San Rafael Resource Area
900 North 700 East
Price, Utah 84501Mr. John J. Whitehead
Permit Supervisor
State of Utah
Division of Oil, Gas and Mining
355 West Temple Street
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

MAR 23 1988


RECEIVED
MAR 25 1988DIVISION OF
OIL, GAS & MINING

Dear Mr. Whitehead:

We have reviewed Beaver Creek Coal Company's Trail Mountain #9 Mine, Mid-Term Review Response, ACT/015/009. The documents are adequate for our areas of jurisdiction. The resource recovery and protection plan (R²P²) part of the responses to the mining and reclamation plan is essentially unchanged. We have no problems with the responses.

Should you have any questions concerning the matter, contact Stephen Falk at this office at 637-4584.

Sincerely yours,


Area Managercc: Beaver Creek Coal Co.
SD, Utah (U-921)
DM, Moab (U-065)