



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

December 6, 1988

TO: File

FROM: *JW* John Whitehead, Permit Supervisor/
Reclamation Hydrologist

RE: Mid-Term Review Response, Beaver Creek Coal Company,
Trail Mountain #9 Mine, ACT/015/009, Folder #2, Emery
County, Utah

In the absence of Reclamation Hydrologist Jim Fricke, I reviewed the mid-term review response dated November 23, 1988, from Beaver Creek Coal Company (BCCC) for the above noted mine.

UMC 817.46 Hydrologic Balance: Sedimentation Ponds - (JJW)

Figure 7-13 (Sedimentation Ponds Design Details) has been submitted to satisfy this concern.

UMC 817.52 Hydrologic Balance: Ground Water Monitoring - (JJW)

The revised attachment IV for Appendix 7-1 which contains sample point T-19 was submitted to adequately address this concern.

Conclusion

BCCC has adequately addressed all hydrologic concerns in this mid-term review.

djh
AT7/61