

0001



To Sue
File Act/015/015, File #2
JIM
JAN 03 1984
Copy to Sue, Debbie

Consolidation Coal Company
Emery Mine
P. O. Box 527
Emery, Utah 84522
(801) 286-2301

December 28, 1983

Mr. James Smith
Division of Oil, Gas, and Mining
4241 State Office Building
Salt Lake City, UT 84114

RE: ACT/015/015
(subsidence monitoring
surveys)

Dear Mr. Smith:

Subsidence surveys at the Emery Mine were begun in November 1983. To date we have completed surveys on the north side of the mine where no significant movement ($\pm .50'$) since the July 1983 survey has been detected. Although, we have surveyed the south side of the mine there is an apparent error in the survey. Due to recent weather conditions we have not been able to check these results. If significant movement is detected when these monuments are resurveyed we will inform the Division.

If you have need of further information or any questions, please contact me.

Sincerely,

Ronald O. Hughes
Mine Engineer

RECEIVED
DEC 30 1983

**DIVISION OF
OIL, GAS & MINING**