

0002

**CONSOL**

Consolidation Coal Company  
Western Region  
2 Inverness Drive East  
Englewood, Colorado 80112  
(303) 770-1600

To Sue  
file Act/0 stops, file #2  
JIM  
JAN 03 1984  
Copy to Sue  
Dore D. Rick

December 22, 1983

RECEIVED  
DEC 22 1983

DIVISION OF  
OIL, GAS & MINING

Deborah L. Richardson  
Richardson Associates of Denver  
P.O. Box 5111  
Denver, Colorado 80217

Dear Ms. Richardson:

Pursuant to our meeting at the OSM-Denver on December 5, 1983 Consol is providing revised inflow and drawdown predictions for our Emery Mine. These predictions are based on revised Plate 3-7 (5-year mine plan) which has been previously transmitted and an updated upper Ferron aquifer potentiometric surface map (Fall, 1983) which is also enclosed.

Certain other informational requirements (surface water salt loading, potential subsidence areas, etc.) are affected by the above revisions as noted in our meeting. Consol is currently addressing these related items and will forward a response as soon as possible.

If you have any questions please do not hesitate to contact me.

Sincerely,

*Louie Meschede*

Louis H. Meschede  
Hydrologist

LHM/bap

cc: R. Holbrook w/o Encl.  
J. Smith w/o Encl.  
OSM w/o Encl.