

0017



United States Department of the Interior
OFFICE OF SURFACE MINING
Reclamation and Enforcement
BROOKS TOWERS
1020 15TH STREET
DENVER, COLORADO 80202

File
ACT/015/015
Folder No. 24

JIM

APR 09 1984

APR 5 1984

Mr. James W. Smith, Jr.
Coordinator, Mined Land Development
Division of Oil, Gas and Mining
4241 State Office Building
Salt Lake City, Utah 84114

Dear Jim:

Enclosed are copies of recent comments received from another agency regarding completeness and adequacy reviews of Utah mine permit application packages. These comments concern the Emery Deep mine.

If you have any questions on this material, please contact either Louis Hamm or Walter Swain at (303) 837-3806.

Sincerely,

Stephen F. Manger
Task Force Leader

Enclosure

cc: Robert Hagen, OSM - Albuquerque
Dianne Nielson, UDOGM
Susan Lineer, UDOGM
Lynn Kunzler, UDOGM



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Moab District
P. O. Box 970
Moab, Utah 84532

IN REPLY REFER TO
3400
U-5287
(U-067)

MAR 30 1984

Memorandum

To: Center Administrator, OSM, Denver, CO

Attention: Louis Hamm

From: **Associate**
District Manager, Moab

Subject: Response to Revisions of Mining and Reclamation Plan for
Consolidation Coal Company's Emery Deep Mine

We have reviewed revisions to the mine plan concerning ground water and alluvial valley floor investigations, OSM Serial No. UT-0005, and have found them to be complete. We have no further comments at this time.

We do not recommend that any of the lands within the mine plan area be designated unsuitable for coal mining.

Kenneth V. Rhea

OSM-UT-3400
1984 APR -1 11:19:13
WESTERN DISTRICT OFFICE



Save Energy and You Serve America!