

0006

Bart

June 10, 1985

TO: Coal File, Inspection and Enforcement Folder
FROM: Barton D. Kale, Mining Field Specialist *BOX*
RE: Consolidation Coal Company, Emery Deep Mine, ACT/015/015,
Folder #7, Emery County, Utah

A partial inspection was conducted at the above mentioned mine site by Barton Kale of the Division on May 29, 1985. The inspector was accompanied by Ron Thompson of Consolidation Coal Company

The main mine yard was toured and found satisfactory. Significant rain had recently fallen and work to the sediment pond diversion has held up well.

The trash area is starting to stack up again due to the closing of the local landfill by the Health Department. They are negotiating an emergency trash removal to the county landfill if the county will permit it.

Berms were satisfactory surrounding the mine site as well as all water diversions and conveyances.

Coal blown into the stream channel was viewed and determined that to the best of the inspectors ability no additional contributions of wind blown coal has been deposited in the drainage.

The new conveyor belt added to the bridge has held up well and seems to be functioning.

re

cc: Donna Griffin
Ron Thompson, Consol
Joe Helfrich, DOGM
Sue Linner, DOGM

Statistics:

Vehicle: 45429 X 350 miles
Per Diem: 1 person X 1 day 1 hour = \$47.00
Grant: A&E

0245Q-19