



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MININGNorman H. Bangertter
GovernorDee C. Hansen
Executive DirectorDianne R. Nielson, Ph.D.
Division Director355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

John ORA

INSPECTION REPORT

INSPECTION DATE & TIME: April 30, 1990
10:00 am to 3:30 pm

Permittee and/or Operators Name: Consolidation Coal Company
 Business Address: P. O. 527 Emery, Utah 84522
 Mine Name: Emery Deep Permit Number: ACT/015/015
 Type of Mining Activity: Underground Surface Other
 County: Emery
 Company Official (s): Dee Bray
 State Official(s): David Darby
 Partial: X Complete: Date of Last Inspection: March 6, 1990
 Weather Conditions: Clear and dry
 Acreage: Permitted 5180 Disturbed 40 Regraded 2.7 Seeded 2.7 Bonded 247
 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	()	(X)
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION April 30, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits

Consolidation Coal Company has proposed development of new access portals on the north end of the mine property. The Division is in the process of reviewing a resubmitted version of the proposal.

The Division recently approved an amendment to the Emery Deep mine operations to allow entries to be driven under an area previously designated as an alluvial valley floor. Findings indicated that no disruption or diminution to the AVF would occur. The operator may request that the AVF be examined and reclassified from an AVF designation.

4. Hydrologic Balance- Sediment Control

All the sediment control ponds were inspected. None of the ponds contained water and all embankments appeared intact.

Both mine water discharge ponds contained water and were discharging. No samples were taken.


14. Subsidence Control

Subsidence control for AVF areas was discussed with the operator. We also visited the Jack Lewis (now owned by Jim Frost) property to examine crops where subsidence had previously taken place and the operator had regraded and reseeded the field (alfalfa). Jim Frost pointed out some areas that he thought were not getting supplied with irrigation water. Dee proposed to discuss matters with him at a subsequent date. Consol had recently had the AVF area flown and was awaiting information from the aerial photographs.

Copy of this Report:

Mailed to: Ron Thompson, SCCC; Brian Smith, OSM;

Given to: Sue Linner, DOGM; Joe Helfrich, DOGM

Inspectors Signature and Number:  #18 Date: May 8, 1990