

Consolidation Coal Company
Mid-Continent Region
12755 Olive Boulevard
St. Louis, Missouri 63141
(314) 275-2300

March 5, 1992

Mr. Daron R. Haddock
Permit Supervisor
Utah Division of Oil, Gas and Mining
355 W. North Temple
3 Triad Center - Suite 350
Salt Lake City, UT 84180-1203

RECEIVED

MAR 16 1992

DIVISION OF
OIL GAS & MINING

Re: Emery Mine, Permit #ACT/015/015

Dear Mr. Haddock:

Please be advised that the Reclamation Agreement Form that you enclosed in your February 6, 1992 letter to Mr. Kevin Cheeks has been forwarded to our legal department and when completed it will be sent to you under separate cover. Also, as requested in your letter, please find the following responses which address items of concern listed in Ms. Priscilla Burton's technical review dated January 27, 1992.

- 1) Map II-1 has been revised to show the field location of existing topsoil stockpile T-2. The shapes of proposed stockpiles S-7 and T-6 have been adjusted to accommodate the new location of stockpile T-2.
- 2) Maps II-1 and IV-10 have been revised to show an existing berm on the south side of the plant access road from points 0+00 to 5+00.
- 3) Consol requests permission to extend the berm listed in item 2 above, by continuing it from point 5+00 to 8+00. The proposed berm extension, shown on maps II-1 and IV-10, will insure that drainage from the coal stockpile area will not contaminate topsoil resources.

Two certified copies of the revised maps are attached. If you have any questions or comments concerning this submittal, please contact me or Mr. Richard Denning at the above location.

Sincerely yours,



John A. Gefferth
Group Leader - Permits

JAG;rjd:vms
Attachments