

C

Outgoing
6/15/2010
OK

OGMCOAL - Re: Citations 10055, 10056, and 10057 Emery Deep

From: Karl Houskeeper
To: John Gefferth
Date: 6/15/2010 2:06 PM
Subject: Re: Citations 10055, 10056, and 10057 Emery Deep
CC: Dana Dean; Daron Haddock; Jim Smith; OGMCOAL; Steve Christensen
Attachments: DSCN1359.JPG; DSCN1360.JPG; DSCN1370.JPG; DSCN1371.JPG; DSCN1372.JPG; DSCN1373.JPG; DSCN1378.JPG; DSCN1379.JPG; DSCN1380.JPG; DSCN1369.JPG

John,

Attached are copies of the pictures you requested. DSCN1369.JPG is a picture of the diversion by the truck exit that has been a concern in the past and still remains a concern. The diversion has a reverse grade toward the culvert outlet causing it to continually plug. During the inspection the culvert was between 50 - 80 % plugged, enforcement action was not taken as I believe this is a design problem that was not adequately addressed when this area was permitted. As you can see from the picture the diversion is impounding water. I have recommended that a Division Order be issued to address this area.

Thanks,
Karl

>>> "Gefferth, John" <JohnGefferth@consolenergy.com> 6/15/2010 12:54 PM >>>
Karl
Would you please send me pictures of the failed silt fence and clogged culverts

Sent from my BlackBerry Wireless Device

From: Karl Houskeeper <KARLHOUSKEEPER@utah.gov>
To: McClain, Ian; Gefferth, John; Behling, Steve; Angela Nance <angelanance@utah.gov>; Dana Dean <danadean@utah.gov>; Daron Haddock <daronhaddock@utah.gov>; Jim Smith <jimdsmith@utah.gov>; OGMCOAL@utah.gov <OGMCOAL@utah.gov>; Suzanne Steab <suzannesteab@utah.gov>
Sent: Tue Jun 15 10:59:07 2010
Subject: Citations 10055, 10056, and 10057 Emery Deep

Attached are copies of the Citations (10055, 10056, & 10057) issued at Emery Deep.

Thanks,
Karl

"This communication, including any attachments, may contain confidential and privileged information that is subject to the CONSOL Energy Inc.'s Business Information Protection Policy. The information is intended solely for the use of the intended recipient(s). If you are not an intended recipient, you are prohibited from any use, distribution, or copying of this communication. If you have received this communication in error, please immediately notify the sender and then delete this communication in its entirety from your system."



















