



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

May 12, 2015

Kerry Goodballet, Director of Permitting
CONSOL Energy Inc.
CNX Center
1000 CONSOL Energy Drive
Canonsburg, PA 15317

Subject: Soil Sample Data, CONSOL Mining Company, LLC, Emery Deep Mine,
C/015/0015, Task ID #4865

Dear Ms. Goodballet :

The Division has reviewed your application. The Division has identified deficiencies that must be addressed before final approval can be granted. The deficiencies are listed as an attachment to this letter.

The deficiencies authors are identified so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied. Please resubmit the entire application.

If you have any questions, please call me at (801) 538-5350.

Sincerely,

Steve Christensen
Permit Supervisor

SKC/sqs
O:\015015.EME\WG4865 SOIL SAMPLE\Deficiencies.doc



GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Technical Analysis and Findings

Utah Coal Regulatory Program

PID: C0150015
TaskID: 4865
Mine Name: EMERY DEEP MINE
Title: SOIL SAMPLE DATA

Reclamation Plan

Contemporaneous Reclamation General

Deficiencies Details:

Finding:
R645-301-231.300, The sampling locations and field notes included with the Stantec Consulting Services report must be included in the application with the laboratory analysis.

pburton