

**Bronco Utah Operations LLC**

PO Box 527  
Emery Utah, 84522  
435-286-2447

September 14, 2018

Mr. Daron Haddock  
Utah Division of Oil, Gas and Mining  
Coal Program  
1594 West North Temple, Suite 1210  
Salt Lake City, UT 84114-5801

**RE: Bronco Utah Operations LLC  
Emery Mine  
Midterm Review Task 5670 Extension Request**

Mr. Haddock:

Per John Gefferth's meeting with your staff on September 13, 2018, please consider this a 90 day extension request to respond to your mid-term review deficiencies. The as-built topography and volumes are scheduled to be flown during the next few weeks. Bronco will need this time to revise the as-built drainage design and recalculate bond.

If you have any questions concerning this request, please contact Kit Pappas at 435-286-2027.

Sincerely,



Kit Pappas  
Environmental Manager

**Bronco Utah Operations LLC**

PO Box 527

Emery Utah, 84522

435-286-2447

September 14, 2018

Mr. Daron Haddock  
Utah Division of Oil, Gas and Mining  
Coal Program  
1594 West North Temple, Suite 1210  
Salt Lake City, UT 84114-5801

**RE: Bronco Utah Operations LLC  
Emery Mine  
2017 Annual Report Response Extension Request**

Mr. Haddock:

Per John Gefferth's meeting with your staff on September 13, 2018, please consider this a 30 day extension request to respond to your annual report comments.

If you have any questions concerning this request, please contact Kit Pappas at 435-286-2027.

Sincerely,



Kit Pappas  
Environmental Manager