

November 3, 1981


Inspection Memo
to Coal File:

RE: Utah Power & Light Company
Church Mines
ACT/015/017
Emery County, Utah

On October 21, 1981, a partial inspection of the Church Mines was conducted by Jean Doutre, to inspect abatement measures completed on Violation No. N81-6-1-2. The second violation was issued on failure to have records of blasting operations available on-site. These were seen and in good order, on October 14, 1981, so that was abated.

The first violation was for failure to maintain sediment control measures for gully formation where runoff exists Desseret pad, and the area near the lower material storage pad where the ditch to Grimes Wash has eroded leading to Grimes Wash. This had been abated and riprap was in place so termination was issued as of October 16, 1981.

Revegetation is planned for the area below the bathhouse-warehouse building, and the highwall adjacent to the haul road, above the lower storage area.


JEAN LESTER DOUTRE
RECLAMATION OFFICER

JLD/te

cc: Tom Ehmett, O.S.M.

Statistics:

Vehicle: EX70237

Miles: 266

Per Diem: 1 person x 1 day, 12 hours = \$49.47