

0061

UTAH POWER & LIGHT COMPANY

1407 WEST NORTH TEMPLE STREET

P. O. BOX 899

SALT LAKE CITY, UTAH 84110

January 17, 1983

File  
ACT/015/0.17  
ACT/015/018-A  
ACT/015/018-B  
No. 10  
Copy to Mary  
& Pam & Wayne

JIM

JAN 18 1983

State of Utah  
Department of Natural Resources  
Division of Oil, Gas & Mining  
4241 State Office Building  
Salt Lake City, Utah 84114

Attention: Mr. James W. Smith, Jr.

Dear Mr. Smith:

In compliance with State and Federal regulations UMC 817.46(t), UMC 817.49(h) and 30 CFR 77.216-3, we submit the quarterly inspection reports for the sedimentation ponds at the Des-Bee-Dove, Wilberg and Deer Creek Mines for 1982.

Should you require any additional information, please advise.

Sincerely,

C. E. Shingleton  
Director of Services  
Mining and Exploration

CES:BMcQ:bb:3725  
Encl.

cc: Larry Guymon

RECEIVED  
JAN 18 1983

DIVISION OF  
OIL GAS & MINING



A SAVAGE BROTHERS COMPANY

QUARTERLY ENGINEERING REPORT

DEER CREEK SEDIMENT PONDS

1982

INTRODUCTION

This report is submitted in compliance with Federal and State Regulations.

UMC 817.46(t)  
UMC 817.49(h)  
30 CFR 77.216-3

STATEMENTS

Monitoring Procedures:

A series of four check points have been established on the dam and abutments. Elevations are taken on these points during each quarterly inspection as listed below to check for settlement:

<u>Point</u>	<u>Baseline</u>	<u>1st Quarter</u>	<u>2nd Quarter</u>	<u>3rd Quarter</u>	<u>4th Quarter</u>
1	7236.50	7236.49	7236.49	7236.48	7236.48
2	7236.54	7236.54	7236.55	7236.54	7236.54
3	7236.56	7236.56	7236.55	7236.55	7236.55
4	7235.96	7235.98	7235.97	7235.96	7235.96

No settlement has occurred during the year.

Elevations:

Design Depth	Top of Dam	7236.54
	Toe of Dam	7216.61

Impounded Water	<u>1st Quarter</u>	<u>2nd Quarter</u>	<u>3rd Quarter</u>	<u>4th Quarter</u>
	7219.53	7219.35	7220.44	7220.44

Storage Capacity:


	<u>1st Quarter</u>	<u>2nd Quarter</u>	<u>3rd Quarter</u>	<u>4th Quarter</u>
Capacity	-	12.22 Ac.Ft.	12.22 Ac.Ft.	-
Sediment	-	.58 Ac.Ft.	.66 Ac.Ft.	-
Available	-	11.64 Ac.Ft.	11.56 Ac.Ft.	-

Ice covered the pond the 1st and 4th Quarter, therefore, no cross sections could be taken to determine capacity.

General:

Visual inspections were made during each quarterly inspection to check for erosion, structural weakness or other hazardous conditions; none were observed.

I do hereby certify that I am a Registered Professional Engineer in the State of Utah holding license #5214 and do also certify that the above report was prepared by myself and that it is true and correct to the best of my knowledge.



Larry J. Guymon  
 #5214

1-11-83  
 Date



A SAVAGE BROTHERS COMPANY

QUARTERLY ENGINEERING REPORT

COTTONWOOD SEDIMENT PONDS

1982

INTRODUCTION

This report is submitted in compliance with Federal and State Regulations.

UMC 817.46 (t)  
 UMC 817.49 (h)  
 30 CFR 77.216-3

STATEMENTS

Monitoring Procedures:

A visual inspection of the three ponds is made each quarter to check for settlement; none has been observed during the year.

Storage Capacity:


	<u>1st Quarter</u>	<u>2nd Quarter</u>	<u>3rd Quarter</u>	<u>4th Quarter</u>
SOUTH				
Capacity	37.8 Cu.Yd.	37.8 Cu.Yd.	37.8 Cu.Yd.	37.8 Cu.Yd.
Sediment	<u>0</u>	<u>0</u>	<u>10.0 Cu.Yd.</u>	<u>-</u>
Available	37.8 Cu.Yd.	37.8 Cu.Yd.	27.8 Cu.Yd.	-
CENTER				
Capacity	448.99 Cu.Yd.	448.99 Cu.Yd.	448.99 Cu.Yd.	448.99 Cu.Yd.
Sediment	<u>0</u>	<u>12.90 Cu.Yd.</u>	<u>15.00 Cu.Yd.</u>	<u>-</u>
Available	448.99 Cu.Yd.	436.09 Cu.Yd.	433.99 Cu.Yd.	-
NORTH				
Capacity	103.33 Cu.Yd.	103.33 Cu.Yd.	103.33 Cu.Yd.	103.33 Cu.Yd.
Sediment	<u>0</u>	<u>0</u>	<u>27.0</u>	<u>-</u>
Available	103.33 Cu.Yd.	103.33 Cu.Yd.	76.33 Cu.Yd.	-

Ponds were iced over during the 4th quarter inspection. The North and South Ponds were cleaned twice during the year.

General:

Visual inspections were made during each quarterly inspection to check for erosion, structural weakness or other hazardous conditions; none were observed.

I do hereby certify that I am a Registered Professional Engineer in the State of Utah holding license #5214 and do also certify that the above report was prepared by myself and that it is true and correct to the best of my knowledge.



Larry A. Gaymon, P.E.  
#5214

1-11-83  
Date