

0041

**Utah
power**

& LIGHT COMPANY
MINING DIVISION
P.O. Box 310
Huntington, Utah 84528

March 7, 1989

File #2
ACT/015/018

RECEIVED
MAR 07 1989

**DIVISION OF
OIL, GAS & MINING**

Mr. Rick Smith
Acting Permit Supervisor
Utah Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Re: Roans Canyon Graben Crossing and
Probable Hydrologic Consequences
Statement
Deer Creek Mid-Term Review

Dear Mr. Smith:

Attached for inclusion into the Deer Creek Mine permit are five (5) copies of text and maps describing the Roans Canyon Fault Crossing. This material was given to you for review a few weeks ago. During our phone conversation of March 1, 1989 you told me this material was approved for inclusion in the permit.


The material to be inserted into the permit is as follows:

Pages 4-37.12, 4-37.13, 4-37.14, 4-37.15
Map 2-13A - Drawing No. CM-10784-DR

Also, to complete the Probable Hydrologic Consequences section of the permit pages 4-36, 4-37 should be renumbered 4-35.1 and 4-35.2. Pages 4-35.3 through 4-35.6 (3/1/89) should be added. Also, pages 4-36 through 4-36.25 (3/1/89) should be added. Five (5) copies of text are included; three (3) copies of Drawing No. CE-10801-EM are included. Two (2) more will be submitted later this week. These maps should be included in the 2-11 map packet.

If you have any questions, please call.

Sincerely,



David Smaldone, Director
Permitting, Compliance & Services
Mining Division