

0036

**Utah
power**

& LIGHT COMPANY
MINING DIVISION
P.O. Box 310
Huntington, Utah 84528

File ACT/015/0
018 } #2
019 }
RECEIVED
APR 16 1990
DIVISION OF
OIL, GAS & MINING

April 9, 1990

Ms. Pamela Grubaugh-Littig
Permit Supervisor
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Ms. Grubaugh-Littig:

Enclosed for submittal are the 1st Quarter 1990 Engineering Reports for Deer Creek, Cottonwood/Wilberg and Des Bee Dove Waste Rock Disposal Sites. Please find also, the 1st Quarter 1990 Report of the Deer Creek Elk Canyon Storage Pad submittal.

Sincerely,



Fob David Smaldone
Director of Permitting,
Compliance and Services

GD/do
Enclosure

COTTONWOOD/WILBERG/DES-BEE-DOVE
ACT/015/019 AND ACT/015/017
WASTE ROCK DISPOSAL SITE
1ST QUARTER 1990

INTRODUCTION

The disposal area is located on an approved 16 acre right-of-way from the BLM located approximately two miles from the Cottonwood/Wilberg Mine site. This site serves both the Cottonwood/Wilberg and the Des-Bee-Dove mines.

OPERATION

During the quarter, approximately 7,840 cubic yards of material from the Cottonwood operation was dumped in the facility.


Leveling and compaction of the material placed at the site took place twice during the quarter. Trash and extraneous material were removed during this operation.

Inspection of the facility for structural stability was done on March 30, 1990. Inspection of the operation of the facility was done on a continual basis.

Several cracks were found on the inside slope at the west berm of cell #7. These were observed several times during the quarter and no additional movement was noticed. There is no danger at the present time.

CERTIFICATION

I do hereby certify that the Cottonwood/Wilberg Waste Rock Site is being constructed according to sound engineering practice, the regulations governing its construction and the approved MRP and I do also certify that there was no evidence of instability, structural weakness or other hazardous conditions at the time of this inspection except as noted herein.



THOMAS J. FAUCHEUX
P.E. 7059