

0019



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING



Handwritten initials 'gd'

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: x Complete: Exploration:
Inspection Date & Time: 4/19/94 9:00AM - 12:00 Noon
Date of Last Inspection: 3/31/94

Mine Name: Deer Creek County: Emery Permit Number: ACT/015/018
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 1005 Huntington, UT 84528
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Tom Munson, Scott Milovich
Company Official(s): Karl Housekeeper
Federal Official(s): None
Weather Conditions: Clear, Cool
Existing Acreage: Permitted- 14,740 Disturbed- 56 Regraded- Seeded- Bonded- 56
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows 1-21 list various permit and performance standards with checkboxes for evaluation.



INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION: 4/19/94

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers

Disturbed area perimeter markers had not been placed on the terrace above the mine site. The Operator indicated that they were waiting for termination of Violation N93-7-1-3. The violation was terminated on 1/4/94. The Operator apparently had not received notice of the termination. Notice of termination will be sent. Disturbed area markers will be in place by 4/29/94.

3. Topsoil

The Operator indicated that deteriorating areas of the silt fence protecting the topsoil stored on the perimeter of the waste rock site had been scheduled for replacement.

4. Hydrologic Balance

a. **Diversions:** The berm at the end of the terrace above the mine had been repaired and the rilling below filled in. No additional sloughing had occurred into the diversion and there appeared to be no blockage of flow by the sloughing noted in the previous inspection.

c. **Other Sediment Control Measures:** Straw bales had been placed adjacent to existing bales along the lower portion of the belt line. The existing bales were deteriorating and it was determined on the previous inspection that it would be more effective to leave the old bales in place and stack the new ones on the uphill side. There was some discussion about the need to have the bales in place at all. The Operator indicated that he would investigate the purpose for the bales and then determine whether or not they are required, or if a Small Area Exemption is in order.

8. Noncoal Waste

The trash that had accumulated in the snow piles had been cleaned up, but trash was now present in other areas of the parking lot. The Operator indicated that the trash would be cleaned up.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Karl Housekeeper (PacifiCorp)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: _____


Scott Milovich #45

Date: 4/21/94