

0011



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1027

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

**DIVISION OF OIL GAS & MINING
FIELD VISIT FORM
TECHNICAL**

Date : August 20, 1996

Time: 11:15 a.m. to 11:30 a.m.

Mine: Deer Creek Mine (Rilda Canyon Facilities)

File Number: ACT/015/018, Folder #2


DOGM Staff: Steven Johnson

Other Attendees: John Christiansen (Energy West)

Purpose:
Look at riprap in the road ditch.

Observations:
Riprap had recently been dumped into the road ditch in many of the steeper reaches. The riprap was not well graded and not yet distributed over the area. The Energy West representative said that work should be done by the end of the day.

Recommendations/Conclusions:
Finalization of riprap placement is well over due and must be completed before August 23, 1996.

Signature:  on August 22, 1996
Steven M. Johnson, Reclamation Hydrologist

