

0046

United States
Department of
Agriculture

Forest
Service


Manti-La Sal
National Forest

59 West Price River Dr.
Price, Utah 84501
(435) 637-2817

Reply to: 2820-4

Date: February 26, 1998

ACT 1015/618 #2
Pam
Daron



Richard Manus
Bureau of Land Management
Price Field Office
125 South 600 West
Price, Utah 84501

Dear Mr. Manus:

An inspection of PacifiCorp's 1995 in-mine drill holes in Rilda Canyon (exploration plan) at the Deer Creek Mine was conducted during the 1997 field season. Two 3-inch diameter holes were drilled from the mine roof to the ground surface. Since surface disturbance was minimal, no bond was required.

PacifiCorp has met all reclamation requirements. We recommend file closure.

If you have any questions or need additional information, please contact Carter Reed or Jeff DeFreest at the Forest Supervisor's Office in Price.

Sincerely,

Janette S. Kaiser
for
JANETTE S. KAISER
Forest Supervisor

cc:
D-2/3
Pam Grubaugh-Littig, UDOGM, SLC