



PO Box 310  
Huntington, Utah 84528

September 23, 2004

Utah Coal Program  
Utah Division of Oil, Gas, and Mining  
1594 West North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, Utah 84114-5801

*Incoming  
C/015/0018 OK  
Copy Wayne,  
J.T.  
Dane*

**Subj: Replacement of Map 500-2, Rilda Canyon Surface Facilities, for the Rilda Canyon Portal Project, Volume 11, PacifiCorp, Deer Creek Mine, C/015/018, Emery County Utah.**

PacifiCorp, by and through its wholly-owned subsidiary, Energy West Mining Company ("Energy West") as mine operator, hereby submits the following maps for replacement in the amended Volume 11 and Volume 11 Appendix Volume submitted September 2, 2004:

- Map 500-2, Deer Creek Mine, Rilda Canyon Surface Facilities, DS1872D
- Map 700-2, Deer Creek Mine, Rilda Canyon Facilities, Minesite Drainage Map, DS1883D
- Map 700-5, Deer Creek Mine, Rilda Canyon Facilities, ASCA Locations Map, DS1885D

The said amendment provides background information and data to support construction activities for the development of new portal facilities in Rilda Canyon.

After submitting the amendment to Volume 11, it was found that there existed elevation errors. Contour elevations were off by +25 feet on the fan pad. The errors have been corrected and are attached to this document. A C2 form is included with this submittal for placement in the revised Volume 11.

If you have any questions or concerns, please contact myself at (435) 687-4720 or Dennis Oakley at (435) 687-4825.

Sincerely,

*Dennis Oakley*

*for* Chuck Semborski  
Manager of Permitting and Geology

cc: Doug Johnson  
File

RECEIVED

SEP 27 2004

DIV. OF OIL, GAS & MINING

File in: *C/015/0018 2004, In Coming*

Refer to:

- Confidential
- Shelf
- Expandable

Date: *09232004* For additional information

Huntington Office:  
(435) 687-9821  
Fax (435) 687-2695  
Purchasing Fax (435) 687-9092

Deer Creek Mine:  
(435) 687-2317  
Fax (435) 687-2285

Trail Mountain Mine:  
(435) 748-2140  
Fax (435) 748-5125

