

0025

From: "Fleck, Ken" <Kenneth.Fleck@PacifiCorp.com>
To: "Pam Grubaugh-Littig" <pamgrubaughlittig@utah.gov>
Date: 3/26/2007 10:40 AM
Subject: FW: Rilda Canyon Left Fork Road Use
Attachments: Rilda Intake Cave Map 032407.doc

> _____
 > **From:** Fleck, Ken
 > **Sent:** Monday, March 26, 2007 9:31 AM
 > **To:** 'Thomas W Lloyd'
 > **Cc:** Oakley, Dennis; Davis, Guy; Snow, H. Earl
 > **Subject:** Rilda Canyon Left Fork Road Use

*Investigat
 3/15/2008*

> Tom,
 >
 > A large and serious roof fall (60' long, 20' wide, and 12'+ high)
 > occurred inside the intake portal at our Rilda Canyon left fork
 > facility on 3/24/07. The location and seriousness of the fall
 > necessitated bringing a roof bolter and roof bolting supplies to the
 > outside end of this fall; the only way to get these items to the fall
 > was to bring them in from the outside (left fork road). The concern
 > is to get the area between the north end of the roof fall and the burn
 > margin re-bolted and stabilized immediately while the fall is being
 > cleaned up from the inside. We still need to deliver some cable bolts
 > and accessories to the left fork portal, so the road is still in use
 > for isolated deliveries.
 >
 > I will keep you posted on the status of the cave recovery and the
 > road.
 >
 > I have attached a map showing the location and dimensions of the fall,
 > it is a scanned Word document.
 >
 > <<Rilda Intake Cave Map 032407.doc>>
 >
 > Thanks,
 >
 > Ken Fleck
 > Geology and Environmental Affairs Manager
 > Energy West Mining Co.
 >
 > P.O. Box 310
 > Huntington, Utah 84501
 > 435 687 6638 Deer Creek Mine
 > 435 687 4712 Huntington Office

 This email is confidential and may be legally privileged.

It is intended solely for the addressee. Access to this email by anyone else, unless expressly approved by the sender or an authorized addressee, is unauthorized.

If you are not the intended recipient, any disclosure, copying, distribution or any action omitted or taken in

