

2015 018 Incoming

cc: Karl

K

RECEIVED

SEP 27 2011

DIV. OF OIL, GAS & MINING



September 21, 2011

Mr. Roger Bankert, Chief, Branch of Minerals  
Bureau of Land Management  
Utah State Office  
P.O. Box 45155  
Salt Lake City, Utah 84145

RE: Exploration License UTU-88021, Notice of Intent to Conduct Minor Coal Exploration - Mill Fork Lease (ML-48258/UTU-88554) (DOGM Task #3819), Notice of Intent to Conduct Minor Coal Exploration - Federal Lease U-06039 (DOGM Task #3793).

Dear Mr. Bankert:

PacifiCorp, by and through its wholly-owned subsidiary, Energy West Mining Company ("Energy West") as mine operator, hereby submits two copies on compact disk of the exploration data obtained from the 2011 surface drilling from Exploration License UTU-88021, Notice of Intent to Conduct Minor Coal Exploration - Mill Fork Lease (ML-48258/UTU-88554) (DOGM Task #3819), Notice of Intent to Conduct Minor Coal Exploration - Federal Lease U-06039 (DOGM Task #3793), including lithologic logs, geophysical logs, coal quality analyses and Reports of Water Observed. Drilling commenced on June 16, 2011 and was completed on August 6, 2011. A total of 10 (ten) holes were drilled detailing the geologic and hydrologic characteristics of coal reserves in Exploration License Area UTU-88021, the Mill Fork Lease (ML-48258/UTU-88554) and Federal Lease U-06039. The following summary outlines the drill hole information submitted along with the hole abandonment documentation:

**PACIFICORP - ENERGY WEST MINING COMPANY**

**2011 Exploration License UTU-88021 Drilling Program**

| DRILL HOLE NUMBER | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|-------------------|----------------|----------|----------|--------|------------------|--------------------|
|                   |                | Section  | Township | Range  |                  |                    |
| EM-216            | June 24, 2011  | 22       | 16 South | 6 East | 9,486'           | 1,484'             |

HOLE ABANDONMENT DATA:  
 BLM Contact: Sue Wiler, BLM Witness: Sue Wiler  
 Energy West Mining Representative: Ken Fleck  
 Lancaster Drilling, Inc. Representative: Joe Lancaster  
 Diameter of Drill Hole: 3.75" 0-99', 2.98" 99-658', 2.36" 658-1,484'  
 Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 7 bags of cement, 12 bags of Super Plug, and 1 bag of bentonite chips were used. Brass cap identification marker installed below the ground surface. All drill pipe and casing was removed from the hole.

Mr. Roger Bankert, Chief, Branch of Minerals  
 Bureau of Land Management  
 September 21, 2011  
 Page Two

2011 Mill Fork Lease Drilling Program

TASK 3819

| DRILL HOLE NUMBER   | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|---|----------------|----------|----------|--------|------------------|--------------------|
|   |                | Section  | Township | Range  |                  |                    |
| EM-217  | July 7, 2011   | 23       | 16 South | 6 East | 10,027'          | 1,998'             |
| HOLE ABANDONMENT DATA:<br>BLM Contact: Sue Wiler, BLM Witness: Vaughn Hughes<br>Energy West Mining Representative: Ken Fleck<br>Lancaster Drilling, Inc. Representative: Joe Lancaster<br>Diameter of Drill Hole: 3.75" 0-399', 2.98" 399-944', 2.36" 944-1,998'<br>Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 7 bags of cement, 12 bags of Super Plug and 3.5 bags of bentonite chips were used. Brass cap identification marker installed below the ground surface. 850' of "N" (2.98") drill pipe and 340' of "H" (3.75") drill pipe was left in the hole after it became stuck. All other drill pipe and casing was removed from the hole. |                |          |          |        |                  |                    |

2011 U-06039 Drilling Program

TASK 3793

| DRILL HOLE NUMBER  | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|--|----------------|----------|----------|--------|------------------|--------------------|
|  |                | Section  | Township | Range  |                  |                    |
| EM-218   | July 11, 2011  | 20       | 16 South | 7 East | 9,124'           | 1,297'             |
| HOLE ABANDONMENT DATA:<br>BLM Contact: Steve Rigby, BLM Witness: None<br>Energy West Mining Representative: Ken Fleck<br>Lancaster Drilling, Inc. Representative: Pat Lancaster<br>Diameter of Drill Hole: 3.75" 0-40', 2.98" 40-340', 2.36" 340-1,297'<br>Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 7 bags of cement, 9 bags of Super Plug and 10 bags of bentonite chips were used. Brass cap identification marker installed below the ground surface. All drill pipe and casing was removed from the hole. |                |          |          |        |                  |                    |

Mr. Roger Bankert, Chief, Branch of Minerals

Bureau of Land Management

September 21, 2011

Page Three

2011 Mill Fork Lease Drilling Program

TASK 3819

| DRILL HOLE NUMBER  | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|--|----------------|----------|----------|--------|------------------|--------------------|
|  |                | Section  | Township | Range  |                  |                    |
| EM-219   | July 12, 2011  | 1        | 16 South | 6 East | 9,141'           | 1,275'             |
| HOLE ABANDONMENT DATA:<br>BLM Contact: Steve Rigby, BLM Witness: None<br>Energy West Mining Representative: Ken Fleck<br>Lancaster Drilling, Inc. Representative: Allen Hackett<br>Diameter of Drill Hole: 3.75" 0-30', 2.98" 30-179', 2.36" 179-1,275'<br>Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 14 bags of cement, 8 bags of Super Plug and 10 bags of bentonite chips were used. Brass cap identification marker installed below the ground surface. 20' of "H"(3.75") drill pipe was left in the hole after it became stuck. All other drill pipe and casing was removed from the hole. |                |          |          |        |                  |                    |

2011 Exploration License UTU-88021 Drilling Program

| DRILL HOLE NUMBER  | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|--|----------------|----------|----------|--------|------------------|--------------------|
|  |                | Section  | Township | Range  |                  |                    |
| EM-220   | July 20, 2011  | 26       | 16 South | 6 East | 9,652'           | 1,637'             |
| HOLE ABANDONMENT DATA:<br>BLM Contact: Steve Rigby, BLM Witness: None<br>Energy West Mining Representative: Ken Fleck<br>Lancaster Drilling, Inc. Representative: Alex Hunt<br>Diameter of Drill Hole: 3.75" 0-69', 2.98" 69-672', 2.36" 672-1,637'<br>Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 14 bags of cement, 10 bags of Super Plug and 10 bags of bentonite chips were used. Brass cap identification marker installed below the ground surface. 580' of "N"(2.98") drill pipe was left in the hole after it became stuck. All other drill pipe and casing was removed from the hole. |                |          |          |        |                  |                    |

Mr. Roger Bankert, Chief, Branch of Minerals  
 Bureau of Land Management  
 September 21, 2011  
 Page Four

**2011 Exploration License UTU-88021 Drilling Program**

| DRILL HOLE NUMBER | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|-------------------|----------------|----------|----------|--------|------------------|--------------------|
|                   |                | Section  | Township | Range  |                  |                    |
| EM-221            | July 19, 2011  | 22       | 16 South | 6 East | 8,790'           | 915'               |

**HOLE ABANDONMENT DATA:**

BLM Contact: Steve Rigby, BLM Witness: None

Energy West Mining Representative: Ken Fleck

Lancaster Drilling, Inc. Representative: Pat Lancaster

Diameter of Drill Hole: 3.75" 0-10', 2.98" 10-179', 2.36" 179-915'

Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 14 bags of cement, 8 bags of Super Plug and 10 bags of bentonite chips were used. Brass cap identification marker installed below the ground surface. All drill pipe and casing was removed from the hole.

**2011 Mill Fork Lease Drilling Program**

TASK 3819

| DRILL HOLE NUMBER | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|-------------------|----------------|----------|----------|--------|------------------|--------------------|
|                   |                | Section  | Township | Range  |                  |                    |
| EM-222            | July 22, 2011  | 1        | 16 South | 6 East | 9,289'           | 1,399'             |

**HOLE ABANDONMENT DATA:**

BLM Contact: Steve Rigby, BLM Witness: None

Energy West Mining Representative: Ken Fleck

Lancaster Drilling, Inc. Representative: Allen Hackett

Diameter of Drill Hole: 3.75" 0-10', 2.98" 10-399', 2.36" 399-1,399'

Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 14 bags of cement, 8 bags of Super Plug and 2.5 bags of bentonite chips were used. Brass cap identification marker installed below the ground surface. All drill pipe and casing was removed from the hole.

Mr. Roger Bankert, Chief, Branch of Minerals  
 Bureau of Land Management  
 September 21, 2011  
 Page Five

**2011 Exploration License UTU-88021 Drilling Program**

| DRILL HOLE NUMBER | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|-------------------|----------------|----------|----------|--------|------------------|--------------------|
|                   |                | Section  | Township | Range  |                  |                    |
| EM-223            | July 30, 2011  | 24       | 16 South | 6 East | 9,862            | 1,916'             |

**HOLE ABANDONMENT DATA:**

BLM Contact: Steve Rigby, BLM Witness: None  
 Energy West Mining Representative: Vincent Jefferies  
 Lancaster Drilling, Inc. Representative: Pat Lancaster  
 Diameter of Drill Hole: 3.75" 0-401', 2.98" 401-1,080', 2.36" 1,080-1,916'  
 Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 14 bags of cement, 12 bags of Super Plug and 12 bags of bentonite chips were used. Brass cap identification marker installed below the ground surface. All drill pipe and casing was removed from the hole.

**2011 Exploration License UTU-88021 Drilling Program**

| DRILL HOLE NUMBER | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|-------------------|----------------|----------|----------|--------|------------------|--------------------|
|                   |                | Section  | Township | Range  |                  |                    |
| EM-224            | July 27, 2011  | 26       | 16 South | 6 East | 9,319'           | 1,317'             |

**HOLE ABANDONMENT DATA:**

BLM Contact: Steve Rigby, BLM Witness: None  
 Energy West Mining Representative: Vincent Jefferies  
 Lancaster Drilling, Inc. Representative: Alex Hunt  
 Diameter of Drill Hole: 3.75" 0-69', 2.98" 69-369', 2.36" 369-1,317'  
 Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 14 bags of cement, 8 bags of Super Plug and 8 bags of bentonite chips were used. Brass cap identification marker installed below the ground surface. 50' of "H"(3.75") drill pipe was left in the hole after it became stuck. All other drill pipe and casing was removed from the hole.

Mr. Roger Bankert, Chief, Branch of Minerals  
Bureau of Land Management  
September 21, 2011  
Page Six

### 2011 Exploration License UTU-88021 Drilling Program

| DRILL HOLE NUMBER  | DATE COMPLETED | LOCATION |          |        | ELEVATION (feet) | TOTAL DEPTH (feet) |
|--|----------------|----------|----------|--------|------------------|--------------------|
|  |                | Section  | Township | Range  |                  |                    |
| EM-225   | August 6, 2011 | 26       | 16 South | 6 East | 9,822'           | 1,809'             |
| HOLE ABANDONMENT DATA:<br>BLM Contact: Steve Rigby, BLM Witness: None<br>Energy West Mining Representative: Ken Fleck<br>Lancaster Drilling, Inc. Representative: Allen Hackett<br>Diameter of Drill Hole: 3.75" 0-409', 2.98" 409-870', 2.36" 870-1,809'<br>Drill hole abandoned utilizing slurry cement/Super Plug pumped through drill rods to bottom of hole. A total of 14 bags of cement, 14 bags of Super Plug and 10 bags of bentonite chips were used. Brass cap identification marker installed below the ground surface. All drill pipe and casing was removed from the hole. |                |          |          |        |                  |                    |

Each of the ten (10) sites were reclaimed and seeded according to U.S.F.S. specifications upon completion.

If any additional information is needed please contact me at 687-4712.

Sincerely,



Kenneth S. Fleck  
Geology and Environmental Affairs Manager

Enclosures: Lithologic Logs (CD)  
Geophysical Logs (CD)  
Reports of Water Observed sheets (CD)  
Coal Quality Analyses (CD)

cc: Mike Glasson (BLM - Price Office), without enclosures  
Joe Dibenedetto (U.S.F.S. - Ferron Office), without enclosures  
DOGM Coal Regulatory Program, without enclosures  
Scott Child (Interwest), without enclosures  
File: 2011 Mill Fork Exploration  
DRILLDATA11\_BLMwpd.wpd