

November 21, 1983

Inspection Memo
to Coal File:

RE: Utah Power & Light Company
Wilberg Mine
ACT/015/019 Folder # 7
Emery County, Utah

On November 8, 1983, Larry Guymon of Emery Mining Corporation, accompanied DOGM Field Specialist Ken Wyatt on a partial inspection of the Wilberg Mine. The purpose of this inspection was to follow up on the abatement of NOV N83-7-8-1.

At this time, the concrete curb had cured and the molding was removed. This curb should be adequate to retain disturbed area runoff on the permit area and channel it toward the sediment pond. The coal/underground development waste pile adjacent to the mine water discharge pipe was beginning to encroach near the undisturbed drainage headwall. This encroachment should be scrutinized closely by the operator to insure against future spillage into the undisturbed drainage. NOV N83-7-8-1 was subsequently terminated following this inspection.

Cell #2 of the waste rock disposal area is approaching capacity. Mr. Guymon indicated the waste rock was still being produced at the mine and disposal was occurring at the waste rock disposal area. No problems were encountered at this time.

KEN WYATT *KW*
FIELD SPECIALIST

cc: Tom Ehmett, OSM
Larry Guymon, Emery Mining Corporation
Joe Helfrich, DOGM
Cy Young, DOGM

Statistics:

Vehicle: EX45429--742 miles
Per Diem: 1 person X 2 days, 7 hours = \$96.42
Grant: A&E