



A SAVAGE BROTHERS COMPANY

RECEIVED

AUG 30 1984

DIVISION OF OIL  
GAS & MINING

August 28, 1984

Mr. Ken Wyatt  
Division of Oil, Gas and Mining  
Natural Resources and Energy  
State of Utah  
4241 State Office Building  
Salt Lake City, Utah 84114

Regarding: Cottonwood Exploration Site

Dear Mr. Wyatt:

On August 10th, 1984, we finished cleaning the lower sediment basin and erosion repair work to the ditch along the toe of the slope.

These facilities were inspected on Friday, August 24th, by Val Payne and again on Monday, August 27th, by myself. Severe damage has occurred to the drainage systems due to heavy thunder shower activity during the proceeding week and week end. Both the upper and lower basins are again full of sediment and severe erosion damage has occurred to the drainage ditch along the toe of the slope.

Because of the continual problems we are having maintaining these facilities we are in the process of evaluating alternative solutions to the erosion and separating the road drainage from the drainage that should be treated by the sediment structures.

Our current plans are to place rip-rap in the drainage ditch to control erosion, construct a dirt berm and road bar ditch to separate the road drainage and to construct a barrier to protect the dirt beam from road maintenance activity.

We anticipate completion of the construction work by September 28th, 1984.

Should you have questions please let me know.

Sincerely,

Larry J. Guymon, P.E.  
Construction Manager

cc: Bill Zeller, Jim Hamlin, Morgan Moon, Val Payne  
Dave Bocoock, Carl Pollastro  
Chris Shingleton, UP&L