



0036

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Scott M. Matheson, Governor  
Temple A. Reynolds, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

March 8, 1984

Larry Guymon  
Emery Mining Corporation  
P.O. Box 310  
Huntington, Utah 84528

RE: Report of Slide  
UMC 817.99  
ACT/015/019  
Folder No. 7 & 10  
Emery County, Utah

Dear Mr. Guymon:

This letter shall serve to document your phone call to this office at 1:50 p.m. March 7, 1984. As you will recall the purpose of the call was to inform the Division in accordance with UMC 817.99 of a slide or other damage at the Wilberg Mine.

The slide area was reported to have been in the vicinity of the previously observed subsidence area along the canyon rim of the Right Fork Grimes Wash. You indicated that part of the rock ledge had fallen. Some rock and debris made it down to the old fan access road and into the Right Fork of Grimes Wash.

No damage or public safety problem was created from this rock fall. Utah Power & Light should consider barricading the lower material storage pad as has been done in prior years as a precautionary measure to prevent access by mining personnel which potentially could be affected by additional falling rock.

If any fallen debris has blocked the Right Fork Grimes Fork drainage, UP&L will be required to clear the channel of obstructions as we discussed by phone the morning of March 8, 1984. Should you have any questions or further problems on this matter, please feel free to call me.

Sincerely,

Ken Wyatt  
Field Specialist

KW/lm

cc: Chris Shingleton, UP&L  
Joe Helfrich, DOGM  
Mary Boucek, DOGM