

August 7, 1991

Mr. Lowell P. Braxton  
Associate Director, Mining  
Division of Oil, Gas and Mining  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

Re: Division Order, Permit Deficiency - Sediment Ponds  
PacifiCorp Electric Operations, Cottonwood/Wilberg Mine  
ACT/015/019-DO-19A, Folder #3, Emery County, Utah  
Request for Response Extension

Dear Mr. Braxton:

Pursuant to your phone conversation with Val Payne, work is continuing in response to the above-referenced Division Order dated July 2, 1991 and received July 8, 1991. We have completed a field work survey of Cottonwood/Wilberg sediment ponds and in-house study of the modifications necessary to comply with the Order.

The Cottonwood/Wilberg ponds are unique in their size, construction, and location within a haul road loop. Extensive design changes and construction may be required for compliance. We are seeking outside professional assistance to fulfill the requirements of the Order. The scope of this project requires a minimum additional 30 days to respond.

Therefore, we respectfully request at least an additional 30 days for response to the permit deficiency regarding Cottonwood/Wilberg sediment ponds.

Your consideration is appreciated.

Sincerely,

  
J. Blake Webster

Permitting Administrator

cc: Val Payne  
Guy Davis

**RECEIVED**

**AUG 12 1991**

**DIVISION OF  
OIL GAS & MINING**